

Spis świadectw wydanych przez COCH w 2007 r.

Numer świadectwa	Numer rejestracyjny (punkt 3 świadectwa)	Uznaje się jako (punkt 6 świadectwa)	Nr protokołu badań (punkt 7.2.3 świadectwa)	Data ważności świadectwa (pkt.8)
1	2	3	4	5
001/2007	WWL 1AA8 / 110016616	FRC	4560, M572, 6045	12.2012
002/2007	WWL 1AA9 / 11016626	FRC	4560, M572, 6046	12.2012
003/2007	WWL 2AA3 / 11016636	FRC	4560, M572, 6047	12.2012
004/2007	KOL 29GN / 411600	FRC	6060	06.01.2010
006/2007	SUDNSICTZ68010782/ 11017946	FRC	5939, M576, 6062	11.2012
007/2007	SUDNSICTZ68010770/11012876	FRC	5939, M576, 6062	11.2012
008/2007	SUDNSICTZ68010769/11012866	FRC	5939, MR79, 6064	11.2012
009/2007	SUDNSICTZ68010771/11014636	FRC	5939, M576, 6065	11.2012
010/2007	WI 717AH / 455669	FRC	6066	03.01.2010
012/2007	WZ 63956 / 5021787	FRC	06 1281 M576	02.10.2012
014/2007	LLU 51PR /5016437	FRC	3367T, MR79, 6067	06. 2012
015/2007	LU 4597P / 443837	FRC	6068	07.01.2010
017/2007	WLS N255 / 5007292	FRC	3338T, MR79, 6070	06.2011
018/2007	WLS N288 / 5011400	FRC	3319T, 3150K, 6071	12.2011
019/2007	LLU R770 / 95C0446.001	FNA	6072	06.01.2010
020/2007	LU 2834P / 5017863	FRC	06 1281, MR79, 6073	07.2012
021/2007	WSMS7480000435700	FRC	6074	06.01.2010
022/2007	WI 744AH / 438613	FRC	6076	06.01.2010
024/2007	TKI P829 / 092387	FRC	6078	12.2009
025/2007	CF/144 ME-SP-L3H2	IN	6081	05.01.2013
026/2007	KSU P689 / 078400	FRC	6080	12.2009
027/2007	LRA R966 / 223910	FRC	6079	07.01.2010
028/2007	WZ 64061 / 5020746	FRC	06 1286, MR81	11.2012
030/2007	SB 88078 / 01C2290.001	FRC/X	6083	10.01.2010
031/2007	SB 88077 / 99/C2120-003	FRC/X	6084	10.01.2010
032/2007	SB 63927 / 128059	FNA/X	6085	10.01.2010
033/2007	NOS V906 / 157178	FNA	6086	15.01.2010
034/2007	SK 4070H / 15932	FRC	6087	12.01.2010
035/2007	NO 16580 / 107135	FRC	6088	15.01.2010
037/2007	LRA R912 / 5020901	FRC	06 1286, MR79	11.2012
039/2007	CSCE15 / SYKR-192/01	IN	5611, 6090	12.2012
040/2007	CSCE15 / SYKR-192/02	IN	5611, 6091	01.2013
041/2007	A.MI.CO / SYKR-055/01	IN	5611, 6092	01.2013
042/2007	BI 4939A / 5018332	FRC	06 1281, MR79	10.2012
043/2007	KNT X272 / 28025	FRC	6093	18.01.2010
045/2007	WPI 1U36 / 438817	FRC	6095	19.01.2010
046/2007	WGR T324 / 431470	FRC	6096	19.01.2010
047/2007	WN 69770 / 2000650	FRC	03 1170, 6097	10.2011
048/2007	BI 87845 / NI 015	FNA/X	4760, M591-A, 6098	10.2012
049/2007	BI 87843 / NI 017	FNA/X	4760, M591-A, 6099	10.2012
050/2007	BI 87844 / NI 016	FNA/X	4760, M591-A, 6100	10.2012
051/2007	BI 4930A / 432193	FRC	6101	22.01.2010
052/2007	WL 3572A / 5000754	FRC	6102	17.01.2010
053/2007	AA8816XX / 11007106	FRC	4560, M608, 6103	06.2012
054/2007	SCI MG60 / 7810699A	FRC	6104	24.01.2010
056/2007	OP 40440 / 436818	FRC	6106	23.01.2010
058/2007	WMA 21AV / 29.567	FRC	3285T, M523	30.06.2010
060/2007	WL 14816 / 24479	FRC	6107	29.01.2010
061/2007	KWA P595 / 007UB4164	FRC	6108	01.02.2010
062/2007	LU 6645P / 5020767	FRC	06 1286, MR79	10.2012
063/2007	LU 6644P / 5020766	FRC	06 1286, MR79	10.2012
066/2007	SUDNSICTZ68010773/11016276	FRC	4838,MR79, 6109	12.2012
067/2007	SUDNSICTZ68010776/11019426	FRC	4838,M576, 6110	12.2012
068/2007	PN 24619 / 11016436	FRC/X	5547,M518, 6111	12.2012
069/2007	GD 6185P / 11017976	FRC	4560,MR92, 6112	12.2012
070/2007	WZ 64466 / 5023197	FRC	3379T,MR79	01.2013
071/2007	WZ 64006 / 5020740	FRC	06 1286, MR79	10.2012
072/2007	WZ 64008 / 5020741	FRC	06 1286, MR79	10.2012

073/2007	WSMS748000097700	FRC	6115	31.01.2010
074/2007	WKOSVKT24W9806221	FRC	6116	01.02.2010
075/2007	WSMS7480000437329	FRC	6117	08.02.2010
076/2007	WKESDR27011274640 / 26679	FRC	6118	08.02.2010
077/2007	WSMS7780000435814	FRC	6119	08.02.2010
078/2007	WSM00000005018363	FRC	3374T,MR79	08.2012
079/2007	WSM00000005016004	FRC	3367T,MR79	05.2012
080/2007	SUDNS1CTZ68010772 / 11014646	FRC	4838,M576, 6120	12.2012
081/2007	SUDNS1CTZ71011911 / 11019496	FRC	4838,M576, 6121	12.2012
082/2007	XLDTXZ33900039769 / 21261	FRC	6122	15.01.2010
083/2007	WKESDR27061248656 / 33991	FRC	6123	14.12.2011
084/2007	WSMS7480000448377	FRC	6124	09.02.2010
086/2007	057465	FNA	6126	10.02.2010
087/2007	WDB6534631K014858 / 26-4420	FNA	6127	10.02.2010
088/2007	WMAL880540Y035426 / 24721	FRC	6128	10.02.2010
089/2007	VM3LVFS3FY1R01095 / 00C0367-001	FRC	6129	10.02.2010
090/2007	VHRS3803A32C01765 / 203239	FRC	6130	12.02.2010
091/2007	VFNSYY3CXRAR04902 / 508033	FNA	6131	09.02.2010
092/2007	WSMS7480000402465	FRC	6132	10.02.2010
093/2007	WSMS7480000402316	FRC	6133	10.02.2010
094/2007	WSMS7480000410624	FRC	6134	09.02.2010
095/2007	VVCSORXBAS4W00166 / 14037	FRC	6135	10.02.2010
096/2007	WKOSVKT24X9838353	FRC	6136	10.02.2010
097/2007	WSMS7480000440157	FRC	6137	09.02.2010
098/2007	WMAM390209Y025923	FNA	6138	10.02.2010
099/2007	WMAM390208Y025921	FNA	6139	10.02.2010
100/2007	WAFXXXXXXRN010700	FNA	6140	09.02.2010
101/2007	WSMS7480000455625	FRC	6141	12.02.2010
102/2007	WSMS748000077175	FNA	6142	12.02.2010
103/2007	SUDNS1CTZ71011509 / 11017956	FRC	4838,M576, 6143	01.2013
104/2007	WSM00000005023582	FRC	06 1286, MR79	01.2013
105/2007	WKESDR27051232376 / 32.295	FRC	6144	15.02.2010
106/2007	WSM00000005018360	FRC	3374T,MR79	08.2012
107/2007	WSM00000005018362	FRC	3374T,MR79	08.2012
108/2007	VF9LVFS3EL2365290	FNA	6145	16.02.2010
109/2007	WSMS7480000439533	FRC	6146	16.02.2010
110/2007	WSM00000005012637	FRC	3367T, M576, 6147	05.2012
111/2007	WSMS7480000453578	FRC	6148	18.02.2010
112/2007	WSMS7480000456198	FRC	04 1183, MR79, 6149	06.2010
113/2007	WSM00000005012648	FRC	3362T, M576, 6150	02.2012
114/2007	WSM00000005003155	FRC	3338T, M509, 6151	01.2011
115/2007	WSMS7480000453579	FRC	6152	16.02.2010
116/2007	VM3LVFS3F21A04666 / 02C0677.001	FRC	6153	17.02.2010
117/2007	WSMS7480000435622	FRC	6154	17.02.2010
118/2007	WSMS7480000437237	FRC	6155	17.02.2010
119/2007	WSMS7480000437210	FRC	6156	17.02.2010
120/2007	WKOSVKT24W9806122	FRC	6157	17.02.2010
121/2007	WSMS7480000418630	FRC	6158	17.02.2010
122/2007	WSMS7480000446073	FRC	6159	17.02.2010
123/2007	WSM00000005001449	FRC	6160	17.02.2010
124/2007	WSM00000005001403	FRC	6161	17.02.2010
125/2007	WSMS7480000457648	FRC	6162	18.02.2010
126/2007	WSMS7480000443020	FRC	6163	17.02.2010
127/2007	WSMS7480000451918	FRC	6164	18.02.2010
128/2007	WSMS7480000450879	FRC	6165	17.02.2010
129/2007	WSMS7480000459863	FRC	03 1180, M576, 6166	06.2010
130/2007	WSM00000005003274	FRC	03 1180, M576, 6167	01.2011
131/2007	WSM00000005013612	FRC	05 1248, 3150K, 6168	03.2012
132/2007	WSM7780000070232	FNA	6169	17.02.2010
134/2007	WSM00000005009509	FRC	6171, 03 1165, M576	31.10.2011
135/2007	WSM00000005014863	FRC	05 1275, MR79, 6172	04.2012
137/2007	WSMS7780000435005	FRC	6174	18.02.2010
138/2007	WSMS7480000439393	FRC	6175	18.02.2010

139/2007	WSM00000005013770	FRC	05 1251, MR79, 6176	03.2012
140/2007	WSM00000005023175	FRC	06 1286, MR79	02.2013
141/2007	WSM00000005023176	FRC	06 1286, MR79	02.2013
147/2007	WSM00000005021570	FRC	3348T, MR79	11.2012
148/2007	WSM00000005021571	FRC	3348T, MR79	11.2012
149/2007	WSM00000005021569	FRC	3348T, MR79	11.2012
150/2007	WSM00000005021568	FRC	3348T, MR79	11.2012
151/2007	WSM00000005023194	FRC	3379T, MR79	01.2013
152/2007	WSM00000005023195	FRC	3379T, MR79	01.2013
153/2007	WSM00000005024925	FRC	06 1286, MR79	02.2013
154/2007	WSM00000005005338	FRC	3338T, MR79, 6177	03.2011
155/2007	YA914703806982950 / F80001.630582	FRC	6178	19.02.2010
156/2007	XLDTXZ33900041050 / 42794	FRC	6179	20.02.2010
157/2007	WSM00000005024048	FRC	06 1286,M576	01.2013
158/2007	SUDNS1CTZ71011927 / 11019476	FRC	4838, MR79, 6180	12.2012
159/2007	WSMS748000088322	FRC	6181	12.2009
160/2007	WSMS7480000560053	FRC	6182	23.02.2010
161/2007	WKESDR27011380935 / 27133	FRC	6183	27.02.2010
162/2007	WSM00000005024044	FRC	06 1286, M576	01.2013
163/2007	WSM00000005024047	FRC	06 1286, M576	02.2013
164/2007	WSMS7480000460804	FRC	05 1275, M576 , 6185	11.2011
165/2007	WKESDR27011264486 / 254353	FRC	6186	23.02.2010
166/2007	VM4CD385G3A050402 / 57625	FRC	6187	26.02.2010
167/2007	VM3LVFS3EW1R08195 / 98/C1334-001	FRC	6188	26.02.2010
168/2007	VM3LVFS3F31R07240 / 03C1197/001	FRC	6189	26.02.2010
169/2007	WSM00000005023200	FRC	3379T, MR79	01.2013
170/2007	WSM00000005023199	FRC	3379T, MR79	01.2013
171/2007	WSMS7780000446645	FRC	6191	01.03.2010
172/2007	WSM0000000500885	FRC	05 1269, MR81 , 6192	11.2011
173/2007	XLRAE45FF7L328414 / 11017496	FRC	5547, M515, 6203	01.2013
174/2007	VF644AGL000000505 / 11000687	FRC	4560, M572, 6204	02.2013
175/2007	XLER6X20005165064 / 11017066	FRC	4560, MR89, 6205	01.2013
176/2007	WK0S0002400078907 / 11019176	FRC	4838,M576, 6206	02.2013
177/2007	WK0S0002400078906 / 11019166	FRC	4838,M576, 6207	02.2013
178/2007	WK0S0002400078891 / 11018126	FRC	4838,M576, 6208	02.2013
179/2007	ZCFC3584075650369 / 11016656	FRC/X	5011,M518, 6209	01.2013
180/2007	ZCFC3584075650368 / 11016646	FRC/X	5011,M518, 6210	01.2013
181/2007	WSMS7780000455757	FRC	6193	02.03.2010
182/2007	WSMS7780000455754	FRC	6194	02.03.2010
183/2007	W09TK0335VLN14083	FRC	6195	02.03.2010
184/2007	VK1ST39WHPA300120 / 204175	FRC	6196	02.03.2010
185/2007	WSMS7480000438607	FRC	6197	02.03.2010
186/2007	WSMS7480000436431	FRC	6198	02.03.2010
187/2007	WK0SVKT24W9806214	FRC	6199	02.03.2010
188/2007	TRGSAF335WD121952	FRC	6200	02.03.2010
189/2007	WSMS7480000436433	FRC	6201	02.03.2010
190/2007	WK0SVKT24W9806215	FRC	6202	02.03.2010
191/2007	SUSL1422VY0000380 / 006014	FRC	6211	07.03.2010
192/2007	WSM00000005024727	FRC	3379T, 6212	01.2013
193/2007	ZCBF111EFY0P59240 / M-123-110	FRC	6213	08.03.2010
194/2007	VM3LVFS3E11R10576 / 01C0302.004	FRC	6214	08.03.2010
195/2007	SUDNS1CTZ71012396 / 11000647	FRC	4838, M576, 6215	09.03.2013
196/2007	SUDNS1CTZ71012394 / 11000627	FRC	4838,MR79, 6216	02.2013
197/2007	SUDNS1CTZ68010765 / 11012546	FRC	4838,M576, 6217	10.2012
198/2007	SUDNS1CTZ68010766 / 11012556	FRC	4838,M576, 6218	10.2012
199/2007	SUDNS1CTZ68010767 / 11012566	FRC	4838,M576, 6219	10.2012
200/2007	XLER6X20005165262 / 11019666	FRC	4560, MR92, 6220	02.2013
201/2007	SUDNS1CTZ68010777 / 11014666	FRC	4838, MR79, 6221	12.2012
203/2007	WSMS7780000093446	FRC	6223	31.12.2009
204/2007	WKOSVKT2440527251	FRC	6224	10.03.2010
205/2007	WSMS7480000432060	FRC	6225	10.03.2010
206/2007	SUZNOJ00RWZ000005 / 809016	FRC	6226	10.03.2010
207/2007	VSRSZ3L00ML052655 / 17067	FRC	6227	10.03.2010
208/2007	VF9LVFS3EM3365335 / 91/0624-001	FNA	6228	10.03.2010

209/2007	VFKX34VCY2EX0521 / 48697	FRC	6229	10.03.2010
210/2007	VK1S338RCPB000369 / 99170	FRC	6230	10.03.2010
211/2007	WSM00000005023150	FRC	06 1286, 6231	01.2013
212/2007	VM3LVFS3FY1R02020 / 00C2613/002	FRC	6232	10.03.2010
213/2007	VS93105SNVL052459 / 38011	FRC	6233	25.11.2009
214/2007	WSMS7480000441832	FRC	6234	12.03.2010
215/2007	WKESDR27071288106 / 36.633	FRC	3383T, MR79	01.2013
216/2007	WKESDR27071288102 / 36.629	FRC	3383T, MR79	01.2013
217/2007	WMV30KS27WL244800	FRC	6235	14.03.2010
218/2007	WMV30KS27WL244798	FRC	6236	14.03.2010
219/2007	VFNSYY3KEXAR00820 / 45782	FRC	6237	15.03.2010
220/2007	TP2820062V0398 / 812022	FNA	6238	14.03.2010
221/2007	VF1UDC1K637133847 / 11000047	FNA/X	4561, M591, 6239	02.2013
222/2007	VF1UDC1K637133846 / 11000057	FNA/X	4561, M591, 6240	02.2013
223/2007	WSMS7480000432882	FRC	6241	14.03.2010
224/2007	XLRS47XS0E467567	FRC	6242	15.03.2010
225/2007	WSM00000005023160	FRC	06 1286, MR79	02.01.2013
228/2007	WSM00000005024726	FRC	3379T, MR79	01.2013
230/2007	WKESDR27011272458 / 26351	FRC	6244	17.03.2010
231/2007	WDB9700581K815629	FRC	6245	17.03.2010
232/2007	VF622CVA000103324 / 44088	FRC	6246	17.03.2010
234/2007	WSMS7480000440697	FRC	6248	21.03.2010
235/2007	SUZPOC02RYZ000028 / 003066	FRC	6249	21.03.2010
236/2007	WSMS7480000072716	FNA	6250	22.03.2010
237/2007	WSMS7480000434721	FRC	6251	22.03.2010
238/2007	SUZNOJ00RXZ000010 / 909006	FRC	6252	23.03.2010
239/2007	VM4CD382GYA020076 / 48424	FRC	6253	21.03.2010
240/2007	VF644AGL000000543 / 11000697	FRC	4560, M572, 6254	03.2013
241/2007	VF1UDC1K637261546 / 11000067	FNA/X	4561, M591, 6255	02.2013
242/2007	VF1UDC1K637261547 / 11000077	FNA/X	4561, M591, 6256	02.2013
243/2007	WSM00000005023178	FRC	06 1286, MR79	02.2013
244/2007	WSM00000005023177	FRC	06 1286, MR79	02.2013
245/2007	WSM00000005023584	FRC	06 1286, MR79	01.2013
246/2007	WSM00000005023583	FRC	06 1286, MR79	01.2013
247/2007	VM4C381BNWA003936 / 39335	FRC	6257	20.02.2010
248/2007	SUDNS1CTZ71012397 / 11019486	FRC	4838, M576, 6263	12.2012
251/2007	WKESDR27011499800 / 29.721	FRC	3290T, MR79	31.12.2009
252/2007	WKESDR27071288120 / 36.647	FRC	3383T, MR79	01.2013
253/2007	VM4CD382G1A020173 / 48498	FRC	6264	02.2010
254/2007	WSM00000005027261	FRC	07 1295, MR79	04.2013
255/2007	WSM00000005003064	FRC	3338T, MR79, 6265	01.2011
256/2007	VM3LVFS3F11R02460 / 01C3812-001	FRC	6266	01.04.2010
257/2007	WSM00000005001405	FRC	6267	01.04.2013
258/2007	WSM00000005020917	FRC	03 1178, MR79, 6268	11.2012
259/2007	WSM00000005014859	FRC	06 15275, MR79, 6269	04.2012
260/2007	VM3LVFS3ER1A02583 / 94C1320.002	FNA	6270	31.03.2010
262/2007	WKESDR27011267988	FRC	6272	30.03.2010
263/2007	WKOSVKT24W9892782	FRC	6273	31.03.2013
264/2007	WSMS7480000413716	FRC	6274	31.03.2010
265/2007	1JJV443W2WL442035 / 98/3836	FRC	6275	31.12.2009
267/2007	WSMS7480000456043	FRC	6277	01.04.2010
268/2007	WSMS7480000455438	FRC	6278	31.03.2010
269/2007	WSM00000005023167	FRC	06 1286, MR79	01.2013
270/2007	WSM00000005023168	FRC	06 1286, MR79	01.2013
271/2007	WSMS7780000452098	FRC	6279	04.04.2010
272/2007	WSMS7780000438659	FRC	6280	06.04.2010
273/2007	WSMS7780000439319	FRC	6281	06.04.2010
274/2007	WSMS7480000440574	FRC	6282	06.04.2010
275/2007	WSM00000005024934	FRC	06 1286, MR79	02.2013
276/2007	VM4CD381J3A011983 / 58312	FRC	6283	06.04.2010
277/2007	VM3LVFS3F11R02599 / 01C0137.007	FRC	6284	10.04.2010
278/2007	WDB9702771K726454 / U065/04	FRC	6285	10.04.2010
279/2007	VM3LVFS3FY1A00909 / 00C3045.001	FRC	6286	11.04.2010
280/2007	YA914703810972674 / F7A46241	FRC	6287	11.2009

281/2007	WKESDR27071288114 / 36.641	FRC	3383T, MR79	01.2013
282/2007	WSM00000005023182	FRC	06 1286, MR79	02.2013
283/2007	VM3LVS3F31R06636 / 03C0132.001	FRC	6289	12.04.2010
284/2007	WSMS7480000432673	FRC	6290	12.04.2010
285/2007	WMAL35ZZZYY059668 / 909044	FRC/X	6291	13.04.2010
286/2007	WDB9702571K472281 / 46530	FRC	6292	13.04.2010
287/2007	WSMS748000083371	FRC	6293	31.12.2009
288/2007	WSMS748000097417	FRC	6294	31.12.2009
289/2007	VGUST338A34058498/FB 93204	FRC	6295	14.04.2010
290/2007	WSMS748000092394	FRC	6296	31.12.2009
291/2007	WSMS748000092386	FRC	6297	31.12.2009
292/2007	WSMS7780000404164	FRC	6298	14.04.2010
293/2007	WSMS748000092388	FRC	6299	31.12.2009
294/2007	WSMS778000085891	FRC	6300	31.12.2009
295/2007	WSMA7420000419923	FRC	6301	14.04.2010
296/2007	VK1SR334FCR2P3939 / 28808	FNA	6302	14.04.2010
297/2007	WSM00000005024935	FRC	06 1286, MR79	02.2013
298/2007	WSM00000005021929	FRC	03 1142, MR79	10.2012
299/2007	VM4CD381JXA000778 / 45067	FRC	6303	14.04.2010
300/2007	WSM00000005020729	FRC	06 1286, MR79	10.2012
301/2007	VV1LTF3E0SNX79812 / 17231	FRC	6304	14.04.2010
302/2007	WSM00000005023180	FRC	06 1286, MR79	02.2013
303/2007	WK0S0002400078894 / 11003777	FRC	4838, M576, 6305	04.2013
304/2007	SUDNS1CTZ71012102 / 11003867	FRC	4838, M576, 6306	03.2013
305/2007	WK0S0002400078892 / 11003397	FRC	4838, M588, 6307	04.2013
306/2007	SUDNS1CTZ71012500 / 11001117	FRC	4838, M576, 6308	03.2013
307/2007	SUDNS1CTZ71012395 / 11000637	FRC	4838, M576, 6309	03.2013
308/2007	SUDNS1CTZ72012750 / 11015196	FRC	4838, M576, 6310	12.2012
309/2007	VFNSYY3CXVAR13285 / 38351	FRC	6311	31.12.2009
310/2007	VM4CD381JYA001618 / 47296	FRC	6312	18.04.2010
311/2007	VM4CD381J1A010840 / 51863	FRC	6313	14.04.2010
312/2007	VM4CD381A010838 / 51861	FRC	6314	14.04.2010
313/2007	WSM00000005023204	FRC	3379T, MR79	01.2013
314/2007	WSM00000005023203	FRC	3379T, MR79	01.2013
315/2007	WSM00000005023201	FRC	3379T, MR79	01.2013
316/2007	WKOSVKT24W9892023	FRC	6315	20.04.2010
317/2007	WSM00000005024084	FRC	6316	18.04.2010
318/2007	WSM00000005024027	FRC	06 1286, M576, 6317	01.2013
319/2007	WSM00000005024026	FRC	06 1286, M425, 6318	01.2013
320/2007	WKESDR27041204659/ 30085	FRC	6319	23.04.2010
321/2007	WSMS7480000455768	FRC	04 1183, MR79	26.02.2010
322/2007	WKESDR27071288116 / 36.643	FRC	3383T, MR79	01.2013
323/2007	WKESDR27071288115 / 36.642	FRC	3383T, MR79	01.2013
324/2007	WMAN26ZZ27Y190077 / 480207	FNA/X	4797, M589, 6319	04.2013
325/2007	VM3LVFS3DW1A00034 / 98/00669-001	FRC	6320	26.04.2010
326/2007	VM3LVFS3ER3R01868 / 94/C0615-003	FNA	6321	26.04.2010
327/2007	SUDNS1CTZ68010778 / 11015186	FRC	4838, MR79, 6322	12.2012
328/2007	SUDNS1CTZ71012187 / 11020006	FRC	4838, M576, 6323	12.2012
329/2007	WK0S0002400078902 / 11004667	FRC	4838, M576, 6324	04.2013
330/2007	WK0S0002400078897 / 11004647	FRC	4838, MR79, 6325	04.2013
331/2007	WSM000000005009301	FRC	3352T, MR79	09.2011
332/2007	VM4CD385G3A050398 / 57623	FRC	6326	27.04.2010
333/2007	WM4CD381J3A11710 / 56905	FRC	6327	27.04.2010
334/2007	WSMS748000090479	FRC	6328	31.12.2009
335/2007	VM4CD381J1A010117 / 49888	FRC	6329	28.04.2010
336/2007	WKOSVKT24W0206161	FRC	6330	07.05.2010
339/2007	WSMSKO24000064115	FNA	6334	08.05.2010
342/2007	WSM00000005024398	FRC	07 1295, MR79	02.2013
343/2007	WSM00000005023181	FRC	06 1286, MR79	02.2013
344/2007	ZCFA1EG1372510204 / 11003597	FRC	4968, MR79, 6337	04.2013
345/2007	WFDFLT33541001141/ 11002084	FRC	4699	30.04.2010
346/2007	SUDNS1CTZ71012501 / 11001127	FRC	4838, M576, 6338	03.2013
347/2007	SUDNS1CTZ670107673 / 11014226	FRC	4838, M576, 6339	11.2012
349/2007	WK0S0002400078895 / 11015206	FRC	4838, MR79, 6341	04.2013

350/2007	WK0S0002400078896 / 11004637	FRC	4838,M576, 6342	04.2013
351/2007	WK0S0002400078901 / 11004657	FRC	4838,MR79, 6343	04.2013
352/2007	VM4S3391BVA036773 / 36773	FRC	6344	31.12.2009
353/2007	WSMS7780000092661	FRC	6345	31.12.2009
354/2007	W09TK0335VGN14086	FRC	6346	31.12.2009
355/2007	XL9DO27VXTM006057 / 36968	FRC	6347	31.12.2009
356/2007	WSMS7480000095760	FRC	6348	31.12.2009
357/2007	VM4CD385G2A05022 / 54500	FRC	6349	12.05.2010
358/2007	WSM00000005023188	FRC	06 1286, MR79	03.2013
359/2007	WKESDR27071303118 / 37332	FRC	3383T, M523, 6350	15.03.2013
360/2007	WSMS7480000437726	FRC	6351	13.05.2010
361/2007	VVCS0RXBCS4201247 / 19234	FRC	6352	12.05.2010
362/2007	VK1S338RCPB001044	FRC	6353	05.2010
363/2007	96-104-FB4-9069 / OP-14079	IR	6354	16.05.2013
364/2007	VM3LVFS3E11R10573 / 01C0302.001	FRC	6355	17.05.2010
365/2007	VM3LVFS3F14R03225	FRC	6356	14.05.2010
366/2007	VM3LVFS3FY1R10318 / 01C1796.001	FRC	6357	18.05.2010
367/2007	WKOSVKT2410269399	FRC	6358	19.05.2010
368/2007	VM3LVFS3FY1202003 / 00C2567.018	FRC	6359	19.05.2010
371/2007	VM3LVFS3F11A03927 / 01C2271.003	FRC	6362	14.05.2010
372/2007	VFNSYY3CXRAR05310 / 31774	FNA	6363	14.05.2010
373/2007	VM3LVFS3ER3A01469/ 94/C0042-006	FNA	6364	21.05.2010
375/2007	WSM00000005024938	FRC	07 1295, MR79	02.2013
376/2007	VP3S34EBT6FPD0153 / 14596	IN	BX 4498 C 398	13.09.2012
377/2007	VP3S34EBT6FPD0152 / 14595	IN	BX 4498 C 398	25.07.2012
378/2007	VP3S34EBT6FPD0149 / 14592	IN	BX 4498 C 398	11.07.2012
379/2007	VP3S34EBT6FPD0148 / 14591	IN	BX 4498 C 398	26.06.2012
380/2007	VP3S34EBT6FPD0150/ 14593	IN	BX 4498 C 39	10.07.2012
381/2007	VP3S34EBT6FPD0154 / 14597	IN	BX 4498 C 398	13.09.2012
382/2007	VP3S34EBT6FPD0145 / 14588	IN	BX 4498 C 398	21.06.2012
383/2007	VP3S34EBT6FPD0147 / 14590	IN	BX 4498 C 398	21.06.2012
384/2007	VP3S34EBT6FPD0146 / 14589	IN	BX 4498 C 398	21.06.2012
385/2007	VP3S34EBT6FPD0151/ 14594	IN	BX 4498 C 398	22.07.2012
387/2007	SUDNS1CTZ72012749 / 11005787	FRC	4838,MR79, 6367	03.2013
388/2007	XLRAE55GF7L330027 / 11001177	FNA/X	4838, M564, 6368	03.2013
389/2007	XLRAE55GF7L330072/ 11001187	FNA	4838, MR91, 6369	03.2013
390/2007	SUDNS1CTZ72012751 / 11002747	FRC	4838,M576, 6370	04.2013
391/2007	WSM00000005020728	FRC	06 1286, MR79	10.2012
392/2007	WKESDR27011274992 / 26096	FRC	6371	25.05.2010
393/2007	VAVSAF335YH148234 / 171UC3670	FRC	6372	28.05.2010
394/2007	WSMS7480000403024	FRC	6373	29.05.2010
395/2007	WSM00000005026985	FRC	07 1295, MR79	04.2013
396/2007	WSM00000005026984	FRC	07 1295MR79	04.2013
397/2007	WSM00000005026983	FRC	07 1295, MR79	04.2013
398/2007	WKESDR27051234930/32620	FRC	6374, 3344T, M576	17.02.2011
399/2007	WSM00000005026977	FRC	07 1295,MR79	04.2013
401/2007	WSM00000005024943	FRC	07 1295, MR79	31.03.2013
402/2007	WSM00000005024918	FRC	06 1281, MR79	28.02.2013
403/2007	WSM00000005024914	FRC	06 1281, MR79	28.02.2013
404/2007	WSM00000005024939	FRC	07 1295, MR79	31.03.2013
405/2007	WSMS7480000435845	FRC	6375	25.05.2010
406/2007	VM3LVFS3ER3A01940/94C0642.035	FNA	6376	26.05.2010
407/2007	WSMS7480000091608	FRC	6377	31.12.2009
408/2007	YV2A4B3CXWA282313	FNA	6378	26.05.2010
409/2007	VK1SR224FVP4T0140	FNA	6379	26.05.2010
412/2007	WKESDR27011157720/24911	FRC	6382	2.05.2010
413/2007	WK0SVKA2410274067	FRC	6383	26.05.2010
414/2007	WSM00000005024729	FRC	6384, 07 1295, M443	28.02.2013
415/2007	WKESDR27011387126	FRC	6385	26.05.2010
417/2007	WKESDR27011380136/27188	FRC	6386	25.05.2010
418/2007	WSMSK024000067544	FNA	6387	31.05.2010
419/2007	VF622AXA0A0002385/36042	FRC	6388	12.2009
420/2007	SUDNS1CTZ71012318/11020026	FRC	6389, 4838, MR79	04.2013
421/2007	WSMS7780000443509	FRC	6390	01.06.2010

422/2007	WKESDR27011269067	FRC	6391	04.06.2010
423/2007	WSMS7480000448252	FRC	6392	01.06.2010
424/2007	WSM00000005025333	FRC	07 1295, MR79	04.2013
425/2007	WMAN26ZZ97Y190044/490207	FNA/X	6393, 4797, M589	31.05.2013
426/2007	WSM00000005027009	FRC	07 1295, MR79	30.04.2013
428/2007	WK0S0002400078898/11006807	FRC	6394, 4838, M576	31.05.2013
429/2007	WK0S0002400078900/11006827	FRC	6395, 4838, M576	31.05..2013
430/2007	WK0S0002400078899/11006817	FRC	6396, 4838, M576	31.05..2013
431/2007	WK0S0002400078904/11006837	FRC	6397, 4838, M576	31.05..2013
432/2007	WK0S0002400078905/11006847	FRC	6398, 4838, M576	31.05..2013
433/2007	WSMS7480000437731	FRC	6399	11.06.2010
434/2007	WSM00000005023232	FRC	06 1286, MR81	31.01.2013
435/2007	WKOSVKT24W9823934	FRC	6400	09.06.2010
436/2007	WSMS7480000453568	FRC	6401	09.06.2010
437/2007	WKOSVKT24V9178596	FRC	6402	31.12.2009
438/2007	WSM00000005028695	FRC	3390T, MR79	31.05.2013
439/2007	SUDNS1CTZ71012398/11005087	FRC	6403, 4838, M576	30.04.2013
440/2007	SUDNS1CTZ71012421/11000717	FRC	6404, 4838, M576	28.02.2013
441/2007	WSMS7480000408937	FRC	6405	12.06.2010
442/2007	WKESDR27071303117/37331	FRC	6406, 3383T, M523	15.03.2013
443/2007	ZFA25000001194890/051/07	FNA/X	4760, 6407, M621	05.2013
444/2007	ZFA25000001198706/052/07	FNA/X	4760, 6408, M621	05.2013
445/2007	ZFA25000001198895/053/07	FNA/X	4760, 6409, M621	05.2013
446/2007	ZFA25000001194975/054/07	FNA/X	4760, 6410, M621	05.2013
447/2007	ZFA25000001194972/055/07	FNA/X	4760, 6411, M621	05.2013
449/2007	WSM00000005027264	FRC	07 1295, MR79	30.04.2013
450/2007	WSM00000005023053	FRC	06 1286, MR79	31.03.2013
451/2007	VS9S0R3NSW4057379	FRC	6412	14.06.2010
452/2007	SUDNS1CTZ68010768/11012846	FRC	4838, 6413	11.2012
453/2007	VM3LVFS3F11R02138/01C3010.001	FRC	6414	15.06.2010
454/2007	WSMS7780000441324	FRC	6415	16.06.2010
455/2007	WKOSVKT24Y0266993	FRC	6416	16.06.2010
456/2007	WMAL35ZZZ2Y100867/236 02 02	FNA	6417	16.06.2010
457/2007	WMAT373725W032530/98/C1020-001	FRC	6418	15.06.2010
458/2007	WSMS7480000434480	FRC	6419	17.06.2010
459/2007	WK0SVKT24V0286108	FRC	6420	31.12.2009
460/2007	WSMS7480000419020	FRC	6421	17.06.2010
461/2007	WSMS7480000444382	FRC	6422	16.06.2010
462/2007	WK0SVKT2430206629	FRC	6423	16.06.2010
463/2007	WSMS7480000455346	FRC	6424	16.06.2010
464/2007	WSMS7480000455347	FRC	6425	16.06.2010
465/2007	WKOSVKT2430206628	FRC	6426	16.06.2010
467/2007	ZCFC35A4055553054/11002546	FNA/X	6428, 4561, M591	31.03.2012
468/2007	VS9SA3NS62A013870/ C14234	FRC	6429	22.06.2010
469/2007	WSM00000005028686	FRC	3390T, MR79	05.2013
470/2007	WSMS7480000098552	FRC	6430	22.06.2010
471/2007	WSM00000005024400	FRC	07 1295, MR79	03.2013
472/2007	WSM00000005028688	FRC	3390T, MR79	31.05.2013
473/2007	WKESDR27041200910/30622	FRC	3276T, MR79	30.06.2010
474/2007	XLDTXZ33900041006/39851	FRC	6431	25.06.2010
475/2007	WSM00000005024949	FRC	06 1286, MR79	28.02.2013
476/2007	WSM00000005024948	FRC	06 1286, MR79	28.02.2013
477/2007	WSM00000005023228	FRC	3379T, MR79	31.01.2013
478/2007	WSM00000005023229	FRC	3379T, MR79	28.02.2013
479/2007	WSM00000005024950	FRC	06 1281, MR79	28.02.2013
480/2007	WSM00000005023230	FRC	3379T, MR79	31.03.2013
481/2007	WSM00000005023224	FRC	06 1286, MR 79	31.01.2013
482/2007	WSM00000005023223	FRC	3379T, MR79	31.01.2013
483/2007	WSM00000005024953	FRC	06 1281, MR79	28.02.2013
484/2007	WSM00000005023227	FRC	3379T, MR79	31.01.2013
485/2007	WSMS7480000407676	FRC	6433	26.06.2010
486/2007	WSMS7480000453965	FRC	5013.3, 03 1161, MR79	31.10.2009
487/2007	WSM00000005023058	FRC	07 1295, MR79	02.04.2013
488/2007	WSM00000005023059	FRC	07 1295, MR79	02.04.2013

489/2007	WSM00000005024735	FRC	07 1295, MR79	02.04.2013
490/2007	WSM00000005027270	FRC	07 1295, MR79	02.04.2013
491/2007	WSM00000005027271	FRC	07 1295, MR79	02.04.2013
492/2007	WSM00000005027313	FRC	07 1295, MR79	02.04.2013
493/2007	WSM00000005027314	FRC	07 1295, MR79	02.04.2013
494/2007	WSM00000005023580	FRC	07 1295, MR79	02.04.2013
495/2007	WSM00000005023040	FRC	07 1295, MR79	02.04.2013
496/2007	WSM00000005028708	FRC	07 1303, MR79	30/06.2013
499/2007	WSM00000005028685	FRC	3390T, MR79	31.05.2013
500/2007	WSMS7480000444789	FRC	6436	23.06.2010
501/2007	WSMS7480000441970	FRC	6437	23.06.2010
502/2007	WKK41700001013270	FNA	6438	23.06.2010
503/2007	VM4C381BRWA004226/40096	FRC	6439	23.06.2010
504/2007	WSMS7780000449821	FRC	6440	25.06.2010
505/2007	WSM00000005004871	FRC	6441	31.01.2012
506/2007	052075	FNA	6442	25.06.2010
507/2007	WSMS7480000444798	FRC	6443	25.06.2010
508/2007	WSMSKO27000095028	FNA	6444	26.06.2010
509/2007	WK0S0002400075522	FRC	6445, 3288T, 3150K	11.04.2013
510/2007	WSMS7780000446444	FRC	6446	29.06.2010
511/2007	WSMS7480000436447	FRC	6447	29.06.2010
512/2007	WSM00000005028614	FRC	07 1303, MR79	31.05.2013
513/2007	VM3LVFS3F24R04348/02C0186.003	FRC	6448	02.07.2010
514/2007	WSM00000005028727	FRC	3390T, MR79	30.06.2013
515/2007	WSM00000005020759	FRC	06 1281, MR79	31.10.2012
516/2007	WSM00000005028707	FRC	3390T, MR79	31.05.2013
517/2007	VM3LVFS3EW1R08332/98/C1515-002	FRC	6449	04.07.2010
518/2007	SUDNS1CTZ72012752/11002757	FRC	6450, 4838, M576	30.04.2013
520/2007	WSM00000005028715	FRC	07 1303, MR79	30.06.2013
521/2007	WSMS7480000072167	FNA	6451	06.07.2010
522/2007	WKOSVKT24V2181550	FRC	6452	31.12.2009
523/2007	ZCFC65D0075651263/07.03.64	IR	6453	05.07.2013
525/2007	WSM00000005003483	FRC	6455, 03 1180, M479	31.12.2010
528/2007	YV2J4DGA421203281/112285	FRC	6456	11.07.2010
529/2007	WKESDR27011269038/26003	FRC	6457	11.07.2010
530/2007	WKESDR27011496238/28958	FRC	6458	11.07.2010
531/2007	WK0SVKT24Y0266994	FRC	6459	13.07.2010
534/2007	VM3LVFS3F24R06465/02C2465.004	FRC	6462	12.07.2010
535/2007	VM3LVFS3F24R06464/02C2465.003	FRC	6463	12.07.2010
536/2007	VM3LVFS3EW1A07130	FRC	6464	12.07.2010
537/2007	SUDNSICTZ67010672/11014656	FRC	4838, MR79, 6465	12.2012
539/2007	YV2A4B3C1RB123615/30483	FNA	6467	14.07.2010
540/2007	WSMS7480000452285	FRC	6468	14.07.2010
541/2007	WSMS7480000452286	FRC	6469	14.07.2010
542/2007	WKESDR27011152069/24269	FRC	6470	14.07.2010
543/2007	0000RIGIN2189285A/31468	FNA	6471	14.07.2010
544/2007	ZCFA1LJ0132401073	FNA/X	6472	14.07.2010
545/2007	WSMS7780000404167	FRC	6473	13.07.2010
546/2007	WKOSVKT2420283791	FRC	6474	13.07.2010
547/2007	WSMS7480000435910	FRC	6475	13.07.2010
549/2007	WKOSVKT24Y9853055	FRC	6477	13.07.2010
550/2007	VM3LVFS3EW1R08032/98C1711-002	FRC	6478	13.07.2010
551/2007	WSMS7480000444715	FRC	6479	13.07.2010
552/2007	WSMS7480000435676	FRC	6480	13.07.2010
554/2007	160260	FRC	6482	31.03.2010
555/2007	2122143/22-65402	FNA	6483	14.07.2010
556/2007	WSMS7780000438660	FRC	6484	14.07.2010
557/2007	XLEP4X20004419055/20067	FRC	6485	14.07.2010
558/2007	WSM00000005024012	FRC	07 1303, MR79	31.01.2013
559/2007	WSM00000005029585	FRC	3390T, MR79	31.06.2013
560/2007	WSM00000005028789	FRC	07 1303, MR79	31.05.2013
561/2007	SUDNS1CTZ73013296/11007277	FRC	6486, 4838, M576	31.07.2013
563/2007	WSM00000005028814	FRC	3390T, MR79	30.06.2013
564/2007	WDB9502031K492345/11009357	FRC	6487, 4560, MR90	31.07.2013

565/2007	WSMS7480000404884	FRC	6488	20.07.2010
566/2007	XL9LABA390X150230/2851	FRC	6489	20.07.2010
568/2007	WKOSVKT24Y0266846	FRC	6490	24.07.2010
569/2007	XLRAE55CE0L166797	FRB	6491	18.07.2013
570/2007	WSM00000005028812	FRC	07 1303, MR79	17.04.2013
571/2007	WSM00000005024857	FRC	3348T, MR79	28.02.2013
572/2007	VM3LVFS3EW1R06880/98/C0002-002	FRC	6492	28.02.2010
573/2007	WSM00000005011622	FRC	6493	31.01.2012
575/2007	WSM00000005018306	FRC	6495	30.09.2012
576/2007	WSM00000005011621	FRC	6496	31.01.2012
579/2007	WSMS7480000430061	FRC	6499	28.07.2010
580/2007	WSMS7480000097189	FRC	6500	31.12.2009
581/2007	WSMS7480000431495	FRC	6501	28.07.2010
582/2007	VV1LTFR3EFL88290	FRC	6502	29.07.2010
583/2007	WSMS7480000410347	FRC	6503	29.07.2010
584/2007	XLDTXZ33900041401/43203	FRC	6504	29.07.2010
585/2007	WSMS7780000099751	FRC	6505	29.07.2010
586/2007	WSMS7780000401802	FRC	6506	29.07.2010
587/2007	VK1SR334FCP1W0563/98053	FRC	6507	29.07.2010
588/2007	WSM00000005024915	FRC	06 1281, MR79	29.01.2013
589/2007	WSM00000005028632	FRC	07 1303, MR79	30.06.2013
590/2007	WKESDR27841213811/30.622	FRC	3276T, MR79	30.06.2010
591/2007	WSM00000005025570	FRC	06 1281, MR79	31.03.2013
592/2007	WSM00000005025317	FRC	06 1281, MR79	28.02.2013
593/2007	VAVSAF3387H242834	FRC	2003/1692, M576	31.01.2013
594/2007	VAVSAF3387H242836	FRC	2003/1692, M576	31.01.2013
596/2007	WSM00000005023183	FRC	06 1286, MR79	28.02.2013
597/2007	WSM00000005028770	FRC	3390T, MR79	01.06.2013
598/2007	WSM00000005028772	FRC	3390T, MR79	01.06.2013
599/2007	WSM00000005028771	FRC	3390T, MR79	01.06.2013
600/2007	VM3LVFS3F21R04673/02C0683.001	FRC	6508	30.07.2010
601/2007	WSMS7480000456806	FRC	4607.1	28.02.2010
602/2007	VM3LVFS3F21R05364/65211	FRC	6509	31.07.2010
603/2007	WSM00000005028788	FRC	07 1303, MR79	17.04.2013
604/2007	WSM00000005028690	FRC	3390T, MR79	02.05.2013
605/2007	WSM00000005028693	FRC	3390T, MR79	02.05.2013
606/2007	WSM00000005028694	FRC	3390T, MR79	02.05.2013
607/2007	YA914703804982891	FRC	6510	31.07.2010
608/2007	WSM00000005020735	FRC	06 1286, MR79	23.10.2012
609/2007	WSM00000005028659	FRC	3390T, MR79	02.07.2013
610/2007	WKESDR27000X25175	FRC	6511	06.08.2010
611/2007	WK0S0002400057582	FRC	6512	30.06.2012
612/2007	VM3LVFS3EW1R07847/98/C1028-001	FRC	6513	31.07.2010
613/2007	WSMS7480000072466	FNA	6514	03.08.2010
614/2007	WKESDR27011267537/25227	FRC	6515	06.08.2010
615/2007	VM3LVFS3F31R05702/02C3919.01	FRC	6516	07.08.2010
617/2007	SUDNS1CTZ74013584/11009257	FRC	6518, 4838, M576	31.07.2013
618/2007	SUDNS1CTZ75013776/11009977	FRC	6519, 4838, M576	31.07.2013
619/2007	SUDNS1CTZ73013292/11000657	FRC	6520, 4838, M576	31.07.2013
620/2007	WSM00000005030494	FRC	3390T, MR79	01.06.2013
621/2007	WSM00000005030492	FRC	3390T, MR79	01.06.2013
622/2007	WSM00000005030493	FRC	3390T, MR79	01.06.2013
623/2007	WSM00000005030501	FRC	07 1295, MR79	02.04.2013
624/2007	SDCFV45B3AGB29844	FRC	6521	07.08.2010
627/2007	WDB6524581K084354/7111073	FRC	6523	30.04.2010
628/2007	WSMS7780000088252	FRC	6524	31.12.2009
629/2007	VAVSAF3387H250250	FRC	2003/1692, M576	30.04.2013
630/2007	WSM00000005023063	FRC	07 1295, MR79	02.04.2013
632/2007	ZCFC3584075650664/11008747	FRC/X	6526, 5011, M517	31.07.2013
633/2007	ZCFC3584075650663/11008737	FRC/X	6527, 5011, M517	31.07.2013
634/2007	ZCFC3584075650665/11008757	FRC/X	6528, 5011, M517	31.07.2013
635/2007	VF1UDC1G637979121/11009507	FRC/X	6529, 5011, M486	31.07.2013
636/2007	WSM00000005031608	FRC	07 1310, MR79	17.07.2013
637/2007	YB4A0FZ3399802256/98.581	FRC	6530	14.08.2010

638/2007	WSM00000005028753	FRC	07 1303, MR79	02.07.2013
639/2007	WSM00000005028752	FRC	07 1303, MR79	02.07.2013
641/2007	1JJV443W3WL442075	FRC	6532	31.12.2009
642/2007	WSMS7480000440166	FRC	6533	18.08.2010
643/2007	WSM00000005028681	FRC	07 1303, MR79	30.04.2013
644/2007	W09001335WMT35055	FRC	6534	17.08.2010
645/2007	WSMS7480000433627	FRC	6535	17.08.2010
646/2007	WKESDR27011388919	FRC	6536	17.08.2010
647/2007	WSMS7480000433724	FRC	6537	17.08.2010
648/2007	SV9PCH263WPMN1033	FRC	6538	17.08.2010
649/2007	WKESDR27011158189/25016	FRC	6539	18.08.2010
650/2007	SFRRCVSA3WR203601/ IC 985121	FRC	6540	18.08.2010
651/2007	WSM00000005024081	FRC	07 1295, 6541, MR79	31.03.2013
652/2007	VM4C382G1A020427/50274	FRC	6542	18.08.2010
653/2007	SUDNS1CTZ74013585/11009267	FRC	6543, 4838, M576	31.07.2013
654/2007	WSM00000005031509	FRC	07 1310, MR79	09.07.2013
655/2007	WSM00000005031508	FRC	07 1310, MR79	09.07.2013
657/2007	SUDNS1CTZ74013582/11009837	FRC	4838, MR79, 6544	06.08.2013
658/2007	YV2VBN0C07B477281/110115216	FRC	4560, MR92, 6545	31.07.2013
661/2007	WSM00000005030431	FRC	3390T, MR79	01.06.2013
662/2007	WSM00000005030432	FRC	3390T, MR79	01.06.2013
663/2007	YV2AS02C37B469822/11005477	FRC	4560, 6548	14.06.2010
664/2007	WSM00000005031599	FRC	07 1303, MR79	05.07.2013
665/2007	XL9TSKA011N092567	FRC	6549	24.08.2010
666/2007	WSMS7480000095387	FRC	6550	31.12.2009
667/2007	VM3LVFS3F34R07055/ 03C0737.001	FRC	6551	28.08.2010
668/2007	XLK301227X0026715 / 42779	FRC	6552	30.08.2010
669/2007	W09109335THS09420 / 9298	FRC	6553	31.12.2009
670/2007	WSMS7480000092250	FRC	6554	31.12.2009
671/2007	WK0SVKT2450735479/60451	FRC	6555	31.08.2010
672/2007	82096	FRC	6556	31.12.2009
673/2007	82222 / 97670	FRC	6557	04.09.2010
674/2007	WSMS7480000456268	FRC	6558	04.09.2010
675/2007	WKESDR27011158500/25014	FRC	6559	04.09.2010
676/2007	VM4C382G1A020222/49244	FRC	6568	06.09.2010
677/2007	WSMS7480000449642	FRC	6569	06.09.2010
678/2007	WSMS7480000439274	FRC	6566	07.09.2010
679/2007	VM4CD381J1A010210/49123	FRC	6567	07.09.2010
680/2007	XLD3139PLPAM28508/900131	FNA	6561	31.08.2010
681/2007	WSMS7980000486839	FRC	6562	29.08.2010
684/2007	WKESDR27051234764	FRC	6565	29.08.2010
685/2007	WSM00000005028767	FRC	3390T, MR79	01.06.2013
686/2007	WKESDR27071303156	FRC	6570	20.07.2013
687/2007	WKESDR27071303158	FRC	6571	20.07.2013
688/2007	WKESDR27071303160	FRC	6572	20.07.2013
689/2007	WKESDR27071303157	FRC	6573	06.09.2013
690/2007	WKESDR27011277063	FRC	6574	08.09.2010
691/2007	VM3LVFS3F21R04255/01C2749.001	FRC	6574	08.09.2010
692/2007	WSM00000005027001	FRC	07 1295, MR79	31.05.2013
693/2007	WSM00000005027031	FRC	07 1295, MR79	02.05.2013
694/2007	WSMS7480000071190	FNA	6576	11.09.2010
695/2007	VAW3SNK36SYY07686/ PB116B066	FNA	6577	11.09.2010
696/2007	WSMS7480000078873	FNA	6578	11.09.2010
697/2007	WSM00000005024022	FRC	06 1286, M576	02.01.2013
698/2007	WSM00000005028697	FRC	3390T, MR79	02.05.2013
699/2007	WSM00000005028696	FRC	3390T, MR79	02.05.2013
700/2007	WSM00000005028687	FRC	3390T, MR79	02.05.2013
701/2007	WSMS7480000416522	FRC	6579	07.09.2010
702/2007	WSMS7480000067207	FNA	6580	07.09.2010
703/2007	WSM00000005011616	FRC	6581	08.09.2010
704/2007	WSMS7480000444713	FRC	6582	08.09.2010
705/2007	VM3LVFS3F21R04792/02C0870.001	FRC	6583	08.09.2010
706/2007	WSMS7480000453207	FRC	6584	08.09.2010
707/2007	WSM00000005028670	FRC	07 1303, MR79	02.07.2013

708/2007	WSM0000005028654	FRC	3390T, MR79	01.06.2013
709/2007	WSM0000005028666	FRC	3390T, MR79	02.07.2013
710/2007	SUDNS1CTZ75013777/ 11009987	FRC	6585, 4838, MR79	31.07.2013
711/2007	WDB9702781K799579/ 19486	FNA	6586	15.09.2010
712/2007	WMAH20ZZ64W053399	FNA	6587	15.09.2010
713/2007	VM3LVFS3FY1R00845/ 99/C2595.001	FRC	6588	15.09.2010
716/2007	WSM0000005031591	FRC	07 1303, MR79	02.07.2013
717/2007	TRGSAF335WD126696	FRC	6591	18.09.2010
718/2007	WSM0000005028640	FRC	07 1303, MR79	03.05.2013
719/2007	VM3LVFS3EX1R08848/ 99/C0065-002	FRC	6592	14.09.2010
720/2007	WSMS7480000418625	FRC	6593	14.09.2010
721/2007	WSMS7480000403821	FRC	6594	14.09.2010
722/2007	ZCFA1ED0372513266/ 11008007	FRC/X	6595, 4560, M538	31.07.2013
723/2007	WK0S0002400078903/ 11009087	FRC	6596, 4838, M576	30.06.2013
724/2007	WSMS7480000402921	FRC	6597	19.09.2010
725/2007	VM4C382BNWA003748/ 38420	FRC	6598	07.01.2010
726/2007	WSMS7780000560022	FRC	6599	21.09.2010
727/2007	VK1S338RHPF301436/21 112	FRC	6600	22.09.2010
728/2007	VAVSAF335VH118332/ 97/C0438-002	FRC	6601	31.12.2009
730/2007	WK0S0002400078893/ 11009247	FRC	6603, 4838, M576	30.09.2013
731/2007	ZCFA1MJ0372517823/ 11012327	FRC/X	6604, 4560, M538	31.08.2013
732/2007	SUDNS1CTZ71012554/ 11001487	FRC	6605, 4838, M576	30.04.2013
733/2007	SUDNS1CTZ76014179/ 11010047	FRC	6606, 4838, M576	31.08.2013
734/2007	SUDNS1CTZ75013781/ 11010027	FRC	6607, 4838, M576	31.08.2013
735/2007	SUDNS1CTZ73013294/ 11007257	FRC	6608, 4838, M576	30.06.2013
736/2007	SUDNS1CTZ73013295/ 11007267	FRC	6609, 4838, M576	30.06.2013
737/2007	WK0S0002400078099	FRC	6610, 3365T, 3150K	30.06.2013
738/2007	ZA9RS139000H24126/ 155UL5979	FRC	6611	22.09.2010
739/2007	WSM0000005003323	FRC	6612	25.09.2010
740/2007	ZCFA1ED0372517093/ 11012347	FNA/X	6613, 4968, M538	31.07.2013
741/2007	ZCFA1MJ0372517182/ 11012317	FRC/X	6614, 4560, M538	31.07.2013
742/2007	ZCFA1ED03715835/ 11012337	FNA/X	6615, 4968, M M538	31.07.2013
743/2007	WKESDR27071312781/ 37.867	FRC	3383T, MR79	21.06.2013
744/2004	WSMS7480000433982	FRC	6616	25.09.2010
745/2004	WSMS7480000432517	FRC	6617	26.09.2010
747/2007	WSM0000005031616	FRC	07 1303, MR79	18.07.2013
748/2007	96-198-FB4-4649/ IP-1623	IR	6619	29.08.2013
749/2007	WK0S0002400078101	FRC	3365T, M576	30.06.2013
750/2007	WK0S0002400078102	FRC	3365T, M576	30.06.2013
751/2007	WK0S0002400070902	FRC	3288T, MR79	20.10.2012
752/2007	TYBFB83BB4DU06003/ 11012587	FNA/X	6620, 4561, 4934	31.08.2013
753/2007	WSMS7780000438663	FRC	6621	29.09.2010
754/2007	YV2J4CNA63B337914/ 422141	FRC	6622	29.09.2010
755/2007	WSM0000005034068	FRC	6623	25.09.2013
756/2007	WSM0000005034063	FRC	6624	12.09.2013
757/2007	WK0S0002400078100	FRC	3365T, 6625	12.06.2013
758/2007	VF644AHH000001248/ 11019955	FRC	6627, 4560, M541	25.03.2012
759/2007	VF644AGL000000840/ 11009757	FNA/X	6628, 4152, M538	31.07.2013
760/2007	WSMS7480000432795	FRC	6629	03.10.2010
761/2007	WSMS 7780000075582	FNA	6630	05.09.2013
762/2007	WKESDR27071303155	FRC	3383T, MR79	20.07.2013
763/2007	WSM0000005028757	FRC	07 1303, MR79	02.07.2013
764/2007	VS9SA3NS61A013386/ C13667	FNA	6631	04.10.2010
765/2007	WSM0000005005289	FRC	6662, 04 1181, MR79	15.03.2011
766/2007	WKESDR27071303152	FRC	3383T, MR79	20.07.2013
767/2007	WKESDR27071303153	FRC	3383T, MR79	20.07.2013
768/2007	WKESDR27071303154	FRC	3383T, MR79	20.07.2013
769/2007	WKESDR27071303159	FRC	3383T, MR79	20.07.2013
770/2007	WKESDR27071303161	FRC	3383T, MR79	20.07.2013
771/2007	WKESDR27071303168	FRC	3383T, MR79	14.08.2013
772/2007	WKESDR27071303167	FRC	3383T, MR79	14.08.2013
773/2007	WSMS7780000432457	FRC	6632	08.10.2010
774/2007	WKESDR27011269601/ 26149	FRC	6633	08.10.2010
775/2007	WSM0000005028768	FRC	3390T, MR79	01.06.2013

776/2007	WSMS7480000437721	FR C	6634	08.10.2010
777/2007	WMAH21ZZ55W056169	FRC	6635	09.10.2010
778/2007	WSMS7780000440824	FRC	6636	09.10.2010
779/2007	SUDNSICTZ74013583/11000657	FRC	4838 ,6637	05.07.2013
780/2007	WK0S0002400057581	FRC	3288T, M576	30.06.2012
781/2007	WK0S0002400057585	FRC	3288T, M576	30.06.2012
782/2007	WK0S0002400057586	FRC	3288T, M576	30.06.2012
783/2007	WK0S0002400057583	FRC	3288T, M576	30.06.2012
784/2007	WK0S0002400057587	FRC	3288T, M576	30.06.2012
785/2007	WK0S0002400057584	FRC	3288T, M576	30.06.2012
786/2007	WK0S0002400057590	FRC	3288T, M576	30.06.2012
787/2007	WK0S0002400057588	FRC	3288T, M576	30.06.2012
788/2007	WK0S0002400057589	FRC	3288T, M576	30.06.2012
789/2007	WKESDR27011158826/24840	FRC	6638	06.10.2010
790/2007	VM3LVFS3EX1R09232/99/C0922-004	FRC	6639	10.10.2010
791/2007	WSM00000005029836	FRC	07 1310, MR79	23.07.2013
792/2007	WSM7480000439822	FRC	6640	11.10.2010
794/2007	WKOSVKT24P213731	FNA	6642	12.10.2010
795/2007	SFRRCVSA3VV121101/PU027448	FRC	6643	31.12.2009
796/2007	VM3LVFS3EY1R10411/00C1552.001	FRC	6644	12.10.2010
798/2007	VM3LVFS3FW3A00130/98/C0450/07	FRC	6646	12.10.2010
799/2007	WKOSVKT24W0223938	FRC	6647	13.10.2010
800/2007	WSM00000005031481	FRC	3395T, MR79	06.08.2013
801/2007	SUDNSICTZ77014568/11014017	FRC	6648, 4838, MR81	31.10.2013
802/2007	SUDNSICBZ71011558/11019456	FRC	6649, 4838, MR79	31.10.2013
803/2007	WSMS7480000407566	FRC	6651	10.10.2010
804/2007	WKESDR27011262205/25010	FRC	6650	12.10.2010
807/2007	WSMS7480000430666	FRC	6654	20.10.2010
808/2007	WSMS7780000078570	FNA	6655	17.10.2010
810/2007	WKOSVKT24W0207830	FRC	6657	16.10.2010
811/2007	XL9DT3339X00170041 / L9388/990325	FRC	6658	16.10.2010
812/2007	VF656ANA000001042/11013677	FRC	6659, 5547, M593	31.10.2013
813/2007	VF656ANA000001045/11013667	FRC	6660, 5547, M593,	31.10.2013
814/2007	VF656ANA000001050/11013657	FRC	666, 15547, M593	31.10.2013
816/2007	VM3LVFS3F21R05140/02C1481.006	FRC	6663	24.10.2010
817/2007	WSM00000005031452	FRC	07 1310, MR79	13.08.2013
818/2007	VF1UDC1G638170669/11011517	FRC/X	6664, 5011, M529	30.09.2013
819/2007	VF1UDC1G638170670/11011527	FRC/X	6665, 5011, M529	30.09.2013
821/2007	WSM00000005023198	FRC	6666, 3379T, MR79	02.01.2013
822/2007	WSMS7480000085854	FNA	6667	29.10.2010
823/2007	WSM00000005011623	FRC	6668, 3238T, MR79	21.02.2012
824/2007	WSM00000005018307	FRC	6669, 3238T, MR79	19.09.2012
825/2007	WSMS7480000453209	FRC	6670	27.10.2010
826/2007	WSMS7480000453206	FRC	6671	24.10.2010
827/2007	WSM00000005011617	FRC	6672, 3319T, MR79	20.01.2012
828/2007	WSM00000005018308	FRC	6673, 3374T, MR79	01.09.2012
829/2007	WSMS7480000416498	FRC	6674	23.10.2010
830/2007	YS2R6X20001239674	FNA	6675	26.10.2010
831/2007	ZCFC4590005408388/11013437	FRC/X	6676, 5011, M621	31.08.2013
832/2007	SX90216ZG75SP2085/11006157	FRC	6677, 4560, M637	30.09.2013
833/2007	WSMS7480000437017	FRC	6678	02.11.2010
834/2007	VM4CD385G3A050461	FRC	6679	27.10.2010
835/2007	WSMS7480000443400	FRC	6680	31.10.2010
836/2007	W0909F339XPA10355/23082	FRC	6681	02.11.2010
837/2007	VM4CD381J4A012113/59104	FRC	6682	03.11.2010
838/2007	VK1S338DHRF001320/201012	FRC	6683	03.11.2010
839/2007	VST0031201M001085/CFF257	FRC	6684	03.11.2010
840/2007	WSM00000005017332	FRC	06 1281, MR79, 6685	28.06.2012
841/2007	WDB9061531N356642/11016667	FNA/X	6687, 4561, M485	31.10.2013
842/2007	WDB9061531N357623/11016657	FNA/X	6688, 4561, M485	31.10.2013
843/2007	WDB9061531N357438/11016637	FNA/X	6689, 4561, M485	31.10.2013
844/2007	WF0FXXTTFF7E48843/11013377	FNA/X	6690, 4561, M529	31.10.2013
845/2007	WDB9061531N357835/11016647	FNA/X	6691, 4561, M485	31.10.2013
846/2007	VF644AGL000000581/11009437	FNA	6692, 4152, M529	30.06.2013

847/2007	WF0FXXTTF7E43083/11013367	FNA/X	6693, 4561, M529	31.10.2013
848/2007	YS2R6X20002029935/11013457	FRC	6694, 4560, M421	30.09.2013
849/2007	SUDNS1CTZ74013581/11019977	FRC	6695, 4838, M576	31.10.2013
850/2007	SUDNS1CTZ75013586/11009277	FRC	6696, 4838, M576	31.07.2013
851/2007	SUDNS1CTZ75013902/11012197	FRC	6697, 4838, M576	31.10.2013
852/2007	VAVSAF3384H192732/11004034	FRC	4047, 4559.11	28.04.2010
853/2007	WSMS7480000439870	FRC	6698	02.11.2010
854/2007	WKOSVKT24X9838390	FRC	6699	06.11.2010
855/2007	VM3LVFS3EW1A07129/98/C0203-001	FRC	6700	23.03.2010
856/2007	WSM00000005031514	FRC	07 1310, MR79	17.07.2013
857/2007	WSM00000005031677	FRC	07 1303, MR79	03.09.2013
858/2007	WK0S0002400051793/65798	FRC	6701, BX5051, M576	31.12.2011
860/2007	WSMS7480000560051	FRC	6702	08.11.2010
861/2007	ZCFC35A8085691824/11013937	FRC/X	6703, 5547, M517	30.09.2013
862/2007	SUDNS1CTZ75013779/11004337	FRC	6704, 4838, M576	31.08.2013
863/2007	WKESDR27071303187	FRC	3383T, MR79	02.10.2013
864/2007	WKESDR27071303185	FRC	3383T, MR79	02.10.2013
865/2007	WKESDR27071303184	FRC	3383T, MR79	02.10.2013
866/2007	WKESDR27071303183	FRC	3383T, MR79	02.10.2013
867/2007	WKESDR27071303189	FRC	3383T, MR79	02.10.2013
868/2007	WKESDR27071303182	FRC	3383T, MR79	03.10.2013
869/2007	WKESDR27071303186	FRC	3383T, MR79	03.10.2013
870/2007	WKESDR27071303188	FRC	3383T, MR79	03.10.2013
871/2007	WSM00000005029837	FRC	07 1310, MR79	23.07.2013
872/2007	WSM00000005029838	FRC	07 1310, MR79	23.07.2013
873/2007	YE730PF381H201873/F10002P1377	FRC	6706	09.11.2010
874/2007	WDB9505061L255225/11011077	FNA/X	6707, 4152, M581	31.07.2013
875/2007	WDB9505061L256944/11011067	FNA/X	6708, 4152, M581	31.07.2013
876/2007	WDB9505061L256945/11011087	FNA/X	6709, 4152, M581	31.07.2013
877/2007	WDB9705061L252319/11011057	FNA/X	6710, 4152, M610	31.07.2013
878/2007	SUDNS1CTZ75013782/11010037	FRC	6711, 4838, M576	31.10.2013
879/2007	SUDNS1CTZ75013780/11013907	FRC	6712, 4838, M576	31.10.2013
880/2007	WSM00000005032171	FRC	3395T, MR79	29.08.2013
881/2007	WSM00000005032172	FRC	3395T, MR79	29.08.2013
882/2007	SUDNS1CTZ77014457/11016407	FRC	6713, 4838, M509	26.10.2013
883/2007	WSMS7480000406085	FRC	6714	26.10.2010
884/2007	VAVSAF3384H195750/21690	FRC	6715	12.11.2010
885/2007	VAVSAF3384H195748/21647	FRC	6716	12.11.2010
886/2007	VS9SA3NS62A013481/C14360	FRC	6717	12.11.2010
887/2007	VM3LVFS3EW1R07246/97/C2066-001	FRC	6718	31.01.2010
888/2007	WSMS7480000437809	FRC	6719	13.11.2010
889/2007	WSM00000005029853	FRC	07 1310, MR79	16.08.2013
890/2007	VAVSAF3387H262890/26.564	FRC	2003/1692, M576	31.07.2013
891/2007	VAVSAF3387Z251454/26.146	FRC	2003/1692, M576	30.04.2013
892/2007	VAVSAF3387H237434/25.668	FRC	2003/1692, M576	21.02.2013
893/2007	VAVSAF3387H250286/26.327	FRC	2003/1692, M576	31.05.2013
894/2007	WSM00000005032180	FRC	07 1310, MR79	01.10.2013
895/2007	WSM00000005032179	FRC	07 1310, MR79	01.10.2013
896/2007	VM3LVFS3EV1A06383/97/C1660-003	FRC	6720	14.11.2009
897/2007	VM3LVFS3EX1R09913/99/C2295-001	FRC	6721	13.11.2010
898/2007	WSMS7480000411019	FRC	6722	31.08.2010
899/2007	WKESDR27041222301 / 31204	FRC	6723	15.11.2010
900/2007	WMAL20ZZZ2Y094517	FNA/X	6724	19.11.2010
902/2007	WSMS7480000096034	FRC	6725	31.03.2010
903/2007	WSM00000005028698	FRC	3390T, MR79	03.05.2013
904/2007	WSM00000005028820	FRC	3390T, MR79	01.06.2013
905/2007	WSM00000005023208	FRC	3379T, MR79	01.02.2013
906/2007	WSM00000005028754	FRC	07 1303, MR79	02.07.2013
907/2007	WSM00000005028606	FRC	07 1303, MR79	21.05.2013
908/2007	WSM00000005033968	FRC	3395T, M576	03.09.2013
909/2007	WSM00000005033962	FRC	3395T, M576	03.09.2013
910/2007	WSM00000005033967	FRC	3395T, M576	03.09.2013
911/2007	WSM00000005033963	FRC	3395T, M576	03.09.2013
912/2007	ZCFA1MJ0382522506 / 11016627	FNA/X	6726, 4152, M589	30.11.2013

913/2007	ZCFA1ED0382523964 / 11014457	FRC/X	6727, 4560, M572	30.11.2013
914/2007	ZCFA1ED0382523960 / 11014427	FRC/X	6728, 4560, M572	30.11.2013
915/2007	ZCFA1ED0382523961 / 11014477	FRC/X	6729, 4560, M572	30.11.2013
916/2007	ZCFA1ED0382523963 / 11014447	FRC/X	6730, 4560, M572	30.11.2013
917/2007	ZCFA1ED0382523965 / 11014487	FRC/X	6731, 4560, M572	30.11.2013
918/2007	ZCFA1ED0382523962 / 11014437	FRC/X	6732, 4560, M572	30.11.2013
919/2007	ZCFA1ED0382523959 / 11014467	FRC/X	6733, 4560, M572	30.11.2013
920/2007	WDB9061531N357834 / 11016677	FNA/X	6734, 4561, M485	31.10.2013
921/2007	WDB9061531N359674 / 11016717	FNA/X	6735, 4561, M485	31.10.2013
922/2007	WDB9061531N359938 / 11016687	FNA/X	6736, 4561, M485	31.10.2013
923/2007	WDB9061531N360331 / 11016697	FNA/X	6737, 4561, M485	31.10.2013
924/2007	WDB9061531N360513 / 11016707	FNA/X	6738, 4561, M485	31.10.2013
925/2007	WDB9061531N360906 / 11016727	FNA/X	6739, 4561, M485	31.10.2013
926/2007	ZCFC50A2085702200 / 11015877	FNA/X	6740, 4561, M486	31.10.2013
927/2007	IP-1683/96-108-FB4-6935	IR	6741	21.11.2013
928/2007	WKESDR27000150937	FRC	6742	23.11.2010
929/2007	WSMS7480000452768	FRC	6743	23.11.2010
930/2007	21331/22662	FRC	6744	23.11.2010
931/2007	VM3LVFS3F11R02316/01C3408.001	FRC	6745	23.11.2010
933/2007	WSMS7480000433574	FRC	6747	23.11.2010
934/2007	WSMS7480000098920	FRC	6749	17.02.2010
935/2007	WSMS7480000440493	FRC	6750	27.11.2010
936/2007	WSMS7480000430085	FRC	6751	23.11.2010
937/2007	WSMS7480000414171	FRC	6752	23.11.2010
938/2007	WSMS7780000402059	FRC	6753	23.11.2010
939/2007	WSMS7480000402313	FRC	6754	13.05.2010
940/2007	43359	FRC	6755	28.11.2010
941/2007	WKOS0002400095786 / 11011697	FRC	6757, 4838, M576	30.11.2013
942/2007	WKOS0002400095787 / 11011677	FRC	6758, 4838, M576	30.11.2013
943/2007	WKOS0002400095788 / 11011687	FRC	6759, 4838, M576	30.11.2013
944/2007	WKOS0002400095789 / 11011707	FRC	6760, 4838, M576	30.11.2013
945/2007	SUDNS1CTZ73013226 / 11007217	FRC	6761, 4838, MR79	31.10.2013
946/2007	WSM00000005028798	FRC	07 1303, MR79	29.05.2013
947/2007	WSM00000005028797	FRC	07 1303, MR79	14.05.2013
948/2007	WSM00000005028775	FRC	07 1303, MR79	29.05.2013
949/2007	WSM00000005028800	FRC	07 1303, MR79	29.05.2013
950/2007	WSM00000005028799	FRC	07 1303, MR79	29.05.2013
951/2007	WSMS7480000430575	FRC	6762	01.12.2010
952/2007	WSM00000005033966	FRC	6763, 3319T, MR79	13.09.2013
953/2007	WSM00000005028774	FRC	07 1303, MR79	29.05.2013
954/2007	25221	FNA	6770	04.12.2010
955/2007	ZCFA1ED0382524061 / 11014557	FRC	6771, 4560, M572	30.11.2013
956/2007	ZCFA1ED0382524059 / 11014577	FRC	6772, 4560, M572	30.11.2013
957/2007	ZCFA1ED0382524058 / 11014507	FRC	6773, 4560, M572	30.11.2013
958/2007	ZCFA1ED0382524172 / 11014527	FRC	6774, 4560, M572	30.11.2013
959/2007	ZCFA1ED0382524169 / 11014547	FRC	6775, 4560, M572	30.11.2013
960/2007	ZCFA1ED0382524173 / 11014607	FRC	6776, 4560, M572	30.11.2013
961/2007	ZCFA1ED0382524056 / 11014587	FRC	6777, 4560, M572	30.11.2013
962/2007	ZCFA1ED0382524261 / 11014597	FRC	6778, 4560, M572	30.11.2013
963/2007	ZCFA1ED0382524060 / 11014497	FRC	6779, 4560, M572	30.11.2013
964/2007	ZCFA1ED0382524167 / 11014537	FRC	6780, 4560, M572	30.11.2013
965/2007	ZCFA1ED0382524057 / 11014567	FRC	6781, 4560, M572	30.11.2013
966/2007	ZCFA1ED0382524062 / 11014517	FRC	6782, 4560, M572	30.11.2013
967/2007	WSM00000005010048	FRC	6783, 05 1251, MR81	14.12.2011
968/2007	WSMS7480000456290	FRC	3329T, MR79	01.10.2010
969/2007	YS2P6X20001274630	FRC	6784	03.12.2010
970/2007	SV91409PB01CM1011	FRC	6785	03.12.2010
971/2007	YS2P6X20001274627	FRC	6786	04.12.2010
972/2007	SV91409PB01CM1010	FRC	6787	04.12.2010
973/2007	WSM00000005028641	FRC	3390T, MR79	01.06.2013
974/2007	WSM00000005017869	FRC	6788, 06 1281, M576	24.07.2012
975/2007	ZFA25000001304342 / 089/07	FNA/X	6789, 4760, M621	30.11.2013
976/2007	ZFA25000001304407 / 088/07	FNA/X	6790, 4760, M621	30.11.2013
978/2007	WSM00000005031642	FRC	07 1310, MR79	24.08.2013

979/2007	VV5STNSFRVV977526 / 12987	FRC	6793	31.12.2009
980/2007	WSMS7480000440084	FRC	6794	10.12.2010
981/2007	WSMS7480000406084	FRC	6795	15.09.2010
982/2007	VF656ANA000004111/11012987	FNA/X	6796, 4561, M486	30.11.2013
983/2007	WV1ZZZ2FZ87003745/11015177	FRC/X	6797, 5011, M486	31.10.2013
984/2007	WK0S0002400095791/11012497	FRC	6798, 4838, M576	30.11.2013
985/2007	WK0S0002400095790/11012487	FRC	6799, 4838, M576	30.11.2013
986/2007	VM3LVFS3F71R16656/07C1002/037	FRC	6800, BX 5193	31.10.2013
987/2007	WSM00000005028773	FRC	07 1303, MR79	29.05.2013
988/2007	WSMS7480000456304	FRC	04 1183, MR79	13.10.2010
989/2007	WSM00000005030509	FRC	07 1303, MR79	02.07.2013
990/2007	VS9SA3NS6YA013017/ C13213	FRC	6801	06.12.2010
991/2007	VM3LVFS3F51A10605/05C0021/001	FRC	6802	07.12.2010
992/2007	WSMS7780000447135	FRC	6803	15.12.2010
993/2007	SUDNS1CBZ71011559/11019466	FRC	6804, 4838, MR79	14.12.2013
994/2007	WK0S0002400084364	FRC	6805, 3288T, M576	23.11.2013
995/2007	WSMS7480000071506	FNA	6806	14.12.2010
996/2007	WSM00000005020898	FRC	6807, 3319T, MR79	13.11.2012
997/2007	XL9DT3339X0017042	FNA	6808	14.12.2010
998/2007	WSM00000005032255	FRC	07 1328, MR79	05.11.2013
999/2007	WSM00000005032517	FRC	07 1310, MR79	01.10.2013
1000/2007	WSM00000005032417	FRC	3395T, MR79	28.09.2013
1001/2007	WK0SVKT2430517718	FRC	6809	19.12.2010
1002/2007	SUZNOJ00RWZ000209 / 802003	FRC	6810	17.03.2010
1003/2007	WKESDR27011158806/25155	FRC	6811	19.12.2010
1004/2007	WSM00000005032444	FRC	3395T, MR79	26.10.2013
1005/2007	WSM00000005020922	FRC	6812, 06 1286, MR79	20.10.2012
1006/2007	WSM00000005001379	FRC	6813	22.12.2010
1007/2007	WSM00000005032218	FRC	3395T, M576	15.10.2013
1008/2007	XMH0NCRP0XCF50788	FRC	6814	22.11.2010
1009/2007	WSM00000005023042	FRC	6815, 06 1286, MR79	03.01.2013
1010/2007	VLUR4X20009057112 / 47317	FRC	6816	24.12.2010
1011/2007	WSM00000005020918	FRC	6817, 06 1286, MR79	20.10.2012
1012/2007	WSM00000005031485	FRC	3395T, MR79	03.09.2013
1013/2007	WSM00000005031484	FRC	3395T, MR79	03.09.2013
1014/2007	WSMS7480000416516	FRC	6818	27.12.2010
1015/2007	WSMS7480000416496	FRC	6819	27.12.2010
1016/2007	WSMS7480000445562	FRC	6820	27.12.2010
1017/2007	WSMS7480000447868	FRC	6821	27.12.2010
1018/2007	WSMS7780000441309	FRC	6822	27.12.2010
1019/2007	WSMS7480000447601	FRC	6823	27.12.2010
1020/2007	WKESDR27011383226 / 27366	FRC	6824	27.12.2010
1021/2007	WSM00000005006942	FRC	6825	27.12.2010
1022/2007	WSMS7480000459764	FRC	6826	27.12.2010
1023/2007	WSMS7480000095704	FRC	6827	31.12.2009
1024/2007	WSMS7480000442351	FRC	6828	27.12.2010
1025/2007	YE730PF385H203931/ F5001.452142	FRC	6829, T4097, MR79	17.02.2012
1026/2007	WSMS7480000416501	FRC	6830	28.12.2010
1027/2007	WSMS7480000438309	FRC	6831	28.12.2010
1028/2007	WK0SVKT2420299803	FRC	6832	28.12.2010
1029/2007	WSMS7480000441829	FRC	6833	28.12.2010
1030/2007	WSMS7480000441837	FRC	6834	28.12.2010
1031/2007	WSMS7780000436107	FRC	6835	31.12.2010
1032/2007	WKOSVKT2420299986	FRC	6836	31.12.2010
1034/2007	WSMS7480000434327	FRC	6838	29.12.2010
1035/2007	WSMS7480000434329	FRC	6839	29.12.2010
1036/2007	WSMS7480000090609	FRC	6840	17.10.2009
1037/2007	WSM00000005027226	FRC	6841, 07 1295, MR79	02.04.2013
1038/2007	VM3LVFS3EV1R06592/97/C1835.001	FRC	6842	31.12.2009
1039/2007	VM4C382DNVA003311 / 01C1218.001	FRC	6843	29.12.2010
1040/2007	VK1ST39MHRA300602 / 203416	FRC	6844	29.12.2010
1041/2007	WSMS7480000401013	FRC	6845	23.04.2010
1042/2007	VM3LVFS3F11A03926 / 01C2271.002	FRC	6846	29.12.2010
1043/2007	VM3LVFS3F11A03929 / 01C2369.002	FRC	6847	29.12.2010

1044/2007	VM4CD382G2A021129 / 57258	FRC	6848	29.12.2010
1045/2007	WSMS7480000433802	FRC	6849	29.12.2010
1046/2007	VM3LVFS3F11A03925	FRC	6850	29.12.2010
1047/2007	WSMS7480000437890	FRC	6851	29.12.2010
1048/2007	VM4C381BNSA001638 / 32090	FNA	6852	29.12.2010
1049/2007	SFRRCVSA3WR210001	FRC	6853	29.12.2010
1050/2007	WSMS7480000437898	FRC	6854	29.12.2010
1051/2007	VM3LVFS3F11A03928 / 01.C2369.001	FRC	6855	29.12.2010
1052/2007	VM4CD382G2A021133 / 54081	FRC	6856	29.12.2010
1053/2007	WSMS7480000411014	FRC	6857	29.12.2010
1054/2007	WK0S0002400084341	FRC	3365T, MR79	21.11.2013
1055/2007	WSMS7780000441346	FRC	6927	29.12.2010
1056/2007	WSM00000005027267	FRC	7065, 06 1286, M576	03.05.2013
1057/2007	WSM00000005023051	FRC	7066, 06 1286, M576	01.03.2013
1058/2007	WSM00000005027268	FRC	7067, 06 1286, M576	03.05.2013
1059/2007	WSM00000005023052	FRC	7068, 06 1286, M576	03.05.2013
1060/2007	WSM00000005027276	FRC	7069, 06 1286, M576	07.05.2013
1061/2007	WSM00000005027275	FRC	7070, 06 1286, M576	07.05.2013