

Spis świadectw wydanych przez COCH w 2008 r.

Numer świadectwa	Numer identyfikacyjny (punkt 3 świadectwa)	Uznaje się jako (punkt 6 świadectwa)	Nr protokołu badań (punkt 7.2.3 świadectwa)	Data ważności świadectwa (pkt.8)
1	2	3	4	5
001/2008	WSMS7480000438817	FRC	6095	2010.01.19
002/2008	WSMS7480000437806	FRC	6858	2011.01.04
003/2008	WK0S0002400078098	FRC	6859, 3365T	2013.06.26
004/2008	WK0S0002400078097	FRC	6860, 3365T	2013.06.26
005/2008	VVCSORXBCS4101133 / 18585	FRC	6861	2011.01.05
006/2008	VM4C383BRXA004991 / 42301	FRC	6862	2011.01.05
007/2008	VM3LVFS3EX1R09700/99 / C1637-002	FRC	6863	2011.01.05
008/2008	VM3LVFS3EW1R08323 / 98C1493.001	FRC	6864	2010.12.31
009/2008	WSMS7480000433657	FRC	6865	2011.01.02
010/2008	WSMS7780000441312	FRC	6866	2011.01.02
011/2008	WSMS7480000431459	FRC	6867	2011.01.02
012/2008	WSMS7480000440711	FRC	6868	2011.01.02
013/2008	WSMS7480000430615	FRB	6869	2011.01.02
014/2008	WSMS7480000411865	FRC	6870	2010.12.31
015/2008	WSM00000005029846	FRC	07 1310, MR79	2013.08.13
016/2008	VGUST331234022202 / 03C0170.002	FRC	6871	2011.01.07
017/2008	WSMS7780000418708	FRC	6872	2011.01.07
018/2008	VM4S3391BWA039744 / 39744	FRC	6873	2010.12.31
019/2008	ZCFC3584085706811 / 11015337	FRC/X	5011, 6874, M517	2013.11.30
020/2008	ZCFC3584085706810 / 11015347	FRC/X	5011, 6875, M517	2013.11.30
021/2008	ZCFC3584085706809 / 11015357	FRC/X	5011, 6876, M517	2013.11.30
022/2008	ZCFC3584085706808 / 11015367	FRC/X	5011, 6877, M517	2013.11.30
023/2008	ZCFC3584085706807 / 11015317	FRC/X	5011, 6878, M517	2013.11.30
024/2008	ZCFC3584085706812 / 11015327	FRC/X	5011, 6879, M517	2013.11.30
025/2008	ZCFA1ED0382524171 / 11014617	FRC	4560, 6880, M572	2013.11.30
026/2008	ZCFA1ED0382524170 / 11014647	FRC	4560, 6881, M572	2013.11.30
027/2008	ZCFA1ED0382524168 / 11014637	FRC	4560, 6882, M572	2013.11.30
028/2008	ZCFA1ED0382524166 / 11014627	FRC	4560, 6883, M572	2013.11.30
029/2008	ZCFA1ED0382524055 / 11014657	FRC	4560, 6884, M572	2013.11.30
030/2008	ZCFA50A2085707536 / 11012047	FNA/X	4561, 6885, M607	2013.11.30
031/2008	ZCFA50A2085707534 / 11012037	FNA/X	4561, 6886, M607	2013.11.30
032/2008	ZCFA50A2085707533 / 11012027	FNA/X	4561, 6887, M607	2013.11.30
033/2008	ZCFA50A2085707532 / 11012107	FNA/X	4561, 6888, M607	2013.11.30
034/2008	ZCFA50A2085707531 / 11012097	FNA/X	4561, 6889, M607	2013.11.30
035/2008	ZCFA50A2085707530 / 11012087	FNA/X	4561, 6890, M607	2013.11.30
036/2008	ZCFA50A2085691775 / 11012117	FNA/X	4561, 6891, M607	2013.11.30
037/2008	ZCFA50A2085691776 / 11012057	FNA/X	4561, 6892, M607	2013.11.30
038/2008	ZCFA50A2085692065 / 11012067	FNA/X	4561, 6893, M607	2013.11.30
039/2008	XLRAS85MC7E775569 / 11015217	FRC	4560, 6884, MR85	2013.09.30
040/2008	ZCFC3583085704310 / 11016597	FNA/X	4561, 6895, M486	2013.11.30
041/2008	WSM00000005034016	FRC	6896, 3319T, 2761K	2013.11.10
042/2008	WSM00000005024145	FRC	6897, 3319T, 3074K	2013.11.09
043/2008	WKESDR27061262002 / 35289	FRC	3344T, MR79, 6898	2012.03.02
044/2008	WKESDR27011157365	FRC	6899	2011.01.07
045/2008	WSM00000005014871	FRC	6900, 3319T, MR79	2012.06.08
046/2008	WSMS7780000438672	FRC	6901	2011.01.09
047/2008	WSM00000005032471	FRC	3404T, MR79	2013.12.03
048/2008	WSM00000005032502	FRC	3395T, MR79	2013.09.24
049/2008	WSM00000005025343	FRC	6902, 07 1303, MR79	2013.04.17
050/2008	WSM00000005025344	FRC	6903, 07 1303, MR79	2013.04.17
051/2008	SUDNSICTZ75013898 / 11010007	FRC	6904, 4838, M576	2014.01.09
052/2008	ZCFC50A2085688763 / 11010467	FNA/X	6905, 4561, M486	2013.08.31
053/2008	ZCFC50A2085688764 / 11010457	FNA/X	6906, 4561, M486	2013.08.31
055/2008	WSM00000005028755	FRC	6907, 07 1303, MR79	2013.07.02
056/2008	WSM00000005019356	FRC	3374T, MR79	2012.09
057/2008	WSM00000005032434	FRC	07 1310, MR79	2013.11.02

058/2008	WSM0000005032435	FRC	07 1310, MR79	2013.11.02
059/2008	WSM0000005033948	FRC	3348T, M576	2013.09.03
061/2008	WSMS748000450202	FRC	6909	2011.01.17
062/2008	WSMS778000445126	FRC	6910	2011.01.18
063/2008	WSM0000005032656	FRC	07 1310, MR79	2013.10.01
064/2008	WKESDR27011385993 / 27639	FRC	6911	2011.01.18
065/2008	VM3LVFS3F71R16630 / 07C1002/011	FRC	6912, BX5193, M509	25.07.2013
066/2008	VM3LVFS3F21A04889 / 02C1093.001	FRC	6913	2011.01.18
067/2008	WSM0000005031483	FRC	3395T, MR79	2013.09.03
068/2008	UH9SL249821HF1092 / 21428	FRC	6916	2010.09.11
069/2008	JAAN1R70LX7100014	FNA/X	4760.1	2010.07.15
070/2008	SUDNS1CTZ77014661 / 11020227	FRC	6918, 4838, M576	2013.12.31
071/2008	SUDNS1CTZ77014662 / 11020237	FRC	6919, 4838, M576	2013.12.31
072/2008	SUDNS1CTZ77014663 / 11020247	FRC	6920, 4838, M576	2013.12.31
074/2008	WSMS748000441236	FRC	6917	2011.01.23
075/2008	SMSS7780000702765	FRC	6921	2011.01.23
077/2008	WSMS748000072558	FNA	6924	2011.01.24
078/2008	YE7SD3AAFN1200161 / F1001.631339	FRC	6922	2011.01.23
079/2008	VM4CD383JYA030006 / 45753	FRC	6923	2011.01.23
080/2008	VM3LVFS3F71R16657 / 07C1002/038	FRC	6925, BX5193, M433	2013.12.08
081/2008	WSMS778000096559	FRC	6926	2010.02.27
082/2008	WSM0000005020745	FRC	6928, 06 1286, MR81	2012.10.23
083/2008	WSMS748000439401	FRC	6929	2011.01.25
084/2008	SUDNS1CTZ77014664 / 11018727	FRC	6930, 4838, M576	2013.12.31
085/2008	WSMS748000406100	FRC	6931	2010.02.12
086/2008	W09270324W0G22006 / 812113	FRC	6932	2010.04.30
087/2008	VM3LVFS3F11R02824 / 01C447.011	FRC	6933	2011.01.26
088/2008	VM4C381BRWA004493 / 41240	FRC	6934	2010.09.30
090/2008	WSM0000005000703	FRC	6936	2011.01.26
091/2008	VM3LVFS3E11R10575 / 01C0302.003	FRC	6937	2011.01.30
092/2008	WSMS778000444863	FRC	6938	2011.01.30
093/2008	VFKT34CGNN1RE2998	FNA	6939	2011.01.26
094/2008	WK0S0002400084335	FRC	6940	2013.10.09
096/2008	WSMS748000436637	FRC	6942	2011.02.02
097/2008	WSMS748000417674	FRC	6943	2011.02.02
098/2008	WSMS748000438684	FRC	6944	2011.02.02
101/2008	WSMS748000434482	FRC	6946	2011.02.05
102/2008	SYG00000070GS0028	FNA	6947, 4968, M515	2013.12.31
103/2008	WSMS778000433099	FRC	6948	2011.02.02
104/2008	WSM0000005034621	FRC	6949, 07 1310, M425	2013.10.04
105/2008	WSM0000005041150	FRC	6950, 3319T, MR79	2014.01.29
106/2008	WSM0000005032445	FRC	3395T, MR79	2013.10.26
107/2008	VFLCS3MDXX0000122 / F10002P1265	FRC	6951	2011.02.07
108/2008	WSMS748000451231	FRC	6952	2011.02.11
109/2008	SUDNS1CTZ81016286 / 11020257	FRC	6953, 4838, MR79	2014.01.31
110/2008	WSMS748000436330	FRC	6956	2011.02.12
111/2008	VM3LVFS3EW1R08195 / 98/C1334-001	FRC	6188	2010.02.26
112/2008	WSMS748000442022	FRC	6957	2011.02.12
113/2008	WSMS748000443458	FRC	6958	2011.02.12
114/2008	WSMS748000442021	FRC	6959	2011.02.12
115/2008	WSM0000005038171	FRC	07 1328, MR79	2013.12.07
116/2008	WSM0000005032167	FRC	07 1310, MR79	2013.08.29
117/2008	WSM0000005032166	FRC	07 1310, MR79	2013.08.22
118/2008	WSM0000005032392	FRC	3395T, MR79	2013.09.07
119/2008	WSM0000005032391	FRC	3395T, MR79	2013.09.07
120/2008	WSM0000005032231	FRC	07 1310, MR79	2013.11.02
121/2008	WSM0000005032232	FRC	07 1310, MR79	2013.11.02
122/2008	WSM0000005031447	FRC	6960, 07 1303, MR79	2013.07.04
123/2008	WSM0000005028663	FRC	6961, 3390T, MR79	2013.07.02
124/2008	WSM0000005031448	FRC	6962, 07 1303, MR79	2013.07.05
125/2008	WSM0000005031446	FRC	6963, 07 1303, MR79	2013.07.04

126/2008	<b>WSM0000005034650</b>	<b>FRC</b>	07 1310, M576	2013.10.01
127/2008	VF656ANA000001618 / <b>11013517</b>	<b>FNA/X</b>	6964, 4968, M611	2013.09.30
128/2008	VF656ANA000001051 / <b>11013547</b>	<b>FNA/X</b>	6965, 4968, M611	2013.09.30
129/2008	VF656ANA000001049 / <b>11013497</b>	<b>FNA/X</b>	6966, 4968, M611	2013.09.30
130/2008	VF656ANA000001043 / <b>11013507</b>	<b>FNA/X</b>	6967, 4968, M611	2013.09.30
131/2008	VF656ANA000001048 / <b>11013527</b>	<b>FNA/X</b>	6968, 4968, M611	2013.09.30
132/2008	VF656ANA000001046 / <b>11013537</b>	<b>FNA/X</b>	6969, 4968, M611	2013.09.30
133/2008	VF624CPA000000878 / <b>11018437</b>	<b>FRC</b>	6970, 4560, MR89	2013.11.30
134/2008	SUZCFJ04R8Z000056 / <b>11018447</b>	<b>FRC</b>	6971, 4560, MR89	2014.01.31
135/2008	<b>VM3LVFS3ES1A03994</b>	<b>FNA</b>	6972	2011.02.14
137/2008	<b>WSMS7480000074148</b>	<b>FNA</b>	6973	2011.02.19
138/2008	<b>WSM0000005024182</b>	<b>FRC</b>	3404T, M576	2013.12.03
139/2008	<b>WSM0000005024183</b>	<b>FRC</b>	3404T, M576	2013.12.03
140/2008	<b>WSM0000005024180</b>	<b>FRC</b>	3404T, M576	2013.12.03
141/2008	<b>WSM0000005024181</b>	<b>FRC</b>	3404T, M576	2013.12.03
143/2008	SUDNS1CTZ72012752 / <b>11002757</b>	<b>FRC</b>	6450, 4838, M576	2013.04.30
144/2008	<b>WSM0000005032184</b>	<b>FRC</b>	07 1310, MR79	2013.10.01
145/2008	<b>WKESDR27011157467</b>	<b>FRC</b>	6975	2011.02.20
146/2008	<b>WKESDF27000Y43052</b>	<b>FRC</b>	6977	2011.02.21
147/2008	<b>WSMS7780000072668</b>	<b>FNA</b>	6985	2011.02.21
148/2008	YF104ST3SYF019480 / <b>23253</b>	<b>FRC</b>	6986	2011.02.22
149/2008	<b>WK0SVKT24W0292760</b>	<b>FRC</b>	6987	2010.02.06
150/2008	<b>WSMS7480000446222</b>	<b>FRC</b>	6991	2011.02.26
151/2008	<b>WSMS7480000446221</b>	<b>FRC</b>	6990	2011.02.26
152/2008	W091643381HS09242 / <b>01C1712.001</b>	<b>FRC</b>	6989	2011.02.26
153/2008	<b>11685</b>	<b>FNA</b>	6993	2010.08.26
154/2008	<b>WSMS7480000076013</b>	<b>FNA</b>	6992	2011.02.26
155/2008	<b>VSRSF3D00ML053380</b>	<b>FRC</b>	6994	2011.02.26
156/2008	<b>WSM0000005050363</b>	<b>FRC</b>	3404T, MR79	2014.01.11
157/2008	<b>YV2A4B2CBVB175349</b>	<b>FRC</b>	6984	2011.02.23
158/2008	<b>YV2A4B1A0TB156002</b>	<b>FNA</b>	6983	2011.02.23
159/2008	<b>WSMS7480000406229</b>	<b>FRC</b>	6982	2011.02.23
160/2008	WKESDR27011380788 / <b>27315</b>	<b>FRC</b>	6981	2011.02.23
161/2008	<b>VFKXXT34CG1NL1511</b>	<b>FNA</b>	6980	2011.02.23
162/2008	<b>WSMS7480000435207</b>	<b>FRC</b>	6979	2011.02.23
163/2008	<b>WSMS7480000445389</b>	<b>FRC</b>	6978	2011.02.23
164/2008	WDB6740101K088660 / <b>94/C1142-003</b>	<b>RRA</b>	6995	2014.02.28
165/2008	WMAM03206Y010980 / <b>77P</b>	<b>FNA</b>	6996	2014.02.26
166/2008	WDB9044121P986982 / <b>2361</b>	<b>FNA</b>	6977	2014.04.03
167/2008	<b>WSMS7480000432676</b>	<b>FRC</b>	6998	2011.02.29
168/2008	<b>WDB9500351K357245</b>	<b>FNA</b>	6999	2011.03.03
169/2008	<b>WSM0000005041162</b>	<b>FRC</b>	07 1328, MR79	2014.01.10
170/2008	<b>WSMS7480000444753</b>	<b>FRC</b>	7000	2011.02.28
171/2008	<b>WSMS7480000443319</b>	<b>FRC</b>	7001	2011.02.28
172/2008	<b>WSMS7480000446534</b>	<b>FRC</b>	7002	2011.02.28
173/2008	ZCFC65D0085703604 / <b>11001036</b>	<b>FRC/X</b>	7003, 5547, M611	2013.11.30
174/2008	SUDNS1CTZ75013899 / <b>11010017</b>	<b>FRC</b>	7004, 4838, M576	2013.12.31
175/2008	SUDNS1CTZ77014665 / <b>11018737</b>	<b>FRC</b>	7005, 4838, M576	2013.12.31
176/2008	<b>XMH0NCRPOWCF32043</b>	<b>FRC</b>	7006	2010.08.26
177/2008	VM3LVFS3FW3A00177 / <b>98/C0484-004</b>	<b>FRC</b>	7007	2010.04.30
178/2008	<b>WSMS7480000441995</b>	<b>FRC</b>	7008	2011.02.28
179/2008	<b>WSM0000005028662</b>	<b>FRC</b>	7009, 3390T, MR79	2013.07.02
180/2008	<b>WSM0000005028646</b>	<b>FRC</b>	7010, 3390T, MR79	2013.06.01
181/2008	<b>WSM0000005028647</b>	<b>FRC</b>	7011, 3390T, MR79	2013.06.01
182/2008	<b>WSM0000005025364</b>	<b>FRC</b>	7012, 07 1310, MR79	2013.07.10
183/2008	<b>IP-1713 / 76-88-FB3-3938</b>	<b>IR</b>	7013	2014.02.20
184/2008	<b>WSM0000005028796</b>	<b>FRC</b>	7014, 07 1303, MR79	2013.05.14
185/2008	VM3LVFS3ET1R04778 / <b>96/C0925-001</b>	<b>FNA</b>	7015	2011.02.29
186/2008	<b>WSMS7480000439397</b>	<b>FRC</b>	7016	2011.03.05
187/2008	<b>WSM0000005002448</b>	<b>FRC</b>	04 1183 ,MR79	2010.10
188/2008	<b>WSM0000005002449</b>	<b>FRC</b>	04 1183, MR79	2010.10

189/2008	VM3LVFS3EX1R08419 / 98 C2191.001	FRC	7017	2011.03.06
190/2008	WKESDR27051234740 / 32530	FRC	7018	2011.03.06
191/2008	VM3LVFS3F21R06224 / 02C2150.001	FRC	7019	2011.03.06
193/2008	WK0S0002400084340	FRC	3365T, M576	2013.12.31
194/2008	WDB9702671K446848 / 51672	FRC	7024	2011.03.06
195/2008	SUDNS1CTZ71012101 / 11019517	FRC	7025, 4838, M576	2013.02.20
196/2008	SUDNS1CTZ71012100 / 11019506	FRC	7026, 4838, M576	2013.02.20
197/2008	VM4CD381YA000944 / 45736	FRC	7027	2011.03.06
198/2008	YE7SD3AASN1201848	FRC	7028	2011.03.06
199/2008	WSMS7480000431289	FRC	7029	2011.03.06
200/2008	VM4C382DNTA002129 / 33686	FNA	7030	2011.03.08
202/2008	VF9SD334095403189 / 95008/01	FNA	7022	2011.03.08
203/2008	WSMS7480000443050	FRC	7023	2011.03.08
204/2008	VM3LVFS3EX4R09737 / 99/C1782.001	FRC	7020	2011.03.07
205/2008	VM3LVFS3EY1R10397 / 00C1531.001	FRC	7031	2011.03.07
206/2008	WK0SVKT2420297613 / 29-7613	FRC	7032	2011.03.07
207/2008	WMAT372390M220575 / 05193	FRC	7033	2011.03.10
208/2008	WSM00000005032256	FRC	07 1328, MR 79	2013.11.05
209/2008	WSMS7480000401032	FRC	7034	2010.06.18
210/2008	WSMS7480000094180	FRC	7035	2010.12.31
211/2008	WKESDR27011266940 / 25896	FRC	7036	2011.03.11
212/2008	WMAL720026Y031064	FNA	7037	2011.03.12
213/2008	VF640AEA000001844 / 40986	FRC	7042	2010.10.15
214/2008	WK0SVKT24W9823975	FRC	7043	2010.12.15
215/2008	WSM0000005028691	FRC	7044, 3390T, MR79	2013.05.02
216/2008	WSM0000005051529	FRC	3404T, MR79	2014.01.25
219/2008	WDB9502031K407055 / 2000650	FRC	03 1170, 6097	2011.10
220/2008	VGUST338A34000399	FRC	7048	2011.03.15
221/2008	VM3LVFS3FY3R01556 / 00C1455.002	FRC	7049	2011.03.15
222/2008	VK1S338DHPF001532 / 20941	FRC	7050	2011.03.15
223/2008	WSMA7420000073655	FNA	7051	2011.03.15
225/2008	WSMS6080000516887	FRC	7053	2011.03.10
226/2008	WSMS7780000441244	FRC	7054	2011.03.15
227/2008	WSM0000005032550	FRC	3319T, MR79	2013.12.06
228/2008	WSM0000005029597	FRC	07 1303, MR79	2013.07.02
229/2008	WSM0000005029629	FRC	7055, 07 1328, M425	2013.12.31
230/2008	VVCS0RXBAS4W00167 / 14038	FRC	7056	2010.07.20
231/2008	WSMS7480000441871	FRC	7057	2011.03.15
232/2008	WSMS7780000415962	FRC	7058	2010.12.29
233/2008	WKESDR27071303199 / 37413	FRC	7059, 3312T, M576	2013.12.05
234/2008	WSM0000005002365	FRC	7060	2011.03.17
235/2008	WSM0000005030496	FRC	7061, 3395T, M576	2013.09.03
236/2008	WSM0000005023585	FRC	7062, 06 1286, 2850K	2013.02.01
238/2008	WSM0000005020868	FRC	7063, 04 1181, MR81	2012.10.31
239/2008	971635	FRC	7064	2010.03.31
246/2008	WSM0000005049712	FRC	3404T, MR79	2014.01.17
247/2008	WSM0000005049711	FRC	3404T, MR79	2014.01.02
248/2008	VM3LVFS3FX4R00395 / 99/C0852.001	FRC	7071	2011.03.20
249/2008	WKESDR27071303197 / 37411	FRC	7072, 3312T, M528	2013.12.31
251/2008	VM3LVFS3F44R09273 / 04C1116/001	FRC	7074	2011.03.21
252/2008	VM3LVFS3F21R05511 / 02C1921.003	FRC	7075	2011.03.21
253/2008	VM3LVFS3EW1R06865 / 97/C2071-002	FRC	7076	2010.04.30
254/2008	WSMS7480000440339	FRC	7077	2011.03.25
255/2008	WSMS7480000434140	FRC	7078	2011.03.25
256/2008	WSMS7480000097312	FRC	7079	2010.03.26
257/2008	WSMS7480000406094	FRC	7080	2010.11.23
258/2008	WSM0000005020742	FRC	7081, 06 1286, MR79	2012.10.31
259/2008	WSM0000005032162	FRC	7082, 07 1310, MR79	2013.09.30
260/2008	WSM0000005041147	FRC	07 1328, MR79	2014.01.10
261/2008	VFNSYY3KEYAR00826 / 47091	FRC	7083	2011.03.25
262/2008	VM4CD382G2A021128 / 54076	FRC	7084	2011.03.25

263/2008	SUDNS1CBZ81015111 / 11023427	FRC	7085, 4838, M576	2014.03.31
264/2008	WKESDR27071306552 / 37.640	FRC	3372T, M576	2013.04.02
265/2008	WSMS7480000561213	FRC	7086	2011.03.27
266/2008	VM3LVFS3E41R11530 / 04C1874/001	FRC	6001, T3917	2010.10
267/2008	VM3LVFS3E41R11451 / 04C1261/002	FRC	5280, T3917	2010.06.03
268/2008	WSM00000005034042	FRC	7087, 07 1310, M523	2014.01.31
269/2008	WSM00000005041179	FRC	07 1328, MR79	2014.01.14
270/2008	VM3LVFS3F71R16522 / 07C0903/005	FRC	BX5193, M576	2013.08.08
271/2008	VM3LVFS3F71R16523 / 07C0903/006	FRC	BX5193, M576	2013.08.08
272/2008	VM3LVFS3F71R16524 / 07C0903/007	FRC	BX5193, M576	2013.08.08
273/2008	VM3LVFS3F71R16529 / 07C0903/012	FRC	BX5193, M576	2013.08.08
274/2008	VM3LVFS3F71R16525 / 07C0903/008	FRC	BX5193, M576	2013.08.08
275/2008	VM3LVFS3F71R16526 / 07C0903/009	FRC	BX5193, M576	2013.08.08
276/2008	VM3LVFS3F71R16527 / 07C0903/010	FRC	BX5193, M576	2013.08.08
277/2008	VM3LVFS3F71R16528 / 07C0903/011	FRC	BX5193, M576	2013.08.08
278/2008	VM3LVFS3F71R16518 / 07C0903/001	FRC	BX5193, M576	2013.08.08
279/2008	VM3LVFS3F71R16519 / 07C0903/002	FRC	BX5193, M576	2013.08.08
280/2008	VM3LVFS3F71R16521 / 07C0903/004	FRC	BX5193, M576	2013.08.08
281/2008	VM3LVFS3F71R16520 / 07C0903/003	FRC	BX5193, M576	2013.08.08
282/2008	VM3LVFS3F71R16531 / 07C0903/014	FRC	BX5193, M576	2013.08.08
283/2008	VM3LVFS3F71R16532 / 07C0903/015	FRC	BX5193, M576	2013.08.08
284/2008	VM3LVFS3F71R16533 / 07C0903/016	FRC	BX5193, M576	2013.08.08
285/2008	VM3LVFS3F71R16534 / 07C0903/017	FRC	BX5193, M576	2013.08.08
286/2008	VM3LVFS3F71R16535 / 07C0903/018	FRC	BX5193, M576	2013.08.08
287/2008	VM3LVFS3F71R16536 / 07C0903/019	FRC	BX5193, M576	2013.08.08
288/2008	VM3LVFS3F71R16537 / 07C0903/020	FRC	BX5193, M576	2013.08.08
289/2008	VM3LVFS3F71R16538 / 07C0903/021	FRC	BX5193, M576	2013.08.08
290/2008	VM3LVFS3F71R16539 / 07C0903/022	FRC	BX5193, M576	2013.08.08
291/2008	VM3LVFS3F71R16530 / 07C0903/013	FRC	BX5193, M576	2013.08.08
292/2008	VM3LVFS3F21R05071 / 02C1389.004	FRC	7088	2011.03.31
293/2008	WSMS7480000561274	FRC	7089	2011.03.17
295/2008	WSMS7480000443803	FRC	7091	2011.03.31
296/2008	WSM00000005032439	FRC	3395T, M576	2013.10.18
297/2008	WSM00000005049782	FRC	07 1328, MR79	2014.03.03
298/2008	WK0S0002400101842 / 11000298	FRC	7092, 4838, M576	2014.03.31
299/2008	WK0S0002400101840 / 11000278	FRC	7093, 4838, M576	2014.03.31
300/2008	WK0S0002400101839 / 11000268	FRC	7094, 4838, M576	2014.03.31
301/2008	WK0S0002400101838 / 11012507	FRC	7095, 4838, M576	2014.03.31
302/2008	WFDFLT33541000970 / 43601	FRC	7096	2011.04.02
303/2008	2107964	FNA	7097	2014.03.28
304/2008	WSM00000005032515	FRC	07 1310, MR79	2013.10.01
305/2008	WSMS7480000403515	FRC	7098	2010.12.31
306/2008	VM3LVFS3EX1R08657 / 99/C2078-003	FRC	7099	2011.04.03
307/2008	WKESDR27071303135 / 37349	FRC	7100, 3383T, M576	2013.04.26
308/2008	WSM00000005050874	FRC	3404T, M576	2014.01.11
309/2008	WSM00000005050838	FRC	3404T, M576	2014.01.11
310/2008	WSM00000005050837	FRC	3404T, M576	2014.01.11
311/2008	WSM00000005050840	FRC	3404T, M576	2014.01.11
312/2008	VM3LVFS3F21R04894 / 02C1099.002	FRC	7101	2011.04.02
313/2008	WSMS7480000561082	FRC	7106	2011.04.02
314/2008	WKESDR27000148602 / 24219	FRC	7107	2011.04.03
315/2008	WKESDR27000148606 / 24223	FRC	7108	2011.04.03
316/2008	XLER6X20004403432	FNA	7102	2011.04.04
317/2008	WSMS7780000443134	FRC	7103	2011.04.04
318/2008	TRGSAF335WD126692 / 8498	FRC	7104	2010.06.23
319/2008	VM3LVFS3FY4R00849 / 00C0001.003	FRC	7105	2011.04.05
321/2008	WSMS7480000078539	FNA	7110	2011.04.05
322/2008	WK0SVKT24S2148018 / 21-48018	FNA	7111	2011.04.04
323/2008	WSM00000005024724	FRC	7112, 3379T, MR79	2013.01.02
324/2008	WSM00000005027315	FRC	7113, 07 1295, MR79	2013.04.02
325/2008	WSM00000005000051	FRC	7115	2011.04.03

326/2008	<b>WSM0000005014857</b>	<b>FRC</b>	7116, 06 1275, MR79	2012.04.05
327/2008	VM3LVFS3FY1R01080 / <b>00C0336-013</b>	<b>FRC</b>	7117	2011.04.04
328/2008	VAVSAF3383H188294 / <b>03C0928/009</b>	<b>FRC</b>	7114	2011.04.07
329/2008	VM3LVFS3EW1R07514 / <b>98/C0808-008</b>	<b>FRC</b>	7118	2010.07.31
330/2008	<b>WSM0000005041156</b>	<b>FRC</b>	07 1328, MR79	2014.01.10
331/2008	VM3LVFS3F21R04409 / <b>02C0236.001</b>	<b>FRC</b>	7119	2011.04.08
332/2008	<b>WSMS7480000441069</b>	<b>FRC</b>	7120	2011.04.08
333/2008	<b>YS2P4X20001230158</b>	<b>FRC</b>	7121	2011.04.08
334/2008	WMAM035009Y026681 / <b>2128-96</b>	<b>FNA</b>	7122	2011.04.09
335/2008	<b>WSM0000005038173</b>	<b>FRC</b>	07 1328,MR79	2014.01.10
336/2008	<b>WSM0000005038174</b>	<b>FRC</b>	07 1328,MR79	2014.01.10
337/2008	WKESDR27051228755 / <b>32101</b>	<b>FRC</b>	7123	2011.04.09
338/2008	<b>WSMS7780000435174</b>	<b>FRC</b>	7124	2011.04.11
339/2008	<b>WKESDR27051225673</b>	<b>FRC</b>	7125	2011.04.12
340/2008	<b>WSMS7480000441981</b>	<b>FRC</b>	7126	2011.04.12
341/2008	VM4CD382G1A020247 / <b>49327</b>	<b>FRC</b>	7127	2011.04.14
342/2008	WK0S0002400101843 / <b>11000308</b>	<b>FRC</b>	7128, 4838, M576	2014.04.30
343/2008	WK0S0002400101841 / <b>11000288</b>	<b>FRC</b>	7129, 4838, M576	2014.04.30
344/2008	VM4CD381J1A010752 / <b>51504</b>	<b>FRC</b>	7130	2011.04.02
345/2008	<b>4128799</b>	<b>FNA</b>	7131	2011.04.02
346/2008	<b>WK0SVKA24X0244733</b>	<b>FRC</b>	7132	2011.04.02
347/2008	VM4CD381J1A010754 / <b>51506</b>	<b>FRC</b>	7133	2011.04.02
348/2008	<b>WSMS7480000455563</b>	<b>FRC</b>	4684, 03 1178	2010.02.02
349/2008	<b>VFNSYY3CX SAR06439</b>	<b>FNA</b>	7134	2011.04.15
350/2008	<b>VVCS0RXBAS4X00567</b>	<b>FRC</b>	7135	2011.04.15
351/2008	<b>WSMS7480000442005</b>	<b>FRC</b>	7136	2011.04.15
352/2008	VM3LVFS3EV1R06585 / <b>97/C1887-002</b>	<b>FRC</b>	7137	2010.02.28
353/2008	<b>WSMS7480000435831</b>	<b>FRC</b>	7138	2011.04.16
354/2008	VM3LVFS3FW1R00227 / <b>98/1202-001</b>	<b>FRC</b>	7139	2010.12.31
355/2008	<b>VAVSAF335XH135166</b>	<b>FRC</b>	7140	2011.04.11
356/2008	<b>WSMS7480000432137</b>	<b>FRC</b>	7141	2011.04.11
357/2008	VM3LVFS3EW1R08619 / <b>98/C1953-006</b>	<b>FRC</b>	7142	2011.01.31
358/2008	<b>WSM0000005053682</b>	<b>FRC</b>	05 1248, MR79	2014.03.13
359/2008	<b>VM4CD381JYA010029</b>	<b>FRC</b>	7143	2011.04.11
360/2008	VM3LVFS3FY1R01087 / <b>00C0336-020</b>	<b>FRC</b>	7144	2011.04.16
361/2008	<b>WSM0000005039993</b>	<b>FRC</b>	05 1248, MR79	2014.01.02
362/2008	<b>WSM0000005039992</b>	<b>FRC</b>	05 1248, MR79	2014.01.02
363/2008	W09218334YDT18S03 / <b>2180200D3</b>	<b>FRC</b>	7145	2011.04.18
364/2008	<b>WSMS7480000406088</b>	<b>FRC</b>	7147	2010.09.22
365/2008	<b>WSMS7480000406089</b>	<b>FRC</b>	7148	2010.09.22
366/2008	VM3LVFS3EW1R08618 / <b>98/C1953-005</b>	<b>FRC</b>	7149	2011.01.31
367/2008	<b>WSM0000005034043</b>	<b>FRC</b>	07 1328, M576	2014.03.03
368/2008	<b>WSM0000005050802</b>	<b>FRC</b>	3404T, MR79	2014.01.11
369/2008	<b>WSM0000005050804</b>	<b>FRC</b>	3404T,MR79	2014.01.11
370/2008	<b>WSM0000005050803</b>	<b>FRC</b>	3404T,MR79	2014.01.11
371/2008	<b>WK0S0002400084347</b>	<b>FRC</b>	7150, 3365T, M576	2013.12.31
372/2008	<b>WK0S0002400084354</b>	<b>FRC</b>	7151, 3365T, M576	2013.12.31
373/2008	<b>WK0S0002400084334</b>	<b>FRC</b>	7152, 3365T, M576	2013.12.31
374/2008	<b>WK0S0002400084343</b>	<b>FRC</b>	7153, 3365T, M576	2013.12.31
375/2008	<b>WK0S0002400111725</b>	<b>FRC</b>	7154, 3365T, M576	2013.12.31
376/2008	<b>WK0S0002400111726</b>	<b>FRC</b>	7155, 3365T, M576	2013.12.31
377/2008	<b>WK0S0002400111727</b>	<b>FRC</b>	7156, 3365T, M576	2013.12.31
378/2008	<b>WK0S0002400084369</b>	<b>FRC</b>	7157, 3365T, M576	2013.12.31
379/2008	<b>WK0S0002400084368</b>	<b>FRC</b>	7158, 3365T, M576	2013.12.31
380/2008	<b>WK0S0002400082638</b>	<b>FRC</b>	7159, 3365T, M576	2013.09.14
381/2008	<b>WK0S0002400082636</b>	<b>FRC</b>	7160, 3365T, M576	2013.09.14
382/2008	<b>WK0S0002400082634</b>	<b>FRC</b>	7161, 3365T, M576	2013.09.14
383/2008	<b>WK0S0002400082635</b>	<b>FRC</b>	7162, 3365T, M576	2013.09.14
384/2008	<b>WK0S0002400082639</b>	<b>FRC</b>	7163, 3365T, M576	2013.09.14
385/2008	<b>WK0S0002400082633</b>	<b>FRC</b>	7164, 3365T, M576	2013.09.14
386/2008	<b>WK0S0002400082632</b>	<b>FRC</b>	7165, 3365T, M576	2013.09.14

387/2008	<b>WK0S0002400082631</b>	<b>FRC</b>	7166, 3365T, M576	2013.09.14
388/2008	<b>WK0S0002400082637</b>	<b>FRC</b>	7167, 3365T, M576	2013.09.14
389/2008	<b>WK0S0002400082640</b>	<b>FRC</b>	7168, 3365T, M576	2013.09.24
390/2008	<b>WK0S0002400082641</b>	<b>FRC</b>	7169, 3365T, M576	2013.09.24
391/2008	<b>WK0S0002400082642</b>	<b>FRC</b>	7170, 3365T, M576	2013.09.24
392/2008	<b>WK0S0002400082643</b>	<b>FRC</b>	7171, 3365T, M576	2013.09.24
393/2008	<b>WK0S0002400082644</b>	<b>FRC</b>	7172, 3365T, M576	2013.09.24
394/2008	<b>WK0S0002400082630</b>	<b>FRC</b>	7173, 3365T, M576	2013.10.03
395/2008	<b>WSM00000005034566</b>	<b>FRC</b>	7174, 3404T, M576	2013.10.30
396/2008	VM3LVFS3E11R10577 / <b>01C0302.005</b>	<b>FRC</b>	7175	2011.04.07
397/2008	SUDNS1CTZ67010670 / <b>11011366</b>	<b>FRC</b>	7185	2012.08.31
399/2008	<b>WSM00000005041159</b>	<b>FRC</b>	07 1328, MR79	2014.01.10
400/2008	<b>WSMS7480000407017</b>	<b>FRC</b>	7186	2010.06.30
401/2008	VM3LVFS3EWSA07273 / <b>98/C0491/001</b>	<b>FRC</b>	7187	2010.05.31
402/2008	<b>WSM00000005050875</b>	<b>FRC</b>	3404T, M576	2014.01.11
403/2008	<b>WSM00000005050839</b>	<b>FRC</b>	3404T, M576	2014.01.11
404/2008	VM3LVFS3EW1R07979 / <b>99/C1150-001</b>	<b>FRC</b>	7182	2011.04.21
405/2008	VM3LVFS3EW1R07982 / <b>99/C1150-002</b>	<b>FRC</b>	7183	2011.04.21
406/2008	<b>WSMS7480000447129</b>	<b>FRC</b>	7184	2011.04.21
407/2008	<b>WSMS7480000065965</b>	<b>FNA</b>	7180	2011.04.19
408/2008	<b>WK0SVKT24W9806204 / 98-06204</b>	<b>FRC</b>	7176	2010.12.31
409/2008	<b>WSMS7480000444431</b>	<b>FRC</b>	7177	2011.04.19
410/2008	<b>WSMS7780000458370</b>	<b>FRC</b>	7178	2011.04.19
411/2008	<b>WK0SVKT24W9814094 / 98-14094</b>	<b>FRC</b>	7179	2010.12.31
412/2008	VF9STE38FLX003027 / <b>212A</b>	<b>FRC</b>	7181	2011.04.19
413/2008	VFNSYY3CXWAR15641 / <b>39827</b>	<b>FRC</b>	7188	2010.05.27
414/2008	VM3LVFS3FY1R02002 / <b>00C2567-017</b>	<b>FRC</b>	7189	2011.04.28
415/2008	VM3LVFS3FS1R04562 / <b>02C0498.001</b>	<b>FRC</b>	7190	2011.04.28
416/2008	WMAN28ZZ98Y207955 / <b>11019417</b>	<b>FRC</b>	7191, 4560, MR91	2014.01.31
417/2008	WMAN28ZZ98Y207927 / <b>11019407</b>	<b>FRC</b>	7192, 4560, MR91	2014.01.31
418/2008	<b>WSMS7480000412270</b>	<b>FRC</b>	7193	2010.09.28
419/2008	WKESDR27011269083 / <b>26075</b>	<b>FRC</b>	7194	2011.04.30
420/2008	<b>WSM00000005034046</b>	<b>FRC</b>	7195, 07 1328, 2761(2)K	2014.03.03
421/2008	<b>VAVSAF3382H172608</b>	<b>FRC</b>	7196	2011.04.26
422/2008	<b>WSM00000005041195</b>	<b>FRC</b>	3404T, M576	2014.01.29
423/2008	<b>WSM00000005039991</b>	<b>FRC</b>	05 1248, MR79	2014.01.02
425/2008	<b>WSM00000005050377</b>	<b>FRC</b>	3404T, MR79	2014.01.11
426/2008	<b>WSM00000005041239</b>	<b>FRC</b>	3421T, M576	2014.04.01
427/2008	<b>WSM00000005041203</b>	<b>FRC</b>	3404T, M576	2014.01.30
428/2008	VFNS383ELK1A11316 / <b>89/1544-006</b>	<b>FNA</b>	7197	2011.04.25
429/2008	<b>519-50.00.002-03 A</b>	<b>FNA</b>	7198	2014.04.09
430/2008	VM4C381BRAW004216 / <b>39694</b>	<b>FRC</b>	7199	2010.05.18
431/2008	<b>2119904</b>	<b>FNA</b>	7200	2011.04.25
432/2008	VM3LVFS3EY1R10218 / <b>00C1349.001</b>	<b>FRC</b>	7201	2011.05.05
433/2008	<b>WSMS7480000433264</b>	<b>FRC</b>	7202	2011.04.26
434/2008	<b>WSMS7480000450205</b>	<b>FRC</b>	7203	2011.04.26
435/2008	<b>WK0SVKT2420297778</b>	<b>FRC</b>	7204	2011.04.26
436/2008	<b>WSMS7480000430626</b>	<b>FRC</b>	7205	2011.04.26
437/2008	<b>WSM00000005001561</b>	<b>FRC</b>	7206	2011.04.26
438/2008	<b>WSMS7480000076006</b>	<b>FNA</b>	7207	2011.04.26
439/2008	<b>WSM00000005003521</b>	<b>FRC</b>	7208	2011.04.26
440/2008	VM3LVFS3F26R05435 / <b>02C1784.001</b>	<b>FRC</b>	7209	2011.04.26
441/2008	<b>WSMS7780000081464</b>	<b>FNA</b>	7210	2011.04.25
443/2008	VM4C381BRXA004992 / <b>43280</b>	<b>FRC</b>	7212	2011.04.07
444/2008	<b>WSMS7480000439653</b>	<b>FRC</b>	7213	2011.04.26
445/2008	<b>WSMS7480000405337</b>	<b>FRC</b>	7214	2010.08.31
446/2008	VFNS383ELK1A11474	<b>FNA</b>	7215	2011.04.25
447/2008	<b>052076</b>	<b>FNA</b>	7216	2011.04.25
448/2008	<b>WSMS7480000406987</b>	<b>FRC</b>	7217	2010.09.29
449/2008	VM3LVFS3E21R05070 / <b>02C1389.003</b>	<b>FRC</b>	7218	2011.05.06
451/2008	<b>WSMS7480000443491</b>	<b>FRC</b>	7220	2011.05.06

452/2008	<b>WK0SVKT24W9814092</b>	<b>FRC</b>	7221	2010.07.13
453/2008	VM3LVFS3F11A03639 / <b>01C2006.001</b>	<b>FRC</b>	7222	2011.05.06
454/2008	<b>ZFA25000001389892</b>	<b>IN</b>	7223	2014.04.01
455/2008	<b>WSM00000005027026</b>	<b>FRC</b>	7224, 07 1295, MR79	2013.05.02
456/2008	<b>WSMS7480000443422</b>	<b>FRC</b>	7225	2011.05.09
458/2008	WK0S0002400101846 / <b>11000318</b>	<b>FRC</b>	7226, 4838, M576	2014.04.30
459/2008	WK0S0002400101844 / <b>11000328</b>	<b>FRC</b>	7227, 4838, M576	2014.04.30
460/2008	WK0S0002400101845 / <b>11000338</b>	<b>FRC</b>	7228, 4838, M576	2014.04.30
461/2008	WK0S0002400101849 / <b>11000348</b>	<b>FRC</b>	7229, 4838, M576	2014.04.30
462/2008	WK0S0002400101848 / <b>11000358</b>	<b>FRC</b>	7230, 4838, M576	2014.04.30
463/2008	WK0S0002400101847 / <b>11000368</b>	<b>FRC</b>	7231, 4838, M576	2014.04.30
464/2008	<b>WSM00000005041258</b>	<b>FRC</b>	7234, 3421T, MR79	2014.04.03
465/2008	<b>WSM00000005052310</b>	<b>FRC</b>	07 1328, MR79	2014.03.03
466/2008	<b>WSMS7480000455735</b>	<b>FRC</b>	5321, 02 1114, 3150K	2010.01.31
467/2008	SUDNS1CTZ81016898 / <b>11000418</b>	<b>FRC</b>	7235, 4838, MR79	2014.01.31
468/2008	VM3LVFS3FY1R01075 / <b>00C0336-008</b>	<b>FRC</b>	7232	2011.05.13
469/2008	VM3LVFS3F24R06200 / <b>02C2091.001</b>	<b>FRC</b>	7233	2011.05.13
470/2008	<b>WSM00000005053548</b>	<b>FRC</b>	3421T, MR79	2014.04.01
471/2008	<b>WSMS7480000441985</b>	<b>FRC</b>	7237	2011.05.16
472/2008	<b>WSMS7480000410586</b>	<b>FRC</b>	7238	2010.12.31
473/2008	VM3LVFS3EX6R08880 / <b>99/C0151-001</b>	<b>FRC</b>	7239	2011.02.28
474/2008	<b>WSM00000005034045</b>	<b>FRC</b>	7240, 07 1328, MR79	2014.03.03
475/2008	VM4CD383JYA030046 / <b>46567</b>	<b>FRC</b>	7241	2011.05.15
476/2008	<b>WSM00000005032473</b>	<b>FRC</b>	3404T, MR79	2013.12.03
477/2008	<b>WSM00000005053226</b>	<b>FRC</b>	07 1328, MR79	2014.03.03
478/2008	<b>WSM00000005053556</b>	<b>FRC</b>	3421T, MR79	2014.04.01
479/2008	<b>WSM00000005052309</b>	<b>FRC</b>	07 1328, MR79	2014.03.03
480/2008	<b>WSM00000005052308</b>	<b>FRC</b>	07 1328, MR79	2014.03.03
481/2008	<b>WSM00000005041254</b>	<b>FRC</b>	7244, 3319T, 3074K	2014.04.24
482/2008	<b>WSM00000005027028</b>	<b>FRC</b>	7245, 3319T, MR79	2013.05.16
483/2008	JAAN1R71P77101673 / Y6LN1R71P7L000033 / <b>11005627</b>	<b>FRC/X</b>	7242, 5547, M611	2013.06.30
484/2008	SUDNS1CTZ81016339 / <b>11023437</b>	<b>FRC</b>	7243 , 4838, MR79	2014.04.30
485/2008	<b>WSM00000005053817</b>	<b>FRC</b>	08 1348, MR79	2014.04.14
486/2008	<b>WSM00000005053818</b>	<b>FRC</b>	08 1348, MR79	2014.04.14
487/2008	<b>WSM00000005053819</b>	<b>FRC</b>	08 1348, MR79	2014.04.14
488/2008	<b>WSM00000005034641</b>	<b>FRC</b>	3395T, MR79	2013.10.08
489/2008	VAVSAF3382H170726 / <b>11389</b>	<b>FRC</b>	7246	2011.05.26
491/2008	VM4CD382G2A021437 / <b>55490</b>	<b>FRC</b>	7248	2011.05.27
492/2008	SUDNS1CTZ64009783	<b>FRC</b>	7249, 4838, M433	26.07.2012
493/2008	<b>WSMS7480000445183</b>	<b>FRC</b>	7250	2011.05.28
494/2008	YE7SD3AABN2202352 / <b>F2001.631594</b>	<b>FRC</b>	7251	28.05.2011
495/2008	<b>WSMS7780000445765</b>	<b>FRC</b>	7252	2011.05.26
496/2008	<b>WSMS7480000440489</b>	<b>FRC</b>	7253	2011.05.26
497/2008	VF9LVFS3EL2365155 / <b>90/0707-020</b>	<b>FNA</b>	7254	2011.04.04
498/2008	<b>WSM00000005029627</b>	<b>FRC</b>	7255, 3319T, M576	2013.12.31
499/2008	<b>WSM00000005029628</b>	<b>FRC</b>	7256, 3319T, M576	2013.12.31
500/2008	<b>WSM00000005041253</b>	<b>FRC</b>	7257, 3421T, MR79	2014.04.01
501/2008	<b>WSM00000005041204</b>	<b>FRC</b>	7258, 3319T, MR79	2014.03.19
502/2008	<b>WSM00000005041205</b>	<b>FRC</b>	7259, 3319T, MR79	2014.03.25
503/2008	SUDNS1CTZ81016273 / <b>11000848</b>	<b>FRC</b>	7260, 4838, M576	2014.03.31
504/2008	SUDNS1CTZ77014410 / <b>11012207</b>	<b>FRC</b>	7261, 4838, M576	2014.02.28
506/2008	W091633382HS09168 / <b>01C1918.007</b>	<b>FRC</b>	7262	2011.05.23
507/2008	<b>WSM00000005053551</b>	<b>FRC</b>	3421T, MR79	2014.04.01
508/2008	VF3YBCMAD11391042 / <b>11003218</b>	<b>FNA/X</b>	7263, 4561, M607	2014.03.31
509/2008	VF3YBCMAD11381963 / <b>11003208</b>	<b>FNA/X</b>	7264, 4561, M607	2014.03.31
510/2008	VF3YBCMAD11384403 / <b>11003228</b>	<b>FNA/X</b>	7265, 4561, M607	2014.03.31
511/2008	VF3YBCMAD11390639 / <b>11003238</b>	<b>FNA/X</b>	7266, 4561, M607	2014.03.31
512/2008	<b>WSM00000005015948</b>	<b>FRC</b>	7270, 04 1181, MR81	2012.06.30
513/2008	<b>WSMS7480000443053</b>	<b>FRC</b>	7267	2011.06.02
514/2008	<b>WSMS7480000443051</b>	<b>FRC</b>	7268	2011.06.02
515/2008	<b>WSMS7480000443049</b>	<b>FRC</b>	7269	2011.06.02

517/2008	WSMS7480000445525	FRC	7272	2011.06.06
518/2008	WSM00000005033984	FRC	7273, 3395T, MR81	2013.09.13
519/2008	WSM00000005033978	FRC	7274, 3395T, MR81	2013.09.04
520/2008	WSM00000005033981	FRC	7275, 3395T, MR81	2013.09.04
521/2008	WSM00000005033983	FRC	7276, 3395T, MR81	2013.09.04
522/2008	WSM00000005033979	FRC	7277, 3395T, MR81	2013.09.04
523/2008	WSM00000005033982	FRC	7278, 3395T, MR81	2013.09.04
524/2008	WSM00000005033980	FRC	7279, 3395T, MR81	2013.09.04
525/2008	WSMS7480000444623	FRC	7280	2011.06.09
526/2008	VM3LVFS3EX6R09004 / 99/C0479-001	FRC	7281	2011.05.19
527/2008	WSM00000005053837	FRC	08 1348, MR79	2014.04.21
528/2008	WSM00000005041172	FRC	07 1328, M576	2014.01.31
529/2008	WSM00000005024913	FRC	7282, 3319T, MR79	2013.03.23
530/2008	WSM00000005024911	FRC	7283, 3319T, MR79	2013.02.16
531/2008	WSM00000005024407	FRC	7284, 3319T, MR79	2013.05.16
532/2008	WSM00000005053228	FRC	3421T, MR79	2014.04.01
533/2008	WSM00000005027020	FRC	7285, 07 1295, MR79	2013.04.02
534/2008	WSM00000005028692	FRC	7286, 3390T, MR79	2013.05.02
535/2008	WSMS7480000444722	FRC	7287	2011.06.09
536/2008	WSMS7480000443502	FRC	7288	2011.06.06
537/2008	WSM00000005041146	FRC	7289, 07 1328, 3074K	2014.01.31
538/2008	WKESDR27061264979	FRC	7290, 3312T, M576	2012.09.07
539/2008	WDB9700781K524228 / 00C1571.003	FRC	7291	2011.06.09
540/2008	WDB9700781K524547 / 00C1571.001	FRC	7292	2011.06.09
541/2008	VK1S338WHPF000223 / 21674	FRC	7293	2011.06.09
542/2008	VK1S338WHPF000216 / 21667	FRC	7294	2011.06.09
543/2008	WSMS7780000442499	FRC	7295	2011.06.12
544/2008	WSM00000005053549	FRC	3421T,MR79	2014.04.01
545/2008	WFDFLT33511000382 / 102008	FRC	7296	2011.06.14
546/2008	WSM00000005041285	FRC	7297, 3421T, M576	2014.05.13
549/2008	VK1S338DHRF000727	FRC	7298	2011.06.10
550/2008	WSMS7480000438652	FRC	7299	2011.06.16
551/2008	WSMS7480000430830	FRC	7300	2011.06.13
552/2008	VM4C381BNVA003708 / 38265	FRC	7301	2010.01.07
554/2008	WSMS7480000430845	FRC	7302	2011.06.21
555/2008	WSMS7780000435941	FRC	7303	2011.06.21
556/2008	WK0S0002400084337	FRC	7304, 3365T, M479	2013.11.16
559/2008	WK0S0002400057577	FRC	7307, 3365T, M576	2012.06.02
560/2008	WK0S0002400057576	FRC	7308, 3365T, M576	2012.06.02
561/2008	WK0S0002400057575	FRC	7309, 3365T, M576	2012.06.02
562/2008	WK0S0002400057574	FRC	7310, 3365T, M576	2012.06.02
563/2008	WK0S0002400057573	FRC	7311, 3365T, M576	2012.06.02
564/2008	WK0S0002400057572	FRC	7312, 3365T, M576	2012.06.02
565/2008	WK0S0002400057571	FRC	7313, 3365T, M576	2012.06.02
566/2008	WK0S0002400084304	FRC	7314, 3365T, M576	2013.11.09
567/2008	WK0S0002400084311	FRC	7315, 3365T, M576	2013.11.09
568/2008	WK0S0002400084312	FRC	7316, 3365T, M576	2013.11.09
569/2008	WK0S0002400084308	FRC	7317, 3365T, M576	2013.11.09
570/2008	WK0S0002400084306	FRC	7318, 3365T, M576	2013.11.12
571/2008	WK0S0002400084310	FRC	7319, 3365T, M576	2013.11.12
572/2008	WK0S0002400084303	FRC	7320, 3365T, M576	2013.11.12
573/2008	WK0S0002400084307	FRC	7321, 3365T, M576	2013.11.12
574/2008	WK0S0002400084359	FRC	7322, 3365T, M576	2014.01.21
575/2008	WK0S0002400084360	FRC	7323, 3365T, M576	2013.12.31
576/2008	WK0S0002400084356	FRC	7324, 3365T, M576	2013.12.31
577/2008	WK0S0002400084357	FRC	7325, 3365T, M576	2013.12.31
578/2008	WK0S0002400084358	FRC	7326, 3365T, M576	2013.12.31
579/2008	WSM00000005034565	FRC	07 1310, M576	2013.09.05
580/2008	WSM00000005034564	FRC	07 1310, M576	2013.09.05
581/2008	WSM00000005034562	FRC	07 1310, M576	2013.09.05
582/2008	WSM00000005034563	FRC	07 1310, M576	2013.09.05

583/2008	WSM00000005034567	FRC	07 1310, M576	2013.09.05
584/2008	WSM00000005034568	FRC	07 1310, M576	2013.09.05
585/2008	WSM00000005034569	FRC	07 1310, M576	2013.09.05
586/2008	WSM00000005034570	FRC	07 1310, M576	2013.09.05
587/2008	WSM00000005034571	FRC	07 1310, M576	2013.09.05
588/2008	WSM00000005034572	FRC	07 1310, M576	2013.10.01
589/2008	WSM00000005034573	FRC	07 1310, M576	2013.10.01
590/2008	WSM00000005034574	FRC	07 1310, M576	2013.10.01
591/2008	WSM00000005034575	FRC	07 1310, M576	2013.10.01
592/2008	WSM00000005034576	FRC	07 1310, M576	2013.10.01
593/2008	WSM00000005034577	FRC	07 1310, M576	2013.10.01
594/2008	WSM00000005034578	FRC	07 1310, M576	2013.10.01
595/2008	WSM00000005034579	FRC	07 1310, M576	2013.10.01
596/2008	WSM00000005034585	FRC	07 1328, M576	2013.11.07
597/2008	WSM00000005034584	FRC	07 1328, M576	2013.11.07
598/2008	WSM00000005034580	FRC	07 1310, M576	2013.10.01
599/2008	WSM00000005034581	FRC	07 1310, M576	2013.10.01
600/2008	WSM00000005034583	FRC	07 1328, M576	2013.11.07
601/2008	WSM00000005034582	FRC	07 1328, M576	2013.11.07
602/2008	WSM00000005034586	FRC	07 1328, M576	2013.11.07
605/2008	ZE5368SP6FJKL1055 / 119	FRC	7329	2011.06.20
606/2008	WSM00000005009073	FRC	7330	2011.06.19
607/2008	WSM00000005050843	FRC	08 1348, M576	2014.04.14
609/2008	SUDNSICTZ83017604 / 11023977	FRC	7331, 4838, M576	2014.06.30
610/2008	SUDNSICTZ83017603 / 11023967	FRC	7332, 4838, M576	2014.06.30
611/2008	WDB9505351L334927 / 11021617	FNA	7333, 4152, M568	2014.05.31
612/2008	VF3YCBMAD11441272 / 11003268	FNA/X	7334, 4561, M607	2014.06.30
613/2008	VF3YCBMAD11441000 / 11003258	FNA/X	7335, 4561, M607	2014.06.30
614/2008	VF3YCBMAD11441154 / 11003278	FNA/X	7336, 4561, M607	2014.06.30
615/2008	VF3YCBMAD11440717 / 11003248	FNA/X	7337, 4561, M607	2014.06.30
616/2008	WK0S0002400101852 / 11000828	FRC	7338, 4838, M576	2014.06.30
617/2008	WK0S0002400101818 / 11000808	FRC	7339, 4838, M576	2014.06.30
618/2008	WK0S0002400101820 / 11000778	FRC	7340, 4838, M576	2014.06.30
619/2008	WK0S0002400101821 / 11000788	FRC	7341, 4838, M576	2014.06.30
620/2008	WK0S0002400101822 / 11000798	FRC	7342, 4838, M576	2014.06.30
621/2008	WK0S0002400101851 / 11000818	FRC	7343, 4838, M576	2014.06.30
623/2008	WSM00000005053425	FRC	3404T, MR79	2014.03.07
624/2008	WSM00000005053426	FRC	3404T, MR79	2014.03.14
625/2008	WSM00000005050842	FRC	3404T, M576	2014.01.11
626/2008	WSM00000005050844	FRC	08 1348, M576	2014.04.14
627/2008	WDB9702771L323069 / 11001308	FRC/X	7344, 4560, M538	2014.05.31
628/2008	WMA18SZZ08P007840 / 11004178	FRC	7345, 4560, MR89	2014.06.30
629/2008	VM3LVFS3F11R02938 / 01C0726.001	FRC	7346	2011.07.03
630/2008	WSMS7480000441506	FRC	7347	2011.07.03
631/2008	WSM00000005012689	FRC	7348, 3330T, MR79	2012.03.02
633/2008	WSMS7480000440398	FRC	7351	2011.07.03
634/2008	WSMS7480000413102	FRC	7350	2010.12.09
635/2008	VM3LVFS3EW1R08122 / 98/C1260-002	FRC	7352	2010.09.25
636/2008	WSMS7780000443807	FRC	7353	2011.07.04
637/2008	WKESDR27011157731 / 25032	FRC	7354	2011.07.04
638/2008	VF644ACA000014261 / 11001448	FNA	7355, 4152, M572	2014.05.31
639/2008	VM4CD385GYA000904 / 44911	FRC	7357	2011.07.08
641/2008	WK0SVKT2420299827	FRC	7359	2011.07.07
642/2008	WSM00000005028810	FRC	7360, 3348T, MR79	2013.07.04
643/2008	WSM00000005032490	FRC	7361, 3404T, MR79	2013.12.03
644/2008	WSM00000005022744	FRC	7362, 3319T, M576	2012.12.31
645/2008	W091653382HS09458 / 108UL4662	FRC	7363	2011.07.01
646/2008	WSM00000005041182	FRC	7364, 3319T, MR79	2014.02.05
647/2008	WSM00000005022746	FRC	7365, 3319T, M576	2012.12.31
648/2008	WSM00000005054097	FRC	08 1348, MR79	2014.04.22
649/2008	WFDFLT3355100063 / 204486	FRC	T3888, M576	2010.12.16

651/2008	VM3LVFS3F14R03795 / 01C2057.003	FRC	7366	2011.07.14
652/2008	VM3LVFS3E21R10707 / 02C1005.001	FRC	7367	2011.07.14
653/2008	VM3LVFS3EW1A07342 / 98/C0626-002	FRC	7368	2010.05.31
654/2008	WK0S0002400084353	FRC	7369, 3365T, M576	2013.12.31
655/2008	WSMS7480000438321	FRC	7370	2011.07.10
656/2008	WKESDR27000149678	FRC	7371	2011.07.11
657/2008	VM3LVFS3ET1R05033 / 96/C1388-001	FNA	7372	2011.07.15
658/2008	SUDNS1CTZ81016272 / 11000838	FRC	7373, 4838, M576	2014.07.31
659/2008	SUDNS1CTZ81016269 / 11022837	FRC	7374, 4838, M576	2014.07.31
660/2008	SUDNS1CTZ81016259 / 11022827	FRC	7375, 4838, M576	2014.07.31
661/2008	SUDNS1CTZ81016022 / 11022807	FRC	7376, 4838, M576	2014.07.31
662/2008	SUDNS1CTZ81016023 / 11022817	FRC	7377, 4838, M576	2014.07.31
663/2008	WSM00000005028665	FRC	7378, 3390T, MR79	2013.07.02
665/2008	VK1S338DHRF000730	FRC	7380	2011.07.17
666/2008	WAX024040430	FRC	7381	2011.07.17
669/2008	W0908F336WPA10021 / 22028	FRC	7382	2010.12.11
670/2008	VV1F3FA3XSN105201	FRC	7383	2011.07.25
671/2008	WSMS7480000430625	FRC	7384	2011.07.18
672/2008	VM3LVFS3F21R04433 / 02C0287.001	FRC	7385	2011.07.17
673/2008	WSMS7480000446113	FRC	7386	2011.07.22
674/2008	WSM00000005052651	FRC	3404T, MR79	2014.02.26
675/2008	WSMS7780000451590	FRC	7387	2011.07.24
676/2008	WSMS7780000433778	FRC	7388	2011.07.24
677/2008	VF3YCBMAD11441118 / 11003308	FNAX	7389, 4561, M607	2014.07.31
678/2008	VF3YCBMAD11441191 / 11003288	FNA/X	7390, 4561, M607	2014.06.30
679/2008	VF3YCBMAD11440866 / 11003298	FNA/X	7391, 4561, M607	2014.06.30
680/2008	VF3YCBMAD11440904 / 11003318	FNA/X	7392, 4561, M607	2014.07.31
681/2008	ZCFC50A2085754065 / 11006518	FNA/X	7393, 4561, M607	2014.07.31
682/2008	ZCFC50A2085753316 / 11006448	FNA/X	7394, 4561, M607	2014.07.31
683/2008	ZCFC50A2085754063 / 11006538	FNA/X	7395, 4561, M607	2014.07.31
684/2008	ZCFC50A2085753688 / 11006508	FNA/X	7396, 4561, M607	2014.07.31
685/2008	ZCFC50A2085753689 / 11006498	FNA/X	7397, 4561, M607	2014.07.31
686/2008	ZCFC50A2085753690 / 11006488	FNA/X	7398, 4561, M607	2014.07.31
687/2008	ZCFC50A2085753693 / 11006458	FNA/X	7399, 4561, M607	2014.07.31
688/2008	ZCFC50A2085753692 / 11006468	FNA/X	7400, 4561, M607	2014.07.31
689/2008	ZCFC50A2085753691 / 11006478	FNA/X	7401, 4561, M607	2014.07.31
690/2008	ZCFC50A2085754064 / 11006528	FNA/X	7402, 4561, M607	2014.07.31
692/2008	VM3LVFS3F24R04851 / 02/C1011.002	FRC	7404	2011.07.24
693/2008	WSMS7480000413928	FRC	7405	2011.02.04
694/2008	WSMS7480000432090	FRC	7406	2011.07.25
695/2008	WSM00000005024912	FRC	7407, 06 1281, MR79	2013.01.29
696/2008	WSMS7480000088312	FNA	7408	2011.07.28
697/2008	VM3LVFS3FY1A00982 / 00C3118.001	FRC	7409	2011.07.28
698/2008	WSMS7480000446278	FRC	7410	2011.07.30
699/2008	WSMS7480000444433	FRC	7411	2011.07.30
700/2008	WSMS7480000443524	FRC	7412	2011.07.30
701/2008	WSM00000005030485	FRC	7413, 3319T, M576	2013.04.30
702/2008	WSMS7480000434245	FRC	7415	2011.07.30
703/2008	WSM00000005013995	FRC	7416, 06 1275, MR79	2012.04.03
704/2008	WSM00000005050850	FRC	08 1348, M576	2014.05.15
705/2008	WSM00000005050851	FRC	08 1348, M576	2014.05.15
706/2008	XLDTXZ33900041497 / 22277	FRC	7417	2011.05.28
707/2008	SUDNS1CBZ81016986 / 11000938	FRC	7418, 4838, M576	2014.06.30
708/2008	SUDNS1CBZ81016987 / 11000948	FRC	7419, 4838, M576	2014.06.30
709/2008	SUDNS1CBZ81016988 / 11000958	FRC	7420, 4838, M576	2014.06.30
710/2008	SUDNS1CBZ81016989 / 11000968	FRC	7421, 4838, M576	2014.06.30
711/2008	SUDNS1CBZ81016985 / 11000928	FRC	7422, 4838, M576	2014.06.30
712/2008	WSM00000005055345	FRC	08 1348, MR79	2014.04.21
713/2008	WK0SVKT24X9838363	FRC	7423	2011.07.26
716/2008	WSM00000005041240	FRC	7425, 3421T, M443	2014.04.01
717/2008	VM3LVFS3EW6A07171 / 98.C0265/003	FRC	7426	2010.04.30

718/2008	VM4CD383JXA000258 / 42975	FRC	7427	2011.05.03
719/2008	WSM00000005054254	FRC	3421T, MR79	2014.05.15
720/2008	WSM00000005053557	FRC	3421T, MR79	2014.05.15
721/2008	WSM00000005003002	FRC	5236.5, 04 1234, 3150K	2011.01
722/2008	WSMS7480000082416	FNA	7428	2011.08.05
723/2008	WSMS7780000411903	FRC	7429	2011.02.08
724/2008	WSMS7480000446851	FRC	7430	2011.08.11
725/2008	WSMS7480000438310	FRC	7431	2011.08.09
726/2008	WSM00000005024927	FRC	7432, 06 1286, MR79	2013.02.01
727/2008	WSMS7780000442529	FRC	7433	2011.08.11
729/2008	VFLCS3WPXX9900038 / F8001.630626	FRC	7435	2011.08.11
730/2008	WSMS7480000415797	FRC	7436	2010.12.31
731/2008	WK0S0002400084305	FRC	7437, 3365T, M576	2013.11.12
732/2008	WK0S0002400084309	FRC	7438, 3365T, M576	2013.11.09
733/2008	WKESDR27051242649	FRC	7439	2011.08.12
734/2008	WSM00000005006702	FRC	7450	2011.08.04
735/2008	WSMS7480000450197	FRC	7440	2011.08.13
736/2008	WSMS7780000444593	FRC	7441	2011.08.18
737/2008	WMA21XZZ78P004424 / 11023077	FRC	7442, 6652, MR92	2014.03.27
738/2008	WSMS7480000448790	FRC	7443	2011.08.14
739/2008	WKESDR27011277057 / 26670	FRC	7444	2011.08.14
740/2008	VF9STE38SLX003001	FNA	7445	2011.08.14
741/2008	VFLCS3WPXY9900078 / F8001.630.860	FRC	7446	2011.08.18
742/2008	WSM00000005010344	FRC	7447	2011.08.14
743/2008	WMV30KS24YL247444	FRC	7448	2011.08.20
744/2008	YV2A4B1C5VB183619 / 159797	FNA	7449	2011.08.21
745/2008	YV2AS02C88B496676 / 11006028	FRC	7451, 4560, MR91	2014.07.31
746/2008	SUZCFJ5FR8Z000081 / 11006068	FRC	7452, 4560, M566	2014.07.31
747/2008	SUZCFJ5FR8Z000078 / 11001358	FNA	7453, 4152, M566	2014.06.30
748/2008	YS2R6X20002039016 / 11001348	FNA	7454, 4152, M566	2014.06.30
749/2008	WK0S0002400101817 / 11007118	FRC	7455, 4838, M576	2014.07.31
750/2008	WSM00000005015817	FRC	7456, 3304T, M511	2012.06.30
751/2008	VFKTE34CCX2XB1331 / 19928	FRC	7457	2011.08.22
752/2008	WK0SVKT24X9827078	FRC	7458	2011.08.22
753/2008	WSM00000005051301	FRC	3404T, MR79	2014.02.19
754/2008	WSM00000005051028	FRC	3404T, MR79	2014.03.13
755/2008	WDB6763181K283667 / 94/C0204-001	FNA	7459	2011.08.26
757/2008	YS2P6X20001264961 / 33620	FRC	7461	2011.08.26
758/2008	WDB9502041K228651 / 40481	FRC	7462	2011.08.26
759/2008	WDB9505351L352977 / 11006778	FNA/X	7463, 4152, M548	2014.08.20
760/2008	ZCFA1ED0382545105 / 11003008	FRC	7464, 4560, M572	2014.08.12
761/2008	ZCFA1ED0382545241 / 11003048	FRC	7465, 4560, M572	2014.08.12
762/2008	ZCFA1ED0382545474 / 11003018	FRC	7466, 4560, M572	2014.08.12
763/2008	ZCFA1ED0382545598 / 11002968	FRC	7467, 4560, M572	2014.08.12
764/2008	ZCFA1ED0382545239 / 11002988	FRC	7468, 4560, M572	2014.08.12
765/2008	ZCFA1ED0382545242 / 11002948	FRC	7469, 4560, M572	2014.08.12
766/2008	ZCFA1ED0382545104 / 11002998	FRC	7470, 4560, M572	2014.08.12
767/2008	ZCFA1ED0382545237 / 11003038	FRC	7471, 4560, M572	2014.08.12
768/2008	ZCFA1ED0382545475 / 11003028	FRC	7472, 4560, M572	2014.08.12
769/2008	ZCFA1ED0382545238 / 11002978	FRC	7473, 4560, M572	2014.08.12
770/2008	WSMS7480000444724	FRC	7474	2011.08.27
771/2008	VM3LVFS3F11R02719 / 01C0257-001	FRC	7475	2011.08.28
772/2008	WKESDR27051239695 / 33045	FRC	7476	2011.08.29
773/2008	VM3LVFS3FW3R08610 / 98C1950.001	FRC	7477	2011.01.01
774/2008	WSMS7480000434138	FRC	7478	2011.08.30
775/2008	VM3LVFS3F34R07447 / 03C1476/001	FRC	7482	2011.09.08
776/2008	WSM00000005006475	FRC	5137, 04 1234	2011.05.31
777/2008	WSM00000005003289	FRC	7479	2011.09.05
778/2008	WSMS7780000435662	FRC	7480	2011.09.06
779/2008	WSMS7480000447573	FRC	7481	2011.09.06
781/2008	IP-1845 / 94-96-FB3-5106	IR	7484	2014.09.02

782/2008	WKESD000000433664 / 1358	FRC	7485, 3392T, MR79	2014.06.30
783/2008	WKESD000000433663 / 1357	FRC	7486, 3392T, MR79	2014.06.30
784/2008	WKESD000000433659 / 1353	FRC	7487, 3392T, MR79	2014.06.30
785/2008	WKESD000000433657 / 1351	FRC	7488, 3392T, MR79	2014.06.30
786/2008	WSM00000005054240	FRC	05 1248, MR79	2014.06.02
787/2008	WSM00000005054237	FRC	05 1248, MR79	2014.06.02
788/2008	WSM00000005054232	FRC	05 1248, MR79	2014.05.02
789/2008	WSM00000005054231	FRC	05 1248, MR79	2014.05.02
790/2008	WSM00000005041238	FRC	7489, 3404T, M523	2014.03.14
791/2008	WSM00000005041176	FRC	7490, 07 1328, MR79	2014.01.14
792/2008	WSM00000005041178	FRC	7491, 07 1328, MR79	2014.01.14
793/2008	WSM00000005054250	FRC	08 1348, MR79	2014.04.21
794/2008	WSMS7780000445697	FRC	7498	15.09.2011
795/2008	WPI0100080 / 401018	FRC	7499	2010.05.12
798/2008	WSMS7780000416790	FRC	7502	2011.09.08
799/2008	WSM00000005054233	FRC	05 1248, MR79	2014.05.02
800/2008	WSM00000005054234	FRC	05 1248, MR79	2014.05.02
801/2008	WSM00000005054235	FRC	05 1248, MR79	2014.05.02
802/2008	WSM00000005054236	FRC	05 1248, MR79	2014.06.02
803/2008	WSM00000005054238	FRC	05 1248, MR79	2014.06.02
804/2008	WSM00000005054239	FRC	05 1248, MR79	2014.06.02
805/2008	WSM00000005054241	FRC	05 1248, MR79	2014.06.02
806/2008	VM3LVFS3EX1R09884 / 99/C1831-002	FRC	7493	2011.09.10
807/2008	VM3LVFS3EX1R09756 / 99/C1831-001	FRC	7494	2011.09.10
808/2008	WK0SVKT24X9828344	FRC	7495	2011.09.10
809/2008	VM3LVFS3EX1R09442 / 99/C1186-003	FRC	7496	2011.09.10
810/2008	WK0SVKT24X9828353	FRC	7497	2011.05.18
812/2008	WKESDR27011378084 / 26767	FRC	7503	2011.09.18
814/2008	WSMS7480000437532	FRC	7505	2011.09.18
815/2008	WSMS7480000459587	FRC	7506	2011.09.19
816/2008	XL9DT3339X0017037 / 4836-25-9903	FRC	7508	2011.09.13
817/2008	WSMS7480000437736	FRC	7509	2011.09.23
818/2008	WKOSVKT24X9828349	FRC	7507	2011.09.22
819/2008	WSM00000005003089	FRC	3338T, MR79	2011.04
820/2008	VM3LVFS3EV1A06484 / 97/C1747-004	FRC	7510	2010.02.28
822/2008	VM4C381BRXA004801	FRC	7512	2011.09.13
823/2008	08-133	RRC	7511	2014.09.12
824/2008	WKOSVKT24X9828345	FRC	7513	2011.05.05
825/2008	SUDNS1CTZ85018086 / 11011518	FRC	7514, 4838, MR79	2014.09.30
826/2008	WDB9702551L367385 / 11006768	FNA/X	7515, 4968, M538	2014.08.31
827/2008	WSMS7480000437735	FRC	7516	2011.09.25
828/2008	WKESDR27041204568 / 29.957	FRC	3285T, M576	2010.07
829/2008	WSM00000005018382	FRC	7517, 3348T, MR81	2012.08.03
830/2008	WSM00000005018384	FRC	7518, 3348T, MR81	2012.08.03
831/2008	VM3LVFS3F41R09005 / 04C0809/008	FRC	5237.2, BX4829, MR79	04.2010
832/2008	VFKTF34C1V3RB3246 / 21197	FRC	7519	2011.10.02
833/2008	VM4CD381JXA000826	FRC	7520	2011.10.03
834/2008	WSMS7480000446408	FRC	7521	2011.10.03
835/2008	VM3LVFS3FX1R00619 / 99C1653.001	FRC	7522	2011.10.01
836/2008	WSMS7480000444760	FRC	7523	2011.10.01
837/2008	WSMS7480000404143	FRC	7524	2010.06.04
838/2008	YE730PF38XH200468 / F8001.630638	FRC	7525	2011.10.06
840/2008	WSMS7780000454633	FRC	7527	2011.10.02
841/2008	XLDTXZ33900041659 / 43225	FRC	7528	2011.04.20
842/2008	WSMS7480000436440	FRC	7529	2011.10.03
843/2008	WSM00000005055313	FRC	08 1348, MR79	2014.04.21
844/2008	WSMS7480000446402	FRC	7530	2011.10.07
845/2008	WSMS7480000446414	FRC	7531	2011.10.07
846/2008	WSMS7480000446401	FRC	7532	2011.10.07
847/2008	WSMS7480000446413	FRC	7533	2011.10.07

848/2008	<b>WSMS7480000446415</b>	<b>FRC</b>	7534	2011.10.07
849/2008	WKESD000000433660 / <b>1354</b>	<b>FRC</b>	7535, 3392T, MR79	2014.05.31
850/2008	WKESD000000433661 / <b>1355</b>	<b>FRC</b>	7536, 3392T, MR79	2014.06.30
851/2008	WKESD000000433662 / <b>1356</b>	<b>FRC</b>	7537, 3392T, MR79	2014.07.31
852/2008	VM3LVFS3F26R04537 / <b>02C0454.003</b>	<b>FRC</b>	7538	2011.10.07
853/2008	VM3LVFS3FY1R01071 / <b>00C0336-004</b>	<b>FRC</b>	7539	2011.10.07
854/2008	VM3LVFS3EW3A08283 / <b>98/C1456-009</b>	<b>FRC</b>	7540	2010.11.30
855/2008	<b>WKOSVKT24X9828346</b>	<b>FRC</b>	7542	2011.05.04
856/2008	<b>WKOSVKT24X9828348</b>	<b>FRC</b>	7543	2011.05.10
857/2008	VM4CD381J3A011978 / <b>58307</b>	<b>FRC</b>	7544	2011.10.10
858/2008	VM3LVFS3E21R10810 / <b>02C2064.001</b>	<b>FRC</b>	7545	2011.11.08
859/2008	WFDFLT33511000381 / <b>102002</b>	<b>FRC</b>	7546	2011.10.14
860/2008	<b>WSMS7480000431648</b>	<b>FRC</b>	7547	2011.09.28
861/2008	SUDNS1CTZ85018087 / <b>11011888</b>	<b>FRC</b>	7548, 4838, MR79	2014.10.31
862/2008	WDB9702751L354039 / <b>11004188</b>	<b>FNA/X</b>	7549, 4152, M589	2014.07.31
863/2008	ZCFA1ED0382545240 / <b>11003058</b>	<b>FRC</b>	7550, 4560, M572	2014.10.31
864/2008	ZCFA1ED0392545849 / <b>11003068</b>	<b>FRC</b>	7551, 4560, M572	2014.10.31
865/2008	ZCFA1ED0392545850 / <b>11003078</b>	<b>FRC</b>	7552, 4560, M572	2014.10.31
866/2008	ZCFA1ED0392545599 / <b>11003088</b>	<b>FRC</b>	7553, 4560, M572	2014.10.31
867/2008	ZCFA1ED0392545847 / <b>11003178</b>	<b>FRC</b>	7554, 4560, M572	2014.10.31
868/2008	ZCFA1ED0392545969 / <b>11003168</b>	<b>FRC</b>	7555, 4560, M572	2014.10.31
869/2008	ZCFA1ED0392545968 / <b>11003158</b>	<b>FRC</b>	7556, 4560, M572	2014.10.31
870/2008	ZCFA1ED0392545967 / <b>11003148</b>	<b>FRC</b>	7557, 4560, M572	2014.10.31
871/2008	ZCFA1ED0392545846 / <b>11003138</b>	<b>FRC</b>	7558, 4560, M572	2014.10.31
872/2008	ZCFA1ED0392545966 / <b>11003128</b>	<b>FRC</b>	7559, 4560, M572	2014.10.31
873/2008	ZCFA1ED0392545848 / <b>11003118</b>	<b>FRC</b>	7560, 4560, M572	2014.10.31
874/2008	ZCFA1ED0392545851 / <b>11003108</b>	<b>FRC</b>	7561, 4560, M572	2014.10.31
875/2008	ZCFA1ED0392545600 / <b>11003098</b>	<b>FRC</b>	7562, 4560, M572	2014.10.31
876/2008	ZCFA1ED0392545970 / <b>11003188</b>	<b>FRC</b>	7563, 4560, M572	2014.10.31
877/2008	<b>WSMS7480000446105</b>	<b>FRC</b>	7564	2011.10.13
878/2008	W09X99335RHS09798 / <b>7447</b>	<b>FNA</b>	7565	2011.10.13
879/2008	<b>WSMS7480000453202</b>	<b>FRC</b>	7566	2011.10.14
881/2008	<b>WKOSVKT24Y0261410</b>	<b>FRC</b>	7568	2011.10.14
882/2008	<b>WSMS7780000443137</b>	<b>FRC</b>	7569	2011.10.15
884/2008	VM4CD381GWA000075 / <b>40634</b>	<b>FRC</b>	7571	2010.09.07
885/2008	943497 / <b>F6-97-9822</b>	<b>FNA</b>	7572	2011.10.15
886/2008	<b>WSM00000005041190</b>	<b>FRC</b>	7573, 3319T, MR79	2014.02.15
887/2008	<b>WK0SVKT24X9838361</b>	<b>FRC</b>	7574	2011.07.26
889/2008	VM3LVFS3F21R04893 / <b>02C1099.001</b>	<b>FRC</b>	7575	2011.10.20
890/2008	<b>WSM00000005019356</b>	<b>FRC</b>	3374T, MR79	2012.09
891/2008	VM3LVFS3EX4R09792 / <b>99/C1902-001</b>	<b>FRC</b>	7576.	2011.10.21
892/2008	ZCFC35A8085763211 / <b>11003588</b>	<b>FNA/X</b>	7577, 4968, M517	2014.09.30
893/2008	ZCFC50A2085727156 / <b>11006098</b>	<b>FRC/X</b>	7578, 5547, M517	2014.06.30
894/2008	WSMS7480000076014 / <b>05-27251</b>	<b>FRC</b>	7579	2011.10.21
896/2008	WKESD000000433658 / <b>1352</b>	<b>FRC</b>	7580, 3392T, MR79	2014.07.31
897/2008	WKESD000000433655 / <b>1349</b>	<b>FRC</b>	7581, 3392T, MR79	2014.05.31
898/2008	WKESD000000433656 / <b>1350</b>	<b>FRC</b>	7582, 3392T, MR79	2014.07.31
900/2008	YV2J4CHC13B325490 / <b>208240</b>	<b>FRC</b>	7585	2011.10.21
901/2008	WKESDR27011387122 / <b>25796</b>	<b>FRC</b>	7586	2011.10.22
902/2008	WKESDR27011387128 / <b>25788</b>	<b>FRC</b>	7587	2011.10.21
903/2008	<b>WSM00000005024939</b>	<b>FRC</b>	7588, 3319T, MR79	2013.03.09
904/2008	WK0S0002400059358 / <b>11018877</b>	<b>FRC</b>	7590, 4838, M576	2013.11.13
905/2008	VM3LVFS3EX4R09797 / <b>99/C1902.006</b>	<b>FRC</b>	7591	2011.10.25
906/2008	<b>WSMS7480000419163</b>	<b>FRC</b>	7592	2011.03.30
907/2008	VM3LVFS3FW1R00272 / <b>98/C1725-009</b>	<b>FRC</b>	7593	2010.11.01
908/2008	VM3LVFS3EX4R09799 / <b>99/C1902-008</b>	<b>FRC</b>	7594	2010.10.29
909/2008	<b>WSM00000005002447</b>	<b>FRC</b>	7595	2011.10.29
910/2008	<b>WSM00000005051300</b>	<b>FRC</b>	7596, 3404T, MR79	2014.03.19
911/2008	<b>WSM00000005028664</b>	<b>FRC</b>	7597, 3390T, MR79	2013.07.02
913/2008	WKESDR27011499547 / <b>29228</b>	<b>FRC</b>	7599	2011.10.31
914/2008	<b>WSM00000005052304</b>	<b>FRC</b>	07 1328, M576	2014.03.03

915/2008	WSM00000005028711	FRC	7600, 07 1303, MR79	2013.05.14
916/2008	WSM00000005041263	FRC	7601, 08 1348, MR79	2014.04.11
917/2008	WSM00000005006478	FRC	7602	2011.10.29
918/2008	VM3LVFS3F21R05366 / 02C1649.004	FRC	7604	2011.10.29
919/2008	WKESDR27011158494 / 342-2001	FRC	7605	2011.10.31
920/2008	WKESDR27071303198 / 37412	FRC	7606, 3290T, M509	2013.12.31
921/2008	WSMS7480000437528	FRC	7607	2011.10.30
923/2008	WSMS7780000438017	FRC	7609	2011.11.03
924/2008	VM3LVFS3EX4R09793 / 99/C1902-002	FRC	7610	2011.10.18
925/2008	VM3LVFS3FX1R00688 / 99/C1956-001	FRC	7611	2011.10.31
926/2008	WSMS7480000442008	FRC	7612	2011.11.04
927/2008	WSMS7480000446849	FRC	7613	2011.11.04
928/2008	WSMS7480000438312	FRC	7614	2011.11.04
929/2008	WSMS7780000441469	FRC	7615	2011.10.13
930/2008	WSM00000005054095	FRC	08 1348, MR79	2014.04.21
931/2008	WSM00000005019351	FRC	3374T, MR79	2012.09
932/2008	WSM00000005019352	FRC	3374T, MR79	2012.09
933/2008	WSM00000005055914	FRC	3421T, MR79	2014.06.04
934/2008	WSMS7480000458191	FRC	7617	2011.11.06
935/2008	WSMS7480000406101	FRC	7618	2010.12.01
936/2008	WSM00000005021788	FRC	7619, 06 1286, MR79	2012.10.31
937/2008	WSM00000005049783	FRC	07 1328, MR79	2014.03.03
938/2008	VV1SR3ESAFLL72077 / 210286	FRC	7620	2011.11.06
939/2008	WSMS7480000444477	FRC	7621	2011.11.06
940/2008	WMAH21ZZ95M400582 / 02C0107.002	FRC	7622	2011.11.07
941/2008	1026298 / F2-98-0533	FNA	7623	2011.11.05
942/2008	WSMS7480000441833	FRC	7624	2011.11.05
943/2008	WSMS7480000435351	FRC	7625	2011.11.08
944/2008	WSMS7480000411020	FRC	7627	2010.08.31
946/2008	WSMS7480000442025	FRC	7628	2011.11.07
947/2008	WKOSVKT24W9806229	FRC	7629	2010.07.14
949/2008	WSMS7480000084127	FNA	7631	2011.11.07
950/2008	WMAH06ZZ25M424273	FNA	7632	2014.11.03
951/2008	WSM00000005041174	FRC	07 1328, MR79	2014.01.09
952/2008	WSM00000005041175	FRC	07 1328, MR79	2014.01.09
953/2008	VF622ACA0A0017210 / 910288	FNA	7633	2011.11.13
954/2008	WSMS7480000406112	FRC	7635	2011.04.08
955/2008	VM3LVFS3EW1A07526 / 98/C1219-001	FRC	7636	2010.12.31
956/2008	WSMS7480000431690	FRC	7637	2011.09.03
957/2008	WSMS7480000450581	FRC	7638	2011.11.15
958/2008	SMSS7780000700410	FRC	7639	2011.11.15
959/2008	WSMS7480000439108	FRC	7640	2011.11.15
961/2008	WSM00000005050845	FRC	08 1348, M576	2014.04.14
962/2008	WSM00000005050848	FRC	08 1348, M576	2014.04.30
963/2008	WSM00000005050849	FRC	08 1348, M576	2014.04.29
964/2008	WSM00000005031600	FRC	7642, 07 1303, MR79	2013.07.06
965/2008	WSM00000005028730	FRC	7643, 3390T, MR79	2013.09.04
966/2008	WK0S0002400084349	FRC	7644, 3365T, M576	2013.12.19
967/2008	ZCFA1TJ0382521330 / 11004268	FRC	7645, 6652, MR89	2014.05.31
968/2008	ZCFA1TJ0382520891 / 11004258	FRC	7646, 6652, MR89	2014.05.31
969/2008	WKESDR27041210291 / 30321	FRC	7647	2011.11.18
970/2008	WSMS7480000439394	FRC	7648	2011.11.10
971/2008	WK0S0002400111738	FRC	7649, 3365T, M576	2014.08.13
972/2008	WSM00000005054266	FRC	3421T, MR79	2014.06.03
973/2008	VM4C381BRXA004802	FRC	7650	2011.11.18
974/2008	WSMS7480000440047	FRC	7651	2011.11.20

975/2008	VSRSF3C97ML042904 / 15782	FRC	7652	2010.12.31
976/2008	VM3LVFS3E21R10692 / 02C0867.009	FRC	7653	2011.11.18
977/2008	WSMS7480000438300	FRC	7654	2011.11.19
978/2008	WKESDR27011388055 / 27977	FRC	7655	2011.11.20
979/2008	WSMSK024000057684	FRC	7656	2010.12.31
980/2008	VM3LVFS3FY1R01020 / 00C0126-015	FRC	7657	2011.11.21
981/2008	WSMS7480000444383	FRC	7658	2011.11.24
982/2008	WSMS7480000414660	FRC	7659	2010.12.09
983/2008	WSM00000005015380	FRC	7660, 3319T, 3150K	2012.04.30
984/2008	WSM00000005015381	FRC	7661, 3319T, MR79	2012.04.30
985/2008	WSMS7480000414866	FRC	7662	2011.11.26
986/2008	WSM00000005055982	FRC	3421T, MR79	2014.05.28
987/2008	VM4CD382G2A021435 / 55488	FRC	7663	2011.12.01
988/2008	WSMS748000088320	FNA	7664	2011.11.20
989/2008	WSMS7480000416519	FRC	7665	2011.01.29
990/2008	GA3FLS9316 / 8677	FNA	7666	2011.11.26
991/2008	WDB6584181K185518 / 904164	FRC	7667	2011.04.30
992/2008	XL9HTFD0139067002 / 01.002.D3040	FRC	7668	2011.11.29
993/2008	VM3LVFS3ET3R05099 / 96/C1500-001	FNA	7669	2011.11.29
994/2008	VM3LVFS3ET1R04706 / 96/C0816-016	FNA	7670	2011.11.29
995/2008	WSMS7780000406154	FRC	7671	2010.12.31
996/2008	WKESDR27011264547 / 35517	FRC	7672	2011.11.29
997/2008	WSMS7480000434998	FRC	7673	2011.11.29
998/2008	W09001335WMT35056 / 35056	FRC	7674	2010.05.08
999/2008	WKESDR27011262274 / 25107	FRC	7675	2011.11.28
1000/2008	W09111111X2S24886	FRC	7676	2011.11.16
1001/2008	4112125486	FNA	7677	2011.11.28
1002/2008	WSMS7480000442057	FRC	7678	2011.11.29
1003/2008	WKESDF27000145898 / 24195	FRC	7679	2011.11.28
1004/2008	VM4CD382G2A021436 / 55489	FRC	7683	2011.12.03
1005/2008	SW9PT122C21CH3924 / 02C1510.001	FRC	7684	2011.11.26
1006/2008	YS2P6X20001283311 / 02C1511.001	FRC	7685	2011.11.26
1007/2008	YS2P6X20001283314	FRC	7686	2011.11.26
1008/2008	SW9PT122C21CH3925	FRC	7687	2011.11.26
1009/2008	SUDNS1CTZ85018161 / 11013258	FRC	7688, 4838, M602	2014.12.31
1010/2008	VF656ANA000012900 / 11012298	FNA/X	7689, 6652, M486	2014.11.30
1011/2008	VF656ANA000012899 / 11012288	FNA/X	7690, 6652, M486	2014.11.30
1012/2008	VM3LVFS3EY1R10341 / 00C1273.001	FRC	7691	2011.12.05
1014/2008	WKESDR27011263380 / 25486	FRC	7693	2011.12.05
1015/2008	WBL22458WTR195390	FRC	7694	2011.12.05
1016/2008	ZGCSFT63UYT050774 / 030BOT05.3241	FRC	7695	2011.12.05
1017/2008	WSM00000005003105	FRC	7696	2011.12.05
1018/2008	80552	FRB	7697	2010.12.31
1019/2008	WDB6763381K322091	FNA	7698	2011.12.08
1020/2008	VM3LVFS3EX4R09795 / 99/C1902-004	FRC	7699	2011.10.30
1021/2008	VF644ACA000006006	FNA	7700	2011.12.11
1022/2008	VF622CXA000100577 / 103054	FRC	7701	2011.12.12
1023/2008	WSMS7480000444758	FRC	7702	2011.12.11
1024/2008	WKESDR27011159599 / 24817	FRC	7703	2011.12.16
1026/2008	WSMS748000097303	FRC	7705	2010.05.20
1027/2008	VM4C381BRWA004547	FRC	7706	2010.11.04
1029/2008	WK0SVKT24W0223997	FRC	7708	2011.02.08
1031/2008	YA5B304A939M53598 / 99561	FRC	7710	2011.08.04
1033/2008	YB4A0FZ3390210491 / 2002192	FRC	7712	2011.12.13
1034/2008	YB4A0FZ3390109195 / 2001521	FRC	7713	2011.12.14
1035/2008	82135/ 97673	FNA	7714	2011.12.13

<b>1036/2008</b>	<b>YB4A0FZ3390109194 /2001522</b>	<b>FRC</b>	7715	2011.12.14
<b>1037/2008</b>	<b>YE730PF38XH200893 /F9001.450929</b>	<b>FRC</b>	7716	2011.12.14
<b>1038/2008</b>	<b>WSMS7780000440618</b>	<b>FRC</b>	7717	2011.12.17
<b>1040/2008</b>	<b>VM3LVFS3ET4A04237 / 96C/0080-003</b>	<b>FNA</b>	7718	2011.12.22
<b>1041/2008</b>	<b>WSMS7480000436298</b>	<b>FRC</b>	7722	2011.12.17
<b>1042/2008</b>	<b>WKESDR27011153769</b>	<b>FRC</b>	7723	2011.12.19
<b>1043/2008</b>	<b>WDB9506051K806435 / 02-06521</b>	<b>FRC</b>	7719	2011.12.31
<b>1044/2008</b>	<b>WKESDR27051201852</b>	<b>FRC</b>	7728	2011.11.21
<b>1045/2008</b>	<b>VM3LVFS3F31A06832 / 03C0482/001</b>	<b>FRC</b>	7729	2011.12.22
<b>1046/2008</b>	<b>WSMS7480000452697</b>	<b>FRC</b>	7730	2011.12.22
<b>1047/2008</b>	<b>WSMS7480000443802</b>	<b>FRC</b>	7731	2011.12.27
<b>1048/2008</b>	<b>WSMS7480000447006</b>	<b>FRC</b>	7732	2011.12.27
<b>1049/2008</b>	<b>WSMS7480000447005</b>	<b>FRC</b>	7733	2011.12.27
<b>1050/2008</b>	<b>WSMS7780000084401</b>	<b>FNA</b>	7727	2011.12.30
<b>1051/2008</b>	<b>WSMS7480000438313</b>	<b>FRC</b>	7734	2011.12.29
<b>1052/2008</b>	<b>WSMS7480000416513</b>	<b>FRC</b>	7735	2011.12.29
<b>1053/2008</b>	<b>WK0S0002400057578</b>	<b>FRC</b>	7721	30.12.2011
<b>1054/2008</b>	<b>WKS0002400057580</b>	<b>FRC</b>	7306, 3365T, M576	02.06.2012
<b>1055/2008</b>	<b>VM3LVFS3E21R10816 / 02C2153.001</b>	<b>FRC</b>	7736	2011.11.29
<b>1056/2008</b>	<b>WSM00000005054203</b>	<b>FRC</b>	08 1348, MR79	2014.04.21
<b>1057/2008</b>	<b>WK0SVKT24X9828352</b>	<b>FRC</b>	7741	2011.05.31
<b>1058/2008</b>	<b>WKESDR27041210288</b>	<b>FRC</b>	7742	2011.12.30
<b>1059/2008</b>	<b>WSMS7480000082312</b>	<b>FNA</b>	7743	2011.12.30
<b>1060/2008</b>	<b>VM3LVFS3F21R05002 / 02C1278.001</b>	<b>FRC</b>	7770	2011.10.29
<b>1061/2008</b>	<b>WSM00000005003129</b>	<b>FRC</b>	7786	2011.12.18