

Spis świadectw wydanych przez COCH w 2009 r.

Numer świadectwa	Numer identyfikacyjny (punkt 3 świadectwa)	Uznaje się jako (punkt 6 świadectwa)	Nr protokołu badań (punkt 7.2.3 świadectwa)	Data ważności świadectwa (pkt.8)
1	2	3	4	5
001/2009	WSMS7780000445329	FRC	7744	02.01.2012
002/2009	WSM00000005028618	FRC	7745, 3390T, MR79	28.05.2013
003/2009	WDB9302031L402850 / 11011558	FRC	7746, 6652, MR92	30.11.2014
004/2009	VF3YDDMAC11580421 / 11012448	FNA/X	7747, 6653, M486	30.11.2014
005/2009	ZCFC50A2085751419 / 11013308	FNA/X	7748, 6653, M529	30.11.2014
006/2009	WMAN14ZZ59Y227861 / 11006818	FRC	7749, 7328, M593	31.10.2014
007/2009	WSMS7480000417003	FRC	7750	10.06.2011
008/2009	WMAT372414W030247 / 158441	FNA	7720	07.01.2015
009/2009	WSMS748000067526	FNA	7751	02.01.2012
010/2009	WSMS7480000416512	FRC	7752	02.01.2012
011/2009	ZCBF111EFT0P54184 / 8378B960331	FNA	5385	21.03.2012
012/2009	VM3LVFS3FX1R00629 / 00C1654.004	FRC	7754	03.01.2012
013/2009	WKOSVKT24W0223770	FRC	7759	03.01.2012
014/2009	WSMS7780000086997	FNA	7760	03.01.2012
015/2009	WSMS748000081302	FNA	7761	03.01.2012
016/2009	VAVSAF3387H242816 / 25.790	FRC	7762, T-2003/1692, M576	31.01.2013
017/2009	WSM00000005006477	FRC	7766	07.01.2012
018/2009	WSM00000005028740	FRC	7767, 3390T, MR79	03.08.2013
019/2009	WSMS7480000455245	FRC	7772	07.01.2012
020/2009	WSMS7480000438946	FRC	7771	09.01.2012
021/2009	VM3LVFS3FY1R02018 / 00C2600.001	FRC	7740	08.01.2012
022/2009	VM3LVFS3ET6R05192 / 00C3530.001	FRC	7774	08.01.2012
023/2009	WK0SVKT24W9892029	FRC	7775	19.03.2010
024/2009	VFKTF34C1W3RB1558 / 98/C0004-005	FRC	7776	31.12.2010
025/2009	VM3LVFS3EX1R08777 / 98/C2208-001	FRC	7777	15.02.2011
026/2009	VM3LVFS3F81R18414 / 08C0020/004	FRC	7778, BX5138, M472	28.02.2014
027/2009	WSM00000005033986	FRC	7780, 07 1317, 3074K	09.10.2013
028/2009	WKESDR27011389179 / 28.405	FRC	7780	08.01.2012
029/2009	WKESDR27011389178 / 27.488	FRC	7781	08.01.2012
030/2009	6752	FNA	7782	08.01.2012
031/2009	WSMS7480000443052	FRC	7783	09.01.2012
032/2009	WKESDR27061279169 / 36.023	FRC	7784, 3336T, MR79	28.07.2012
033/2009	WSMS7480000458974	FRC	7785	10.01.2012
034/2009	VM3LVFS3F31R06686 / 03C0239.006	FRC	7789	12.01.2012
035/2009	WSM00000005040002	FRC	05 1248, MR79	01.07.2014
036/2009	WSM00000005015881	FRC	05 1248, M576	06.2012
037/2009	WSMS7480000083106	FNA	7755	13.01.2012
038/2009	WSMS7480000095917	FNA	7756	13.01.2012
039/2009	WSMS7480000450442	FRC	7757	13.01.2012
040/2009	WSMS7480000437531	FRC	7758	13.01.2012
041/2009	WSM00000005009304	FRC	7793	13.01.2012
042/2009	WSMS7480000447139	FRC	7773	13.01.2012
043/2009	WSM00000005032197	FRC	7794, 3390T, MR79	09.11.2013
044/2009	VM3LVFS3FY1R00845 / 99/C2595-001	FRC	7765	13.01.2012
045/2009	VM3LVFS3F44R08197 / 04C0816/002	FRC	7787	14.01.2012
046/2009	XLER6X20005214324 / 11013948	FRC	7792, 6652, MR71	31.12.2014
047/2009	WMAT37ZZZYW040821 / 434255	FRC	7768	13.01.2012
048/2009	WK0AWE01810781686 / U029/01	FRC	7769	13.01.2012
049/2009	VM4CD382G2A021438 / 55491	FRC	7795	15.01.2012
050/2009	WKESDR27011274808 / 26548	FRC	7797	19.01.2012
051/2009	WK0S0002400111732	FRC	0716, M576	28.02.2014
052/2009	WKESDR27011157464 / 24736	FRC	7796	20.01.2012
054/2009	VAVSAF3383H181096 / 5587	FRC	7801	22.01.2012
055/2009	WSMS7780000431746	FRC	7800	31.08.2011
056/2009	VM4CD382G2A021439 / 55492	FRC	7804	23.01.2012
057/2009	VV1LTF3E0SNX86005 / 21530	FRC	7805	24.04.2010

058/2009	VM4C382DRTA002183 / 33821	FNA	7806	21.01.2012
059/2009	WSM00000005004064	FRC	7827	27.01.2012
060/2009	VM3LVFS3ES1R03588 / 95.C1048.002	FNA	7483	04.09.2011
061/2009	WSMS7480000450179	FRC	4260.7, 03 1143, MR79	03.04.2009
062/2009	WSMS7780000095598	FRC	7608	17.12.2009
064/2009	VM4CD382G1A020440 / 50700	FRC	7813	28.01.2012
065/2009	WSMS7780000433534	FRC	7814	23.01.2012
066/2009	MW1038214	FNA	7815	23.01.2012
067/2009	WMAT376312W035317 / 2229103	FNA	7816	23.01.2012
068/2009	WSMA7520000065261	FNA	7817	23.01.2012
069/2009	WSMS7480000092392	FNA	7818	24.01.2012
070/2009	WSMS7780000099006	FNA	7819	24.01.2012
071/2009	MW1036899	FNA	7820	24.01.2012
072/2009	WSMS7480000443907	FRC	7821	24.01.2012
073/2009	YA5B304A739B52261 / 98203	FRC	7822	31.12.2010
074/2009	WK0SVKT2410283713	FRC	7823	23.01.2012
075/2009	WSM00000005011016	FRC	7825	27.01.2012
076/2009	WK0SVKT24V0289537	FRC	7826	31.12.2009
077/2009	WSMS7780000403369	FRC	7828	14.05.2010
078/2009	VM3LVFS3EV1R06584 / 97/C1889-002	FRC	7829	31.12.2009
079/2009	WSMS7480000448526	FRC	7830	30.01.2012
080/2009	WSMS7480000448525	FRC	7831	30.01.2012
081/2009	WSMS7480000448788	FRC	7832	30.01.2012
082/2009	WSMS7480000448543	FRC	7833	30.01.2012
083/2009	WSMS7480000084942	FNA	7835	30.01.2012
084/2009	WSMS7780000401863	FRC	7836	31.12.2010
085/2009	WSMS7780000445459	FRC	7837	02.02.2012
086/2009	WSM00000005018383	FRC	7838	04.02.2012
087/2009	WSM00000005018292	FRC	7839	28.01.2012
088/2009	WK0SVKT2420297605	FRC	7840	04.02.2012
089/2009	WK0SVKT24R2141813	FRC	7841	28.05.2011
090/2009	WKESDR27061264962 / 35177	FRC	7842	04.02.2012
091/2009	VM3LVFS3F41R09005 / 04C0809/008	FRC	5237.2, BX4829, MR79	04.2010
092/2009	WSM00000005003014	FRC	5238, 3252T, 3150K	07.2011
093/2009	WSMS7780000435005	FRC	6174	18.02.2010
094/2009	WSM00000005012112	FRC	05 1269, MR79	01.2012
095/2009	VM3LVFS3F21R04894 / 02C1099.002	FRC	7101	02.04.2011
096/2009	WSM00000005012117	FRC	05 1269, MR79	01.2012
097/2009	WSM00000005012118	FRC	05 1269, MR79	01.2012
098/2009	WSM00000005028664	FRC	7597, 3390T, MR79	02.07.2013
099/2009	WSM00000005010430	FRC	05 1269, MR79	11.2011
100/2009	VK1S338DHRF000729 / 200116	FRC	7852	06.02.2012
101/2009	WSMS7480000450223	FRC	5237, 03 1161, 3150K	09.2009
102/2009	WSMS7480000434789	FRC	7764	09.02.2012
103/2009	VM3LVFS3F31R07399 / 03C1405.002	FRC	7854	05.02.2012
104/2009	WSMS7480000449034	FRC	7855	09.02.2012
105/2009	WSMS7780000432732	FRC	7807	14.01.2012
106/2009	WSMS7480000449155	FRC	7856	31.01.2012
107/2009	WSMS7480000488521	FRC	7857	03.02.2012
108/2009	VM4CD381J3A011982 / 58311	FRC	7858	09.02.2012
109/2009	W091513351HS09092 / 059UG3906	FRC	7859	09.02.2012
110/2009	VM3LVFS3F21R04964 / 02C1196.021	FRC	7860	09.02.2012
111/2009	WSMS7780000088790	FRC	7861	09.06.2009
112/2009	WK0S0002400084492	FRC	7862	05.02.2012
113/2009	WSMS7480000450691	FRC	7864	09.02.2012
114/2009	WK0S0002400084348	FRC	7865, R2033/319, M576	19.12.2013
115/2009	VFKTF34C1T3RB1464 / 33901	FRC	7866	09.02.2012
116/2009	VM4CD382G1A020174 / 48499	FRC	7863	11.02.2012
117/2009	VF656ANA000012574 / 11007798	FNA/X	7867, 6653, M486	31.10.2014
118/2009	VF644AHL000003981 / 11012248	FRC/X	7868, 7328, M538	31.10.2014
119/2009	VF644AHL000003866 / 11007808	FRC/X	7869, 7328, M538	31.10.2014

120/2009	ZCFC50A2085756062 / 11012088	FRC/X	7870, 5547, M517	31.12.2014
121/2009	VF656ANA000011249 / 11007788	FNA/X	7871, 6653, M486	31.10.2014
122/2009	VM3LVFS3E21R10698 / 02C0867.015	FRC	7873	09.02.2012
123/2009	VM3LVFS3F21R04966 / 02C1196.023	FRC	7874	12.02.2012
124/2009	VF644ACA000015568 / 11015156	FNA/X	7875	13.02.2012
125/2009	WSMS7480000449033	FRC	7876	13.02.2012
126/2009	WGA30KS27VL242806	FNA	7872	12.02.2012
127/2009	SUDNS1DBZ81015965 / 11009468	FRC	7877, 4838, M602	28.02.2015
128/2009	WDB9061551N416157 / 11014088	FNA/X	7878, 6653, M486	28.02.2015
129/2009	WSMS7780000445279	FRC	7879	18.02.2012
130/2009	VV1F3FA3XSN110742 / C4 040	FRC	7763	09.01.2012
131/2009	XLEP4X20004386525 / 7120900	FRC	7880	31.12.2009
132/2009	VM3LVFS3F51A10468 / 04C2625/001	FRC	7882	21.02.2012
133/2009	WSM00000005003171	FRC	7883	05.02.2012
134/2009	WSM00000005012084	FRC	7884	05.02.2012
135/2009	WSM00000005031611	FRC	7885. 07 1310, MR79	25.09.2013
136/2009	WSMS7480000455787	FRC	7886	05.02.2012
137/2009	WSMS7480000448735	FRC	7887	14.02.2012
138/2009	SUDNS1DBZ81015969 / 11009478	FRC	7888, 4838, M602	28.02.2015
139/2009	XLD3142PL00031099 / 1521	FNA	7881	25.02.2015
140/2009	ZCFC50A2085756385 / 11014038	FRC/X	7894, 5547, M628	31.01.2015
141/2009	SUDNS1CTZ81016270 / 11025087	FRC	7895, M4838, M602	30.09.2014
142/2009	WSMS7480000432368	FRC	7891	31.12.2011
143/2009	WSMS7480000432398	FRC	7889	31.01.2012
144/2009	YE730PF38YH201312 / F9003E220958	FRC	7890	25.02.2012
145/2009	VM3LVFS3EX3R08897 / 99/C0223-002	FRC	7892	26.03.2011
146/2009	WKESDR27011159613 / 24759	FRC	7893	25.02.2012
147/2009	WSMS7480000433694	FRC	7896	26.02.2012
148/2009	WK0S0002400110114	FRC	7897, 3365T, M576	31.12.2014
149/2009	WSM00000005054259	FRC	3421T, MR79	20.05.2014
150/2009	WSMA7420000409873	FRC	7899	09.09.2010
151/2009	WSMS7480000447548	FRC	5201.8, 03 1165, M576	31.12.2010
152/2009	WK0S0002400084367	FRC	3365T, MR79	31.12.2013
153/2009	WK0S0002400110112	FRC	7902, 3365T, M576	20.03.2014
154/2009	WSMS7480000448515	FRC	7903	18.02.2012
155/2009	WSM00000005057901	FRC	05 1248, MR81	28.07.2014
156/2009	WSM00000005009860	FRC	03 1165, M576	10.2011
157/2009	WSM00000005016639	FRC	7907	21.02.2012
158/2009	WK0SVKT2450735494 / 60467	FRC	7908	23.02.2012
159/2009	VM3LVFS3F11R02313 / 01C3405.001	FRC	7909	24.02.2012
160/2009	WSMS7480000083391	FNA	7910	23.02.2012
161/2009	VM3LVFS3F71R17839 / 07C1586/007	FRC	7911, BX5193, M441	31.10.2013
162/2009	ZCFC35A8085743922 / 11012208	FNA/X	7912, 4561, M607	28.02.2015
163/2009	ZCFC35A8085744330 / 11012218	FNA/X	7913, 4561, M607	28.02.2015
164/2009	ZCFC35A8085744328 / 11012198	FNA/X	7914, 4561, M607	28.02.2015
165/2009	SUDNS1CTZ83017690 / 11004408	FRC	7915, 4838, M576	30.09.2014
166/2009	SUDNS1CTZ83017691 / 11004418	FRC	7916, 4838, M576	30.09.2014
167/2009	WSMS7480000450137	FRC	7917	28.02.2012
168/2009	WSMS7480000450134	FRC	7918	28.02.2012
169/2009	VM4CD382G3A021526 / 55494	FRC	7919	04.03.2012
170/2009	60669	FNA	7921	04.03.2012
171/2009	WSMS7480000444577	FRC	7922	04.03.2012
172/2009	WSMS7480000430631	FRC	7923	05.03.2012
173/2009	VF652AFA000011254 / 08.12.258	FRC/X	7924, 6453, 5056	31.12.2014
174/2009	WSMS7480000439389	FRC	7925	25.02.2012
175/2009	WSMS7480000432079	FRC	7926	31.12.2011
176/2009	VM3LVFS3F31R06684 / 03C0239.004	FRC	7927	02.03.2012
177/2009	WK0SVKT24Y0259855	FRC	7932	05.03.2012
178/2009	YV2A4B3CXWA273420 / 6129	FNA	7933	05.03.2012
179/2009	WSMS7480000439618	FRC	7934	06.03.2012
180/2009	WSMS7480000439402	FRC	7938	04.03.2012

181/2009	<b>WSMS7780000445678</b>	<b>FRC</b>	7943	06.03.2012
182/2009	<b>VM4CD382H7A024189</b>	<b>FRC</b>	7942	04.03.2012
183/2009	<b>WSMS7480000448531</b>	<b>FRC</b>	7941	05.03.2012
184/2009	<b>WK0SVKT24W9892776</b>	<b>FRC</b>	7944	02.02.2010
185/2009	<b>WSMS7480000455572</b>	<b>FRC</b>	7946	07.03.2012
186/2009	<b>WSMS7480000449749</b>	<b>FRC</b>	7947	09.03.2012
187/2009	TRGSA1335VD120354 / <b>8658</b>	<b>FNA</b>	7948	09.03.2012
188/2009	VM4CD382G3A021527 / <b>55495</b>	<b>FRC</b>	7949	10.03.2012
189/2009	<b>VF622CVA000110979</b>	<b>FRC</b>	7935	06.03.2012
190/2009	<b>VM3LVFS3F54R10901</b>	<b>FRC</b>	7936	06.03.2012
191/2009	VK1ST39WGPA500488 / <b>206197</b>	<b>FRC</b>	7937	06.03.2012
192/2009	YS2R6X20002012491 / <b>11016545</b>	<b>FRC</b>	7939	10.03.2012
193/2009	SUDPC4ZTZ59007915 / <b>11016555</b>	<b>FRC</b>	7940	10.03.2012
194/2009	VM3LVFS3EW1A07496 / <b>98/C0807.002</b>	<b>FRC</b>	7945	30.06.2010
196/2009	<b>WSMS7480000455355</b>	<b>FRC</b>	7951	09.03.2012
197/2009	VK1S338DHRF001744 / <b>201089</b>	<b>FRC</b>	7952	10.03.2012
198/2009	VM3LVFS3F31R06622 / <b>03C0104.001</b>	<b>FRC</b>	7953	13.03.2012
199/2009	SUDNS1CTZ81016594 / <b>11023957</b>	<b>FRC</b>	7955, 4838, M576	31.10.2014
200/2009	VM4CD382G3A021525 / <b>55493</b>	<b>FRC</b>	7954	13.03.2012
201/2009	WKESDR27011384778 / <b>27488</b>	<b>FRC</b>	7956	14.03.2012
202/2009	<b>WSMS7480000450968</b>	<b>FRC</b>	7957	12.03.2012
203/2009	<b>WSMS7480000450036</b>	<b>FRC</b>	7958	08.03.2012
204/2009	VM4C382DNVA002900 / <b>42348</b>	<b>FRC</b>	7959	22.01.2011
205/2009	VM3LVFS3ES1A03863 / <b>96.1472.006</b>	<b>FNA</b>	7960	16.03.2012
206/2009	VFKTE34CCX2XA1378 / <b>9228</b>	<b>FRC</b>	7961	31.12.2010
207/2009	<b>WSMS7480000430085</b>	<b>FRC</b>	6751	23.11.2010
208/2009	VS9SA3NS5XA013625 / <b>C12675</b>	<b>FRC</b>	7963	30.09.2011
209/2009	VAVSAF3383H182034 / <b>11712</b>	<b>FRC</b>	7964	16.03.2012
210/2009	WKESDR27041201826 / <b>29600</b>	<b>FRC</b>	7965	16.03.2012
211/2009	<b>WSMS7480000403045</b>	<b>FRC</b>	7966	30.04.2010
212/2009	<b>WK0SVKT2420203745</b>	<b>FRC</b>	7967	16.03.2012
213/2009	<b>WSMS7780000448781</b>	<b>FRC</b>	7968	16.03.2012
214/2009	SUDNS1CTZ81016695 / <b>11000258</b>	<b>FRC</b>	7969, 4838, M576	31.10.2014
215/2009	XLRAE45FF9L351817 / <b>11014548</b>	<b>FNA/X</b>	7970, 4968, M610	31.03.2015
216/2009	XLRAE45FF9L351818 / <b>11014498</b>	<b>FNA/X</b>	7971, 4968, M610	31.03.2015
217/2009	XLRAE45FF9L351816 / <b>11014508</b>	<b>FNA/X</b>	7972, 4968, M610	31.03.2015
218/2009	XLRAE45FF9L351819 / <b>11014558</b>	<b>FNA/X</b>	7973, 4968, M610	31.03.2015
219/2009	XLRAE45FF9L351814 / <b>11014478</b>	<b>FNA/X</b>	7974, 4968, M610	31.03.2015
220/2009	XLRAE45FF9L351815 / <b>11014468</b>	<b>FNA/X</b>	7975, 4968, M610	31.03.2015
221/2009	XLRAE45FF9L351813 / <b>11014538</b>	<b>FNA/X</b>	7976, 4968, M610	31.03.2015
222/2009	XLRAE45FF9L351810 / <b>11014518</b>	<b>FNA/X</b>	7977, 4968, M610	31.03.2015
223/2009	XLRAE45FF9L351812 / <b>11014488</b>	<b>FNA/X</b>	7978, 4968, M610	31.03.2015
224/2009	XLRAE45FF9L351811 / <b>11014528</b>	<b>FNA/X</b>	7979, 4968, M610	31.03.2015
225/2009	VAVSAF3383H182370 / <b>02C2350.005</b>	<b>FRC</b>	7980	17.03.2012
226/2009	<b>VFKTF34C1S3RB1143 / 95028</b>	<b>FNA</b>	7981	18.03.2015
227/2009	<b>WSMS7780000401924</b>	<b>FRC</b>	7984	14.03.2012
228/2009	<b>WSM00000005032442</b>	<b>FRC</b>	7985	31.12.2013
229/2009	VFNS383ELM3A22693 / <b>25086</b>	<b>FNA</b>	7986	13.03.2012
230/2009	<b>WSMS7480000446046</b>	<b>FRC</b>	7983	19.03.2012
231/2009	<b>WSM00000005028811</b>	<b>FRC</b>	7987, 3348T, MR79	30.06.2012
232/2009	<b>WSM00000005028808</b>	<b>FRC</b>	7988, 3348T, MR79	02.05.2013
233/2009	<b>WSM00000005028809</b>	<b>FRC</b>	7989, 3348T, MR79	02.05.2013
235/2009	WDB6763371K336401 / <b>24604</b>	<b>FRC</b>	7990	24.06.2010
236/2009	<b>WSMS7480000450377</b>	<b>FRC</b>	7991	19.03.2012
237/2009	<b>WSM00000005032233</b>	<b>FRC</b>	7992, 3608T, MR79	30.11.2013
238/2009	<b>WSMS7480000432526</b>	<b>FRC</b>	7993	19.03.2012
239/2009	<b>WSM00000005040095</b>	<b>FRC</b>	7994, 07 1295, M576	19.02.2014
240/2009	<b>WSMS7480000441787</b>	<b>FRC</b>	7995	20.03.2012
241/2009	<b>WSMS7480000435216</b>	<b>FRC</b>	7996	20.03.2012
242/2009	VM3LVFS3EX1R09755 / <b>99C1830.001</b>	<b>FRC</b>	7997	31.12.2011
243/2009	<b>WSMS7480000431539</b>	<b>FRC</b>	7998	25.08.2011

244/2009	W09W00334YDT18S03	FRC	7999	20.03.2012
245/2009	VFKTF34CAX2XB0514	FRC	8007	13.10.2011
246/2009	WSM00000005016330	FRC	8000	24.03.2012
247/2009	WKESDR27011154413	FRC	8001	25.03.2012
248/2009	WKOSVKT24Y0259859	FRC	8002	24.03.2012
249/2009	WSMS7480000438761	FRC	8003	23.03.2012
250/2009	TRGSAF335WD121950	FRC	8004	23.07.2010
251/2009	TRGSAF335WD121942 / 9105	FRC	8005	28.04.2010
252/2009	VAVSAF335VH118330 / 97/C0438-001	FNA	8006	25.03.2012
253/2009	WSM00000005003724	FRC	8008	26.03.2012
254/2009	WSMS7480000443837	FRC	6068	07.01.2010
255/2009	VM3LVFS3FY1R01260 / 00C1009.002	FRC	8010	23.03.2012
256/2009	WSMS7480000081283	FNA	8016	26.03.2012
257/2009	VSMS7780000081876	FNA	8011	26.03.2012
258/2009	WSMS7780000435223	FRC	8012	26.03.2012
259/2009	WKESDR27011386637/27890	FRC	8013	26.03.2012
260/2009	WSMS7480000430628	FRC	8014	09.11.2011
261/2009	ZCBF111EFSOP53426 / 11WX-43-1314	FNA	8015	26.03.2012
262/2009	990862	FRC	8017	01.12.2011
263/2009	WSMS7780000096450	FNA	8018	31.03.2012
264/2009	WKOS0002400101827 / 11007318	FRC	8019, 4838, M576	31.03.2015
265/2009	WKOS0002400101828 / 11007328	FRC	8020, 4838, M576	31.03.2015
266/2009	WKOS0002400101826 / 11007308	FRC	8021, 4838, M576	31.03.2015
267/2009	WKOS0002400101824 / 11003948	FRC	8022, 4838, M576	31.03.2015
268/2009	WSMS7480000448517	FRC	8023	30.03.2012
269/2009	WSMS7780000095948	FRC	8024	13.03.2010
270/2009	WSMS7780000099239	FRC	8025	17.07.2010
271/2009	W09500334VDT18E04	FNA	8026	30.03.2012
272/2009	99424 / 7467	FRC	8027	28.03.2012
273/2009	WSMS7780000434084	FRC	8028	28.03.2012
274/2009	VM3LVFS3FY1R01045 / 00C0236-002	FRC	8029	31.03.2012
275/2009	YS2P6X20001269099 / 01C0031.001	FRC	8030	27.03.2012
276/2009	WMAT37ZZZ2L029737 / 112540	FRC	8031	27.03.2012
277/2009	WSMS7480000453470	FRC	8032	28.03.2012
278/2009	WSMS7480000442014	FRC	8034	26.03.2012
279/2009	WSM00000005011885	FRC	8035	26.03.2012
280/2009	WSMS7480000416511	FRC	8036	30.03.2012
281/2009	WSM00000005032505	FRC	8037, 07 1310, MR79	16.11.2013
282/2009	WSMS7480000434697	FRC	8038	31.03.2012
283/2009	VM3LVFS3F41R09471 / 04C1386/001	FRC	8033	01.04.2012
284/2009	WSMS7480000405109	FRC	8039	20.07.2010
285/2009	WSMS7480000448533	FRC	8040	02.04.2012
286/2009	SUDNSIDBZ81015971 / 11009498	FRC	8041, 4838, M602	28.02.2015
287/2009	SUDNSIDBZ81015970 / 11009488	FRC	8042, 4838, M602	28.02.2015
288/2009	SUDNS1CTZ81016271 / 11023917	FRC	8043, 4838, M576	31.10.2014
289/2009	VM3LVFS3FY1R01072 /00C0336.005	FRC	8044	01.04.2012
290/2009	WSMS7480000445447	FRC	8045	27.03.2012
291/2009	VM3LVFS3F31R06685 / 03C0239.005	FRC	8046	05.04.2012
292/2009	WSMS7480000432949	FRC	8047	28.01.2012
293/2009	WSM00000005055982	FRC	3421T, M601	28.05.2014
294/2009	WMAL860010Y027570 / 2274763	FNA	8048	04.04.2012
295/2009	WMAN26ZZ89Y232089 / 11000229	FRC	8055, 7328, MR99	31.03.2015
296/2009	WSM00000005041335	FRC	8056, 07 1310, 3165K	30.06.2014
297/2009	VM3LVFS3EX1R00447 / 99/C0799.003	FRC	8057	01.06.2011
298/2009	WSMS7480000450281	FRC	8058	05.04.2012
299/2009	XLRAS47XS0E494486 / V 038/01	FRC	8049	06.04.2012
300/2009	W09KKS232STK26011 / 7722	FNA	8050	06.04.2012
301/2009	WK0AVKT18X0228358	FRC	8051	21.06.2011
302/2009	XLRAS48XS0E590785 / 2277791	FRC	8052	06.04.2012
303/2009	WDB9700121K328840 / 24786	FRC	8053	01.07.2010
304/2009	WKESDR27011274964 / 26614	FRC	8059	10.04.2012

305/2009	VM3LVFS3EX1R09868 / 99/C2056-001	FRC	8060	31.12.2011
306/2009	WSM00000005032199	FRC	8063, 07 1310, MR79	09.11.2013
307/2009	VM4C382DRWA004245 / 38952	FNA	8064	08.04.2012
308/2009	WSMS7480000450179	FRC	8065	05.04.2012
309/2009	VM4C382DNTA002469 / 50559	FRC	8066	09.04.2012
310/2009	WSMS7480000410830	FNA	8067	08.04.2012
311/2009	VM4CD382G4A022782 / 59832	FRC	8068	31.03.2012
312/2009	VM3LVFS3EV1R06593 / 97/C1835-002	FRC	8071	21.12.2009
313/2009	WSMS7480000084126	FNA	8069	10.04.2012
314/2009	WKESDR27011264480 / 25447	FRC	8061	14.04.2012
315/2009	SFRRCVSA3VV129801 / 302036	FRC	8062	14.04.2012
316/2009	WSMS7480000447073	FRC	8072	16.04.2012
317/2009	VM4CD381J3A012007 / 58458	FRC	8073	17.04.2012
318/2009	VM4CD381J3A011633 / 56259	FRC	8074	17.04.2012
319/2009	VM4CD385GXA000202 / 42223	FRC	8081	16.02.2011
320/2009	VM3LVFS3F11A03046 / 01C0905.002	FRC	8075	17.04.2012
321/2009	WSMS7480000449750	FRC	8076	14.04.2012
322/2009	WSMS7480000434333	FRC	8077	28.02.2012
323/2009	WSM00000005014226	FRC	8078	20.04.2012
324/2009	WSM00000005032337	FRC	8079, 3390T, MR79	31.01.2014
325/2009	WSMS7480000450138	FRC	8080	14.04.2012
326/2009	VM3LVFS3F21R06224 / 02C2150.001	FRC	7019	06.03.2011
327/2009	21722 / 23793	FRC	8086	20.04.2012
328/2009	VM3LVFS3F31R07401 / 03C1405/004	FRC	8087	20.04.2012
329/2009	WSMS7480000456142	FRC	8083	15.04.2012
330/2009	WSMS7480000456140	FRC	8084	15.04.2012
331/2009	VM4CD382GXA000748	FRC	8085	08.11.2011
332/2009	XLRAE55GF8L348877 / 11004838	FRC	8088, 6652, M578	31.10.2014
333/2009	SUDNS1CTZ86018429 / 11008238	FRC	8089, 4838, M602	30.11.2014
334/2009	VS9SA3NS3TA013873 / C10603	FNA	8094	21.04.2015
335/2009	WSM00000005013334	FRC	3352T, MR79	02.2012
336/2009	VM3LVFS3F41R09460 / 04C1223.001	FRC	8096	30.03.2012
337/2009	WSM00000005013770	FRC	6176, 05 1251, MR79	03.2012
338/2009	WSMS7480000085479	FRC	8092	31.12.2009
339/2009	VM4CD382G1A020542 / 52216	FRC	8093	21.04.2012
340/2009	VF617CKA000000633 / 11001109	FRC	8099, 6652, M629	31.03.2015
341/2009	VF644AGM000000477 / 11001129	FRC	8100, 7328, M568	31.03.2015
342/2009	VF644AHH000002074 / 11001139	FRC	8101, 7328, M568	31.03.2015
343/2009	VF644AGM000000422 / 11001119	FRC	8102, 7328, M568	31.03.2015
344/2009	WSM00000005034070	FRC	8103	16.04.2012
345/2009	WSM00000005031534	FRC	8104, 07 1310, MR79	30.10.2013
346/2009	WKESD000000431604	FRC	8105	20.04.2012
347/2009	VAVSAF3383H185390 / 5790	FRC	8106	17.04.2012
349/2009	WSM00000005002595	FRC	8108	23.04.2012
350/2009	WKESDR27011385261 / 27675	FRC	8109	24.04.2012
351/2009	VM3LVFS3ET1R05115 / 96/C1550-001	FNA	8110	24.04.2012
352/2009	ZCFA1GG0002257675 / 30503	FRC	8111	24.04.2012
353/2009	VM3LVFS3EV6R05596 / 97/C0506-002	FNA	8112	28.04.2015
355/2009	WKESDR27011385263 / 27674	FRC	8114	27.04.2012
356/2009	WSMS7480000416497	FRC	8115	30.06.2011
357/2009	WSM00000005004173	FRC	8116	21.04.2012
358/2009	WSM00000005004894	FRC	8117	21.04.2012
359/2009	ZE5368SP6FJKL0982 / 031	FRC	8118	22.04.2012
360/2009	WSM00000005014227	FRC	8119	27.04.2012
361/2009	WSM00000005014228	FRC	8120	27.04.2012
362/2009	ZCFC35A8085743921 / 11012188	FNA/X	8121, 7327, M607	31.10.2014
363/2009	ZCFC35A8085743924 / 11012168	FNA/X	8122, 7327, M607	31.10.2014
364/2009	ZCFC35A8085743923 / 11012158	FNA/X	8123, 7327, M607	31.10.2014
365/2009	ZCFC35A8085743925 / 11012148	FNA/X	8124, 7327, M607	31.10.2014
366/2009	ZCFC35A8085732715 / 11012128	FNA/X	8125, 7327, M607	31.10.2014
367/2009	ZCFC35A8085732713 / 11012138	FNA/X	8126, 7327, M607	31.10.2014

368/2009	ZCFC35A8085744329 / 11012178	FNA/X	8127, 7327, M607	31.10.2014
369/2009	VVCSORXBCS4X00371 / 14910	FRC	8128	31.01.2011
370/2009	WK0S0002400109692	FRC	8129, R2003/319, M580	31.12.2013
371/2009	VVCSORXBAS4Y00780 / 16994	FRC	8131	29.04.2012
372/2009	VM3LVFS3EV1R05437	FNA	8131	30.04.2012
373/2009	WKESDR27011388295 / 28.073	FRC	8132	21.04.2012
374/2009	WKESD000000431605	FRC	8133	29.04.2012
375/2009	WSMS7480000448530	FRC	8134	27.04.2012
376/2009	WSMS7480000450358	FRC	8135	29.04.2012
377/2009	WSMS7480000403027	FRC	8136	31.12.2010
378/2009	WSMS7480000450184	FRC	8138	24.04.2012
379/2009	WK0SVKT24Y0249926	FRC	8139	02.05.2012
380/2009	VM3LVFS3EW1R07999 / 98.C1150-050	FRC	8140	31.12.2010
381/2009	WSMS7480000450136	FRC	8141	29.04.2012
383/2009	VM3LVFS3E21R10693 / 02C0867.010	FRC	8143	29.04.2012
384/2009	VM3LVFS3ET4A04600 / 96.C0602.002	FNA	8144	04.05.2012
385/2009	VM3LVFS3EX1R09229 / 99.C0922-001	FRC	8145	28.06.2011
386/2009	VM3LVFS3F21R06396 / 02C2509.001	FRC	8146	12.03.2012
387/2009	WSMS7480000430253	FRC	8147	31.05.2011
388/2009	WSMS7480000440276	FRC	8148	02.05.2012
389/2009	WSMS7480000434356	FRC	8149	02.05.2012
390/2009	VM3LVFS3FX1R00351 / 99.C0154-004	FRC	8150	31.05.2011
391/2009	WSMS7780000439645	FRC	8151	02.05.2012
392/2009	VM3LVFS3F16R03673 / 01C1958.001	FRC	8152	02.05.2012
393/2009	21723 / 23794	FRC	8137	05.05.2012
394/2009	WKESDR270113870073 / 26265	FRC	8153	07.05.2012
395/2009	VFNSYY3CXTAR09894 / F9001.630468	FRC	8154	31.03.2011
401/2009	VM3LVFS3FY1R01076 / 00C0336.009	FRC	8160	31.01.2012
402/2009	WSMS7480000087996	FNA	8161	07.05.2012
403/2009	WSMS7480000451022	FRC	8162	05.05.2012
404/2009	VM3LVFS3F21R04237 / 01C2682.005	FRC	8163	06.05.2012
405/2009	VS9SA3NS5WA013203 / C12157	FNA	8164	06.05.2012
406/2009	VM4C381BRRA001096	FNA	8165	06.05.2012
407/2009	WKESDR27041203716	FRC	8166	06.05.2012
408/2009	WKESDR27041203714	FRC	8167	06.05.2012
409/2009	WDB9702781K799579 / 19486	FRC	8168	29.02.2012
410/2009	WDB9506051K742276	FNA	8169	09.05.2012
411/2009	ZCFC35A8085751771 / 11001019	FRC	8170, 5547, M610	31.03.2015
412/2009	YS2P6X20002037992 / 11001478	FRC	8171, 6652, M421	31.05.2014
413/2009	WSMS7480000092867	FNA	8172	07.05.2012
414/2009	WKESDR27011267947	FRC	8173	06.05.2012
415/2009	WSMS7480000438299	FRC	8174	05.05.2012
416/2009	VM3LVFS3F36R07478 / 03C1537-002	FRC	8175	05.05.2012
417/2009	WSMS7480000450378	FRC	8176	11.05.2012
418/2009	WSMS7480000450967	FRC	8177	12.05.2012
419/2009	VM3LVFS3F14A03612 / 01/C1726.05	FRC	8178	12.05.2012
420/2009	WSMS7480000448217	FRC	8179	12.05.2012
421/2009	WK0S0002400101829 / 11002149	FNA	8180, 4525, M576	31.05.2015
422/2009	WSMS7480000081297	FNA	8181	11.05.2012
423/2009	VM3LVFS3FX1R00995 / 99/C2406-001	FRC	8182	31.01.2012
424/2009	WSM00000005012647	FRC	5510, 3362T	17.01.2012
425/2009	WKESDR27011386636 / 27.889	FRC	8185	16.06.2012
426/2009	WSMS7480000441454	FRC	8186	16.05.2012
427/2009	WKESDR27011385656 / 28138	FRC	8187	13.05.2012
428/2009	VM3LVFS3EX1R08726 / 98.C2144-002	FRC	8188	31.01.2011
429/2009	WKESDR27011383433 / 1153-2003	FRC	8189	02.05.2012
430/2009	WKESDR27011274620 / 932-2002	FRC	8190	02.05.2012
431/2009	W0907F336WPA10046 / 22053	FRC	8191	26.01.2011
434/2009	80976	FRC	8194	31.12.2010
435/2009	VM4C382DNVA003487	FRC	8195	31.12.2010
436/2009	VP3S34EBT6FPD0160 / 14581	IN	8198	14.05.2015

437/2009	VFNS383ELN3A24915 / 99038	FRC	8197	30.04.2011
438/2009	WSMS7480000432708	FRC	8196	13.01.2012
439/2009	VAVSAF3384Z203288 / 11000825	FRC	4838, MR79	30.01.2011
440/2009	WSM00000005059272	FRC	05 1248, M602	27.11.2014
441/2009	WSM00000005045610	FRC	8201, 07 1310, M576	31.10.2013
443/2009	WSMS7480000437717	FRC	8203	18.05.2012
444/2009	WK0SVKT24Y9853051	FRC	8204	24.03.2012
445/2009	WSMS7480000459587	FRC	7506	19.09.2012
446/2009	WSMS7480000450925	FRC	8206	20.05.2012
447/2009	VF622CVA000100963	FNA	8207	22.05.2012
448/2009	WKESDR27011264525 / 25532	FRC	8208	21.05.2012
449/2009	VVCS0RXBCS4X00517 / 15747	FRC	8209	30.09.2011
450/2009	WSM00000005002435	FRC	8210	20.05.2012
451/2009	VM3LVFS3FX1R00659 / 99/C1838-001	FRC	8211	26.10.2011
452/2009	VM3LVFS3EV1A06471 / 97/C1747.001	FRC	8223	31.12.2009
453/2009	WKESDR27041222336 / 31287	FRC	8224	21.05.2012
454/2009	VM3LVFS3FY1A00879 / 00C3011-001	FRC	8212	31.01.2012
455/2009	VVCS0RXBCS4X00463 / C108589	FRC	8213	22.05.2012
456/2009	WSMS7480000450314	FRC	8214	23.05.2012
457/2009	WSMS7480000444811	FRC	8215	23.05.2012
458/2009	WSMS7480000450481	FRC	8216	23.05.2012
462/2009	WSM00000005025348	FRC	8220, 07 1303, MR79	29.06.2013
463/2009	VM3LVFS3EX1R09245 / 02C0691.001	FRC	8221	23.05.2012
464/2009	4125890	FNA	8222	23.05.2012
465/2009	WSMS7480000403776	FRC	8225	14.05.2010
467/2009	WSMS7480000454910	FRC	8227	21.05.2012
468/2009	SMSS7780000700929	FRC	8228	21.05.2012
469/2009	WSMS7480000446726	FRC	8229	25.05.2012
470/2009	WSMS7780000441423	FRC	8230	23.05.2012
471/2009	VM3LVFS3EX1R08937 / 99/C0307.002	FRC	8231	31.03.2011
473/2009	VM4CD381J1A010459 / 50380	FRC	8233	22.05.2012
474/2009	WSMSKO24000057302	FNA	8234	23.05.2012
475/2009	WSMS7480000401036	FRC	8235	02.07.2010
476/2009	WKESDR27000151777 / 24528	FRC	8236	23.05.2012
477/2009	VM4C382BRYA005400 / 47275	FRC	8237	26.05.2012
478/2009	WSMS7480000456457	FRC	03 1180, MR79	02.2010
479/2009	SZ9N320003HGR1982 / 11003723	FNA	4525, 4736.2	31.10.2009
480/2009	VM3LVFS3EW1R08405 / 98/C1580-002	FRC	8238	31.12.2010
481/2009	21369 / 22689	FRC	8239	22.03.2011
482/2009	VM3LVFS3F24R04649 / 02C0634.003	FRC	8240	27.05.2012
483/2009	VM3LVFS3F24R04644 / 02C0633.001	FRC	8241	27.05.2012
484/2009	1028798	FNA	8247	28.05.2012
485/2009	WSMS7480000448505	FRC	8244	27.05.2012
486/2009	WSMS7480000450312	FRC	8245	15.05.2012
487/2009	WSMS7480000444719	FRC	8246	27.05.2012
488/2009	VM3LVFS3F21R04234 / 01C2682.002	FRC	8248	23.05.2012
489/2009	WSMS7480000450203	FRC	8249	27.05.2012
490/2009	YA914703812972742	FRC	8250	08.05.2010
491/2009	VM3LVFS3ET1R05031 / 96/C1381-001	FNA	8251	02.06.2012
492/2009	WSMS7480000082425	FNA	8252	01.06.2012
493/2009	VM4C381BNVA003616 / 38285	FNA	8253	01.06.2012
494/2009	WSMS7480000082480	FNA	8254	31.05.2012
495/2009	WKESDR27051226501 / 31810	FRC	8255	01.06.2012
496/2009	WKESDR27011265109	FRC	8256	31.05.2012
497/2009	VK1SR334FAP2W0991 / 98/02535.002	FRC	8257	15.06.2011
498/2009	VM4C381BNVA003051 / 36787	FNA	8258	01.06.2012
499/2009	UH9S36LJ3PBP3929 / 93/C0713.001	FNA	8259	01.06.2012
500/2009	WSMS7780000445148	FRC	8260	01.06.2012
501/2009	WKESDR27011265101 / 25573	FRC	8261	31.05.2012
502/2009	WSMS7480000068226	FNA	8262	31.05.2012
505/2009	WSM00000005006433	FRC	8265	29.05.2012

506/2009	<b>WSMS7480000447002</b>	<b>FRC</b>	8266	29.05.2012
507/2009	<b>WSMS7780000435749 / 185-2000</b>	<b>FRC</b>	8267	27.05.2012
508/2009	VM3LVFS3ET1A04188 / <b>96C.0176-001</b>	<b>FNA</b>	8268	27.05.2012
509/2009	<b>WSMS7480000448161</b>	<b>FRC</b>	8269	04.06.2012
511/2009	WFDFLT33551001164 / <b>11002575</b>	<b>FRC</b>	4838, M576	03.2011
512/2009	2122145 / <b>97/C0258-006</b>	<b>FNA</b>	8270	04.06.2015
513/2009	<b>WKESDR27011269071</b>	<b>FRC</b>	8271	04.06.2012
514/2009	<b>VF644ACA000007783</b>	<b>FRC</b>	8272	04.06.2012
515/2009	<b>WKESDR27011385662</b>	<b>FRC</b>	8273	04.06.2012
516/2009	VM3LVFS3EV3R06360 / <b>97/C0101-001</b>	<b>FNA</b>	8274	05.06.2012
519/2009	SUDNS1CTZ83017692 / <b>11004428</b>	<b>FRC</b>	8280, 4838, M576	31.01.2015
520/2009	<b>WSM00000005013341</b>	<b>FRC</b>	05 1251, MR79	03.2012
521/2009	<b>WSM00000005059647</b>	<b>FRC</b>	05 1248, MR79	02.01.2015
522/2009	VM3LVFS3EW1R07246 / <b>97/C2066-001</b>	<b>FRC</b>	6718	31.01.2010
523/2009	<b>WSMS7480000447368</b>	<b>FRC</b>	8284	30.05.2012
524/2009	<b>WSMS7480000450580</b>	<b>FRC</b>	8285	03.06.2012
525/2009	VM3LVFS3ET6R05199 / <b>96.C1647-025</b>	<b>FNA</b>	8286	30.05.2012
526/2009	VM3LVFS3FY1R01025 / <b>00C127.004</b>	<b>FRC</b>	8287	28.02.2012
527/2009	<b>WSMS7480000401035</b>	<b>FNA</b>	8288	03.06.2012
528/2009	<b>WSMS7480000400964</b>	<b>FNA</b>	8289	03.06.2012
529/2009	VM3LVFS3F41R08249 / <b>03C2534/002</b>	<b>FRC</b>	8290	09.06.2012
530/2009	<b>WKOSVKT2420203778</b>	<b>FRC</b>	8291	08.06.2012
531/2009	<b>WSMS7480000450190</b>	<b>FRC</b>	8292	08.06.2012
532/2009	<b>14360</b>	<b>FNA</b>	8293	08.06.2012
533/2009	VA9USLAKT1FZT0308 / <b>CFE 268</b>	<b>FRC</b>	8294	10.06.2012
534/2009	WKOSVKT2450735495 / <b>60474</b>	<b>FRC</b>	8295	21.05.2012
535/2009	<b>WSMS7480000414661</b>	<b>FRC</b>	8296	04.02.2011
536/2009	<b>WSMS7480000431638</b>	<b>FRC</b>	8297	26.10.2011
537/2009	<b>WSMS7480000450183</b>	<b>FRC</b>	8298	12.06.2012
538/2009	WKESDR27071288113 / <b>36640</b>	<b>FRC</b>	8301	15.06.2012
539/2009	XL9DT3339X0017020 / <b>L9368H990108</b>	<b>FRC</b>	8302	28.01.2011
540/2009	02-01381 / <b>03C0316.001</b>	<b>FRC</b>	8305	17.06.2012
541/2009	20769 / <b>20382</b>	<b>FNA</b>	8299	15.06.2012
542/2009	<b>WSMS7480000442039</b>	<b>FRC</b>	8300	15.06.2012
543/2009	SUDNS1CTZ68010773 / <b>11016276</b>	<b>FRC</b>	6109, 4838, MR79	12.2012
544/2009	WKESDR27011378748 / <b>27079</b>	<b>FRC</b>	8306	16.06.2012
545/2009	<b>WKOSVKT24X9845358</b>	<b>FRC</b>	8307	10.01.2012
546/2009	VF9SR34BTA0049100 / <b>12850</b>	<b>IN</b>	8308, 8198	14.05.2012
547/2009	VP3S34EBT6FPD0044 / <b>14254</b>	<b>IN</b>	8309, 8198	14.05.2015
548/2009	VP3S34EBT6FPD0043 / <b>14253</b>	<b>IN</b>	8310, 8198	14.05.2015
549/2009	VP3SR34B27FPD0139 / <b>15727</b>	<b>IN</b>	8311, 8198	14.05.2015
550/2009	VF9SR34BT40049099 / <b>12849</b>	<b>IN</b>	8312, 8198	14.05.2012
551/2009	VF9SR34BT50049141 / <b>13385</b>	<b>IN</b>	8313, 8198	14.05.2012
552/2009	VF9SR34BT30049275 / <b>12492</b>	<b>IN</b>	8314, 8198	14.05.2012
553/2009	VP3S34EBT6FPD0162 / <b>14583</b>	<b>IN</b>	8315, 8198	14.05.2015
554/2009	VP3S34EBT6FPD0157 / <b>14586</b>	<b>IN</b>	8316, 8198	14.05.2015
555/2009	VP3S34EBT6FPD0152 / <b>14595</b>	<b>IN</b>	8317, 8198	14.05.2015
556/2009	VP3S34EBT6FPD0042 / <b>14252</b>	<b>IN</b>	8318, 8198	14.05.2015
557/2009	<b>WSMS7480000451594</b>	<b>FRC</b>	8319	16.06.2012
558/2009	VFKTF34C1W3RB2232 / <b>39961</b>	<b>FRC</b>	8320	15.05.2010
559/2009	<b>WKOSVKA24Y0254915</b>	<b>FRC</b>	8321	10.05.2012
560/2009	XLEP4X20004388030 / <b>2275753</b>	<b>FNA</b>	8322	16.06.2012
561/2009	<b>WSMS7480000451539</b>	<b>FRC</b>	8323	18.06.2012
562/2009	VM3LVFS3FY1R01242 / <b>00C0889.001</b>	<b>FRC</b>	8324	31.05.2012
563/2009	VM3LVFS3F11R02597 / <b>01C0137.005</b>	<b>FRC</b>	8325	19.06.2012
564/2009	<b>WSMS7780000440823</b>	<b>FRC</b>	8326	17.06.2012
565/2009	W091643381HS09362 / <b>059U14585</b>	<b>FRC</b>	8327	19.06.2012
566/2009	WKESDR27011264549 / <b>25542</b>	<b>FRC</b>	8328	19.06.2012
567/2009	<b>WSM00000005007156</b>	<b>FRC</b>	8329	22.06.2012
568/2009	<b>WSMS7780000090321</b>	<b>FNA</b>	8331	22.06.2012
569/2009	<b>WSMS7480000448328</b>	<b>FRC</b>	8330	23.06.2012

570/2009	WKESDR27011386346 / 27680	FRC	8332	23.06.2012
571/2009	VF1UDC1K641514753 / 11002129	FNA/X	8333, 7327, M486	31.05.2015
572/2009	WKESDR27011495673 / 29460	FRC	8334	20.06.2012
573/2009	VF622CVA000109737 / 98-28073	FRC	8335	31.01.2011
574/2009	WSMS7480000438084	FRC	8336	20.06.2012
575/2009	SMSS7780000700102	FRC	8337	20.06.2012
576/2009	VM3LVFS3FY1R02001 / 00C2567.016	FRC	8338	20.06.2012
577/2009	VAVSAF3386Z228172 / 24.565	FRC	2003/1692, M588	03.2012
578/2009	TRGSAI335VD120352 / 8803	FNA	8340	23.06.2012
579/2009	TRGSAF335WD128066 / 9225	FNA	8341	23.06.2012
580/2009	WSMS7780000094273	FNA	8342	23.06.2012
581/2009	WSMS7480000416517	FRC	8343	29.01.2011
582/2009	WKESD000000404421 / 000247	FRC	8345, 3392T, M576	18.04.2014
583/2009	WSM00000005019078	FRC	8346	25.06.2012
584/2009	VM3LVFS3ET1R05007 / 96/C1295.01	FRC	6945	16.10.2009
585/2009	WSM00000005014860	FRC	06 1275, MR79	04.2012
586/2009	WSMS7780000092659	FNA	8348	25.06.2012
587/2009	SUDNS1CTZ83017693 / 11004438	FRC	8349, 4838, M576	28.02.2015
588/2009	WK0S0002400101830 / 11003589	FRC	8350, 4838, M576	31.05.2015
589/2009	WK0S0002400052172 / 66023	FRC	8351	26.06.2012
590/2009	WKESDR27011267011 / 25869	FRC	8352	26.06.2012
591/2009	VM3LVFS3ET3R05076 / 96C1469.001	FNA	8353	26.06.2012
592/2009	VFNSYLLY2RA0284 / 47327	FRC	8354	27.06.2012
593/2009	VM3LVFS3FW1R00278 / 98C1839-005	FRC	8359	14.12.2010
594/2009	VM3LVFS3FY1R01023 / 00C0127-002	FRC	8360	29.02.2012
595/2009	92766	FNA	8355	29.06.2012
596/2009	200146	FRC	8356	01.01.2012
597/2009	WSM00000005000106	FRC	8357	29.06.2012
598/2009	WSMS7780000445284	FRC	8358	09.06.2012
599/2009	WSMS7780000417494	FRC	8361	31.12.2011
600/2009	VVCS0RXBCS4Y00747 / 16602	FRC	8362	29.06.2012
601/2009	VFNSYY3CXWAR16618 / F8001.630612	FRC	8363	31.12.2010
602/2009	YA914703806962287 / F6A41140	FNA	8364	29.06.2012
603/2009	VM3LVFS3EW1R07269 / 98/C0482-001	FNA	8365	29.06.2012
604/2009	WM3LVFS3ES3R04016 / 96/C1526-001	FNA	8366	29.06.2012
605/2009	VM3LVFS3F11R03435 / 01C1595.002	FRC	8367	30.06.2012
606/2009	WSMS7780000446057	FRC	8368	29.06.2012
607/2009	WSMS7480000430516	FRC	8369	16.07.2011
608/2009	WKESDR27011158495 / 25009	FRC	8370	30.06.2012
609/2009	SU9S0000TY9WL1206	FRC	8371	31.12.2011
610/2009	YE7SD3AASN4203282 / F40002.P1869	FRC	8375	03.07.2012
611/2009	WSM00000005015578	FRC	8373, 07 1295, M523	26.09.2013
612/2009	VM3LVFS3EX4R09137 / 99/C0708. 003	FRC	8374	31.12.2011
613/2009	VM3LVFS3F31R05742 / 03C3702/001	FRC	8372	03.07.2012
614/2009	VM3LVFS3F41R08529 / 04C1353.001	FRC	8376	03.07.2012
615/2009	VM3LVFS3FY1R01156 / 00C0587.001	FRC	8377	28.04.2012
616/2009	VM3LVFS3ET1R04796 / 96/C0955.001	FNA	8378	06.07.2012
617/2009	WSM00000005034004	FRC	8379, 06 1286, MR79	31.10.2013
618/2009	WSMS7480000450196	FRC	8380	07.07.2012
619/2009	WSMA7420000067271	FNA	8381	08.07.2012
620/2009	WDB9502031K578405 / 0276840	FRC	8382	08.07.2012
621/2009	WSMK0180000061583	FNA	8383	08.07.2012
622/2009	VM3LVFS3ET6R05190 / 96/C1647.016	FNA	8384	08.07.2012
623/2009	YA914703802972471 / F706009	FRC	8385	07.01.2010
624/2009	WSMS7780000403036	FNA	8386	14.07.2012
625/2009	WSMS7480000441552	FRC	8387	14.07.2012
626/2009	WSM00000005029594	FRC	8388, 3390T, MR79	12.07.2013
628/2009	VM4CD3824GA022402 / 58187	FRC	8389	15.07.2012
629/2009	VM4CD382G4A022453 / 58749	FRC	8390	15.07.2012
630/2009	VM4CD382G3A021619 / 56183	FRC	8391	15.07.2012
631/2009	VM4C381BRTA002603 / 34377	FNA	8392	16.07.2012

632/2009	<b>WSM0000005041212</b>	<b>FRC</b>	8396, 3404T, MR79	18.02.2014
633/2009	<b>WSMS748000094200</b>	<b>FNA</b>	8397	14.07.2012
634/2009	<b>WSMS7480000446108</b>	<b>FRC</b>	8398	16.07.2012
635/2009	<b>WSMS7480000431968</b>	<b>FRC</b>	8399	05.11.2011
636/2009	VM4CD382G1A020449	<b>FRC</b>	8400	20.07.2012
638/2009	WKESDF27000Y41521 / <b>23780</b>	<b>FRC</b>	8394	21.07.2012
639/2009	<b>WSMS7480000441901</b>	<b>FRC</b>	8395	21.07.2012
640/2009	WDB9702531L390927 / <b>11003659</b>	<b>FRC/X</b>	8402, 5547, M581	30.06.2015
641/2009	ZCFA1EG1382540733 / <b>11004809</b>	<b>FNA/X</b>	8403, 4152, MR76	31.07.2015
642/2009	XLER6X20005224860 / <b>11014138</b>	<b>FRC</b>	8404, 6652, M588	31.03.2015
643/2009	XLER6X20005224870 / <b>11014128</b>	<b>FRC</b>	8405, 6652, M588	31.03.2015
644/2009	TYBFE659H6DS29330 / <b>0904068</b>	<b>RRC/X</b>	8406, 6453, MR75	17.07.2015
645/2009	VAVSAF335YH148244 / <b>217UG3356</b>	<b>FRC</b>	8407	31.12.2011
646/2009	VAVSAF3398Z280452 / <b>27.851</b>	<b>FRC</b>	2004/1687, M576	30.04.2014
647/2009	VAVSAF3398Z280454 / <b>27.852</b>	<b>FRC</b>	2004/1687, M576	30.04.2014
648/2009	VAVSAF3398Z280450 / <b>27.850</b>	<b>FRC</b>	2004/1687, M576	30.04.2014
649/2009	VAVV203399H288408 / <b>28.239</b>	<b>FRC</b>	2004/1687, M576	31.07.2014
650/2009	<b>WSMS7480000401512</b>	<b>FRC</b>	8412	31.12.2010
651/2009	<b>WSMS7480000437722</b>	<b>FRC</b>	8413	23.07.2012
652/2009	VM3LVFS3ES1A02975 / <b>95C0324.001</b>	<b>FNA</b>	8414	24.07.2012
653/2009	VM3LVFS3ES1A02885 / <b>95C0144.001</b>	<b>FNA</b>	8415	24.07.2012
654/2009	VM4CD382G2A021132 / <b>54080</b>	<b>FRC</b>	8416	24.07.2012
655/2009	VM3LVFS3EY1R10397 / <b>00C1531.001</b>	<b>FRC</b>	7031	07.03.2011
656/2009	<b>WSM0000005033177</b>	<b>FRC</b>	8418, 3395T, M576	30.09.2013
657/2009	<b>WSMS7480000450161</b>	<b>FRC</b>	8419	28.07.2012
658/2009	<b>WSMS7480000452826</b>	<b>FRC</b>	8420	28.07.2012
659/2009	ZCFA1EG1492546385 / <b>11004199</b>	<b>FNA/X</b>	8421, 4968, M517	31.07.2015
660/2009	<b>WKESDR27011272441</b>	<b>FRC</b>	8422	11.04.2012
661/2009	<b>WSMS7780000433816</b>	<b>FRC</b>	8423	11.04.2012
662/2009	<b>WSM0000005003153</b>	<b>FRC</b>	3338T, MR79	01.2011
663/2009	<b>WSMS7480000084177</b>	<b>FNA</b>	8425	29.07.2012
664/2009	WK0SVKT24Y0248640 / <b>02-48640</b>	<b>FRC</b>	8426	30.06.2012
665/2009	XLK301227T0023874 / <b>02C1196.003</b>	<b>FRC</b>	8427	30.07.2012
666/2009	<b>WSMS7480000451042</b>	<b>FRC</b>	8428	24.07.2012
667/2009	<b>80653</b>	<b>FNA</b>	8429	30.07.2012
668/2009	YV2JL60A68A661504 / <b>2804046</b>	<b>IN</b>	8430, 5611	10.05.2014
669/2009	YV2JL60A38A661945 / <b>2804047</b>	<b>IN</b>	8431, 5611	10.05.2014
670/2009	YV2JL60A78A662211 / <b>2804065</b>	<b>IN</b>	8432, 5611	10.05.2014
671/2009	YV2JL60AX8A663904 / <b>2804078</b>	<b>IN</b>	8433, 5611	18.07.2014
672/2009	YV2JL60A78A663844 / <b>2804080</b>	<b>IN</b>	8434, 5611	18.07.2014
673/2009	YV2JL60A59A683589 / <b>2920347</b>	<b>IN</b>	8435, 5611	24.03.2015
674/2009	YV2JL60A79B540606 / <b>2903045</b>	<b>IN</b>	8436, 5611	24.03.2015
675/2009	ZB311260ATZD49118 / <b>2804049</b>	<b>IN</b>	8437, 5611	10.05.2014
676/2009	ZB311260ATZD49121 / <b>2804062</b>	<b>IN</b>	8438, 5611	10.05.2014
677/2009	ZB311260ATZD49395 / <b>2804079</b>	<b>IN</b>	8439, 5611	18.07.2014
678/2009	ZB311260ATZD49394 / <b>2804081</b>	<b>IN</b>	8440, 5611	18.07.2014
679/2009	ZB311260ATZD49119 / <b>2804050</b>	<b>IN</b>	8441, 5611	10.05.2014
680/2009	ZB311260ATZD50019 / <b>2903048</b>	<b>IN</b>	8442, 5611	24.03.2015
681/2009	ZB311260ATZD50020 / <b>2903046</b>	<b>IN</b>	8443, 5611	24.03.2015
682/2009	<b>WSMS7480000452825</b>	<b>FRC</b>	8444	01.08.2012
683/2009	<b>WSMS7480000451044</b>	<b>FRC</b>	8445	01.08.2012
684/2009	<b>WSMS7480000450970</b>	<b>FRC</b>	8446	01.08.2012
685/2009	<b>WSMS7480000443421</b>	<b>FRC</b>	8447	03.08.2012
686/2009	<b>WSMS7480000451259</b>	<b>FRC</b>	8448	30.07.2012
687/2009	<b>WSMS7480000448541</b>	<b>FRC</b>	8449	28.07.2012
688/2009	VM3LVFS3F21R04029 / <b>01C2450.003</b>	<b>FRC</b>	8450	30.07.2012
689/2009	<b>WK0SVKT24V2181239</b>	<b>FRC</b>	8451	30.07.2012
690/2009	<b>WSM0000005016434</b>	<b>FRC</b>	3367T, MR79	06.2012
691/2009	<b>WSMS7480000449660</b>	<b>FRC</b>	8453	05.08.2012
692/2009	<b>WSMS7780000435007</b>	<b>FRC</b>	8454	05.08.2012
693/2009	<b>2130620</b>	<b>FNA</b>	8455	05.08.2012

694/2009	<b>WKESDR27011386612</b>	<b>FRC</b>	8456	06.08.2012
695/2009	WMAH18ZZ97W091098 / <b>11001287</b>	<b>FRC</b>	8457, 4560, MR92	31.12.2013
696/2009	WMAH18ZZ96W061176 / <b>11008015</b>	<b>FRC</b>	8458	06.08.2012
697/2009	VF622ACA000111439 / <b>11000165</b>	<b>FRC/X</b>	8459	06.08.2012
698/2009	<b>WSMS7480000443456</b>	<b>FRC</b>	8462	04.08.2012
699/2009	<b>WSMS7480000450159</b>	<b>FRC</b>	8463	04.08.2012
700/2009	<b>WSMS7780000436891</b>	<b>FRC</b>	8464	05.08.2012
701/2009	<b>WSM00000005039988</b>	<b>FRC</b>	8465, 05 1248, MR79	02.01.2014
702/2009	<b>WSMS7780000444554</b>	<b>FRC</b>	8466	06.08.2012
703/2009	<b>WK0SVKT2420203670</b>	<b>FRC</b>	8467	06.08.2012
704/2009	<b>WSMS7480000450524</b>	<b>FRC</b>	8468	11.08.2012
705/2009	<b>WSMS7780000454206</b>	<b>FRC</b>	8469	06.08.2012
706/2009	W0907F336VSA10437 / <b>11013178</b>	<b>FRC</b>	8470	06.08.2012
707/2009	WJME2NP0054285385 / <b>887</b>	<b>FRC</b>	8471	20.06.2012
708/2009	<b>VS9SASNS61A013763</b>	<b>FRC</b>	8472	07.08.2012
709/2009	<b>XLRAS47XS0E530625</b>	<b>FNA</b>	8473	07.08.2012
710/2009	<b>26948</b>	<b>FNA</b>	8474	07.08.2012
711/2009	YV2E4C3A9WB190903 / <b>39530</b>	<b>FNA</b>	8475	06.08.2012
712/2009	<b>WSMS7480000450209</b>	<b>FRC</b>	8476	06.08.2012
713/2009	ZCFC3575005774166 / <b>11003029</b>	<b>FRC/X</b>	8477, 5011, M518	30.06.2015
714/2009	ZCFC3575005780876 / <b>11003039</b>	<b>FRC/X</b>	8478, 5011, M518	30.06.2015
715/2009	ZCFC3575095797935 / <b>11003059</b>	<b>FRC/X</b>	8479, 5011, M518	31.07.2015
716/2009	ZCFC3575085693847 / <b>11003069</b>	<b>FRC/X</b>	8480, 5011, M518	31.07.2015
717/2009	ZCFC3575095797934 / <b>11003049</b>	<b>FRC/X</b>	8481, 5011, M518	31.07.2015
718/2009	WMAH09ZZZ3M362104 / <b>220206</b>	<b>FRC</b>	8482	12.08.2012
719/2009	VF1UDC1K641591367 / <b>11005259</b>	<b>FRC</b>	8483, 5547, M529	31.07.2015
720/2009	<b>WSMS7780000447084</b>	<b>FRC</b>	8484	10.08.2012
721/2009	<b>WSMS7480000451025</b>	<b>FRC</b>	8485	04.08.2012
722/2009	<b>WSMS7780000435563</b>	<b>FRC</b>	8486	13.08.2012
723/2009	<b>WSMS7480000452459</b>	<b>FRC</b>	8488	13.08.2012
724/2009	<b>WSMS7480000445342</b>	<b>FRC</b>	8489	13.08.2012
725/2009	<b>WSMS7480000431659</b>	<b>FRC</b>	8490	31.12.2011
726/2009	<b>WSMS7480000071190</b>	<b>FNA</b>	6576	11.09.2010
727/2009	<b>WSM00000005016119</b>	<b>FRC</b>	8492	19.08.2012
728/2009	<b>WSMS7480000560388</b>	<b>FRC</b>	8493	21.08.2012
729/2009	VK1S338RJP101335 / <b>203348</b>	<b>FRC</b>	8495	24.08.2012
730/2009	<b>WSM00000005030893</b>	<b>FRC</b>	8496, 07 1311, M576	16.11.2013
731/2009	<b>WSMS7480000450229</b>	<b>FRC</b>	8497	24.08.2012
732/2009	VM3LVFS3F24R04647 / <b>02C0634.001</b>	<b>FRC</b>	8498	24.08.2012
733/2009	<b>WSMS7480000438611</b>	<b>FRC</b>	8499	10.08.2012
734/2009	<b>WSM00000005017152</b>	<b>FRC</b>	8500	14.08.2012
735/2009	<b>WSM00000005025357</b>	<b>FRC</b>	8501, 07 1303, MR79	02.07.2013
736/2009	<b>WSM00000005012608</b>	<b>FRC</b>	8502	23.07.2012
737/2009	WKESDR27011388775 / <b>28103</b>	<b>FRC</b>	8503	18.08.2012
738/2009	WKESDR27011380825 / <b>27464</b>	<b>FRC</b>	8504	26.08.2012
739/2009	<b>WSM00000005000214</b>	<b>FRC</b>	8505	21.08.2012
740/2009	<b>WSM00000005006388</b>	<b>FRC</b>	8506	21.08.2012
741/2009	VM4CD381J1A010198 / <b>49279</b>	<b>FRC</b>	8507	27.08.2012
742/2009	<b>WSM00000005009081</b>	<b>FRC</b>	8508	18.08.2012
743/2009	VM3LVFS3F31R06682 / <b>03C0239.002</b>	<b>FRC</b>	8509	21.08.2012
744/2009	WKESDR27011266453 / <b>25597</b>	<b>FRC</b>	8510	22.08.2012
745/2009	<b>WKESDR270111387111</b>	<b>FRC</b>	8511	22.08.2012
746/2009	<b>SMSS7780000700104</b>	<b>FRC</b>	8512	22.08.2012
747/2009	WKESDR27041201923 / <b>29479</b>	<b>FRC</b>	8513	22.08.2012
748/2009	VM3LVFS3FY1R01942 / <b>00C2461.002</b>	<b>FRC</b>	8514	22.08.2012
749/2009	<b>WKESDR27011277050</b>	<b>FRC</b>	8515	22.08.2012
750/2009	VF622CVA000109538 / <b>98-28071</b>	<b>FRC</b>	8516	31.01.2011
751/2009	WKESDR27011378414 / <b>26755</b>	<b>FRC</b>	8517	22.08.2012
752/2009	VM3LVFS3EX1R08864 / <b>99/C0112-001</b>	<b>FRC</b>	8518	28.02.2011
753/2009	<b>WSMS7480000448548</b>	<b>FRC</b>	8519	27.08.2012
754/2009	<b>WSMS7480000442791</b>	<b>FRC</b>	8520	30.08.2012

755/2009	<b>WKESDR27011386566</b>	<b>FRC</b>	8521	29.08.2012
756/2009	WKESDR27011272439 / <b>26090</b>	<b>FRC</b>	8522	29.08.2012
757/2009	<b>WSMS7480000438150</b>	<b>FRC</b>	8523	31.08.2012
758/2009	<b>WSMS7480000443902</b>	<b>FRC</b>	8524	29.08.2012
759/2009	<b>WSM00000005018312</b>	<b>FRC</b>	3374T, MR79	08.2012
760/2009	YV2E4C4A3VB179327 / <b>116078</b>	<b>FNA</b>	8526	28.08.2015
761/2009	<b>WSM00000005029894</b>	<b>FRC</b>	8527, 07 1296, M576	20.06.2013
762/2009	<b>WKESD000000422150</b>	<b>FRC</b>	8528	30.07.2012
763/2009	<b>SMSS7780000700411</b>	<b>FRC</b>	8529	02.09.2012
764/2009	VAW3SNK36SYY07686 / <b>PB116B066</b>	<b>FNA</b>	6577	11.09.2010
765/2009	<b>WKESD000000452706</b>	<b>IR</b>	8531, 3392T	16.04.2015
766/2009	WKESD000000453854 / <b>2328</b>	<b>IR</b>	8532, 3392T	31.05.2015
767/2009	<b>SMSS7780000990619</b>	<b>FNA</b>	8533	29.08.2012
768/2009	<b>WSMS7780000099242</b>	<b>FNA</b>	8534	29.08.2012
769/2009	<b>WSMS7780000402090</b>	<b>FNA</b>	8535	29.08.2012
770/2009	<b>WSMS7480000408937</b>	<b>FNA</b>	8536	29.08.2012
771/2009	<b>WSMS7480000406086</b>	<b>FNA</b>	8537	29.08.2012
772/2009	<b>WSMS7480000452648</b>	<b>FRC</b>	8538	04.09.2012
773/2009	<b>WSMS7480000448243</b>	<b>FRC</b>	8539	07.09.2012
774/2009	<b>WSM00000005039982</b>	<b>FRC</b>	8540, 3348T, MR79	19.03.2014
775/2009	<b>WSM00000005058286</b>	<b>FRC</b>	8541, 3348T, MR79	31.08.2014
776/2009	<b>WSMS7480000444382</b>	<b>FRC</b>	8542	06.09.2012
777/2009	<b>WSMS7480000438092</b>	<b>FRC</b>	8543	06.09.2012
778/2009	<b>WSMS7480000434469</b>	<b>FRC</b>	8544	30.06.2012
779/2009	VM3LVFS3FY1A01542 / <b>00C1054-001</b>	<b>FRC</b>	8545	31.05.2012
780/2009	<b>WKESDR27011380783</b>	<b>FRC</b>	8546	06.09.2012
781/2009	<b>WSMS7480000433791</b>	<b>FRC</b>	8547	30.04.2012
782/2009	WKESDR27041201829 / <b>29603</b>	<b>FRC</b>	3285T; MR81	09.2010
783/2009	WDB9061531N425646 / <b>11004649</b>	<b>FRC/X</b>	8549, 5547, M486	31.08.2015
784/2009	WDB9061331N426001 / <b>11004639</b>	<b>FRC/X</b>	8550, 5011, M518	31.08.2015
785/2009	ZCFC35A80A5802099 / <b>11005439</b>	<b>FNA/X</b>	8551, 6653, MR76	31.08.2015
786/2009	WKESD000000452926 / <b>2291</b>	<b>IR</b>	8552, 3392T	30.04.2015
787/2009	WKESD000000452927 / <b>2292</b>	<b>IR</b>	8553, 3392T	06.05.2015
788/2009	<b>WK0SVKT24V9886689</b>	<b>FNA</b>	8554	29.08.2012
789/2009	WKESD000000452925 / <b>2290</b>	<b>IR</b>	8555, 3392T	30.04.2015
790/2009	VM3LVFSFX1R00748 / <b>99/C2166-001</b>	<b>FRC</b>	8556	30.11.2011
791/2009	WKESD000000431611 / <b>1316</b>	<b>FRC</b>	8557, 3392T, M509	31.03.2014
792/2009	<b>WSMS7480000094177</b>	<b>FRC</b>	8558	31.12.2010
793/2009	<b>WSMS7480000094183</b>	<b>FRC</b>	8559	31.12.2010
794/2009	WDB9702471K511189	<b>FNA</b>	8560	09.09.2015
795/2009	VM3LVFS3EW1A07611 / <b>98/C0902.001</b>	<b>FNA</b>	8566	08.09.2012
796/2009	VM3LVFS3F31R06681 / <b>03C0239.001</b>	<b>FRC</b>	8561	03.09.2012
797/2009	<b>WSM00000005030054</b>	<b>FRC</b>	8562, 07 1310, M576	18.10.2013
798/2009	<b>WSMS7480000450163</b>	<b>FRC</b>	8563	20.08.2012
799/2009	<b>WK0S0002400109935</b>	<b>FRC</b>	8564, 3365T, MR79	25.08.2015
800/2009	VM3LVFS3F31R06683 / <b>03C0239.003</b>	<b>FRC</b>	8565	05.09.2012
801/2009	<b>WSM00000005055969</b>	<b>FRC</b>	8572, 3421T, M528	14.05.2014
802/2009	WKESDR27011391699 / <b>28252</b>	<b>FRC</b>	8567	04.09.2012
803/2009	WKESDR27011264565 / <b>25525</b>	<b>FRC</b>	8568	04.09.2012
804/2009	WK0SVKT24V9184980 / <b>512985</b>	<b>FRC</b>	8569	05.09.2012
805/2009	<b>WSMS7480000450193</b>	<b>FRC</b>	8570	07.09.2012
806/2009	<b>WSMS7480000452650</b>	<b>FRC</b>	8571	07.09.2012
807/2009	WKESDR27011380811 / <b>27351</b>	<b>FRC</b>	8573	09.09.2012
808/2009	<b>WSMS7480000450400</b>	<b>FRC</b>	8574	10.09.2012
809/2009	<b>WSM00000005060891</b>	<b>FRC</b>	05 1248, M602	30.03.2015
810/2009	VM3LVFS3FX1R00505 / <b>99/C1179-002</b>	<b>FRC</b>	8576	31.07.2011
811/2009	<b>WSM00000005017219</b>	<b>FRC</b>	8577	14.09.2012
812/2009	<b>WSMS74800004477072</b>	<b>FRC</b>	8578	10.09.2012
813/2009	<b>WK0SVKA24Y0265160</b>	<b>FRC</b>	8579	11.09.2012
814/2009	VM3LVFS3FX1A00753 / <b>99/C2199.001</b>	<b>FRC</b>	8580	30.11.2011
815/2009	<b>VM4S3381GVA037357</b>	<b>FNA</b>	8581	12.09.2012

816/2009	WSM0000005041911	FRC	8582, 07 1269, M523	28.03.2014
817/2009	WSM0000005028552	FRC	8583, 07 1269, MR79	22.05.2013
818/2009	WSMS7780000438971	FRC	8584	11.09.2012
819/2009	VM3LVFS3EX1R09861 / 99.C2049.001	FRC	8585	28.02.2011
820/2009	WSMS7780000432989	FRC	8586	28.01.2012
821/2009	WSM0000005041191	FRC	8587, 3319T, MR79	15.04.2014
822/2009	WSM0000005017323	FRC	8588	11.09.2012
823/2009	WSMS7780000436037	FRC	8589	11.09.2012
824/2009	VM3LVFS3FY1R02081 / 00C2665.010	FRC	8590	12.09.2012
825/2009	WSM0000005028553	FRC	8591, 07 1269, MR79	30.05.2013
826/2009	WSMS7480000442051	FRC	8592	12.09.2012
827/2009	VM3LVFS3EV3R05310 / 96.C1857.001	FNA	8593	12.09.2012
828/2009	WKESDR27051234611 / 32326	FRC	8594	12.09.2012
829/2009	WSMS6980000750969	FRC	8595	11.09.2012
830/2009	WKESDR27011497838	FNA	8598	08.09.2009
831/2009	113088 / 96C1298.001	FNA	8599	11.08.2012
832/2009	ZE5368SP6FJKL0088 / 033	FRC	8600	11.08.2012
833/2009	YF104ST3SYF019677	FNA	8601	11.08.2012
834/2009	WSMS7480000402453	FNA	8596	15.09.2012
835/2009	WKESDR27011383582 / 27336	FRC	8597	15.09.2012
836/2009	WSMS7480000451963	FRC	8602	17.09.2012
837/2009	WK0SVKT2450736209 / 60792	FRC	5344, BX4933, MR81	10.2010
838/2009	WSM0000005003825	FRC	8604	10.09.2012
839/2009	VM3LVFS3FX1R00788 / 99.C2292-002	FRC	8605	30.11.2011
840/2009	VFKTF34C1V3RB2027 / 97/C0502.002	FNA	8606	16.09.2012
841/2009	WK0SVKT24W9821145	FRC	8607	31.12.2010
842/2009	TRGSAF335WD128064	FNA	8608	22.09.2012
845/2009	WSM0000005008271	FRC	3252T, MR79	07.2011
846/2009	VM3LVFS3F11R02464 / 01C3816.001	FRC	8612	22.09.2012
847/2009	WSMS7480000453965	FRC	8613	17.09.2012
848/2009	WSMS7780000457427	FRC	8614	18.09.2012
849/2009	WDB9702551L398451 / 11004149	FNA/X	8615, 4968, M517	31.07.2015
850/2009	WDB9702551L399711 / 11004159	FNA/X	8616, 4968, M517	31.07.2015
851/2009	WDB9702551L411694 / 11004139	FNA/X	8617, 4968, M517	31.07.2015
852/2009	WSMS7480000451401	FRC	8618	23.09.2012
853/2009	WSMS7480000452651	FRC	8619	23.09.2012
854/2009	WSMS7480000454107	FRC	8620	23.09.2012
855/2009	WK0S0002400084328	FRC	8621, 3365T, M511	23.11.2013
856/2009	WSMS7480000090621	FNA	8622	21.09.2012
857/2009	W091543381HS09648 / 021UF3840	FRC	8623	21.09.2012
858/2009	WSMS7480000451279	FRC	8624	21.09.2012
859/2009	WK0S0002400109937	FRC	8625, 3365T, MR79	07.09.2015
860/2009	WK0S0002400109938	FRC	8626, 3365T, MR79	07.09.2015
861/2009	WK0S0002400109939	FRC	8627, 3365T, M602	08.09.2015
862/2009	WSMS7480000455565	FRC	8628	23.09.2012
863/2009	VM3LVFS3FY1A01258 / 00C1004.001	FRC	8629	23.06.2012
864/2009	WSMS7480000450198	FRC	8630	23.09.2012
865/2009	WSM0000005029423	FRC	8631, 07 1303, M580	31.05.2013
866/2009	WSM0000005062579	FRC	8632, 3404T, MR79	18.09.2015
867/2009	WSM0000005062580	FRC	8633, 3040T, M509	18.09.2015
868/2009	WSMS7480000457714	FRC	8634	25.09.2012
869/2009	WO9001335WMT35102 / 35102	FRC	8635	31.12.2012
870/2009	WSMS7480000453201	FRC	8636	25.09.2012
871/2009	WSMS7480000450220	FRC	8637	28.09.2012
873/2009	WSM0000005030055	FRC	8639	25.09.2012
874/2009	WSM0000005033181	FRC	8640, 07 1303, M576	14.05.2013
875/2009	VM4CD381J3A011934 / 57894	FRC	8641	27.09.2012
876/2009	WSMS7480000436721	FRC	8642	26.09.2012
877/2009	SUDNS1CTZ62008974 / 133UD7451	FRC	8643	26.09.2012
878/2009	VM4C381BRWA004136 / 39558	FNA	8644	26.09.2012
879/2009	WMAT378284W036994 / 161543	FRC	8645	30.04.2011

880/2009	<b>WSMS7480000433265</b>	<b>FRC</b>	8646	22.03.2012
881/2009	<b>WKOSVKT24V9178563</b>	<b>FNA</b>	8647	26.09.2012
882/2009	<b>WSMS7480000433707</b>	<b>FRC</b>	8648	30.04.2012
883/2009	<b>WSM00000005030052</b>	<b>FRC</b>	8649, 07 1303, M576	11.10.2013
884/2009	<b>WSMS7480000453145</b>	<b>FRC</b>	8650	30.09.2012
885/2009	<b>WK0SVKA24Y0266939</b>	<b>FRC</b>	8651	30.09.2012
886/2009	<b>WSM00000005019236</b>	<b>FRC</b>	8652	02.10.2012
887/2009	WKESDR27011387206 / <b>27748</b>	<b>FRC</b>	8653	02.10.2012
888/2009	WKESD000000452924 / <b>2289</b>	<b>IR</b>	8654, 3392T	30.04.2015
889/2009	VM3LVFS3F31R07178 / <b>03C0989.001</b>	<b>FRC</b>	8655	01.10.2012
890/2009	<b>WSMS7480000453199</b>	<b>FRC</b>	8656	02.10.2012
891/2009	<b>WSMS7480000455560</b>	<b>FRC</b>	8657	01.10.2012
892/2009	<b>502077</b>	<b>FNA</b>	8658	02.10.2012
893/2009	<b>990301</b>	<b>FRC</b>	8659	01.10.2011
894/2009	<b>WK0SVKT24Y9853064</b>	<b>FRC</b>	8660	28.04.2012
895/2009	<b>WSM00000005027459</b>	<b>FRC</b>	8661, 07 1310, M576	03.04.2013
896/2009	<b>WSMS7480000450155</b>	<b>FRC</b>	8662	05.10.2012
897/2009	<b>YE13B0045AA082164</b>	<b>FNA</b>	8663	06.10.2012
898/2009	<b>VFKTX34VW22FX0166</b>	<b>FRC</b>	8664	06.10.2012
899/2009	<b>WSM00000005016797</b>	<b>FRC</b>	8665	13.08.2012
900/2009	WFDFLT33541001407 / <b>11006634</b>	<b>FNA</b>	4559.26	22.07.2010
901/2009	WFDFLT33541001409 / <b>11006654</b>	<b>FNA</b>	4559.28	22.07.2010
902/2009	WFDFLT33541001408 / <b>11006644</b>	<b>FNA</b>	4559.27	22.07.2010
903/2009	WFDFLT33541001405 / <b>11006614</b>	<b>FNA</b>	4559.24	15.07.2010
904/2009	WFDFLT33541001406 / <b>11006624</b>	<b>FNA</b>	4559.25	15.07.2010
905/2009	VM3LVFS3F31R06616 / <b>03C0095.006</b>	<b>FRC</b>	8677	10.10.2012
906/2009	VFKTF34CAX2XB0535 / <b>01C0782.001</b>	<b>FRC</b>	8678	08.10.2012
907/2009	YV2E4C318X1921263 / <b>99/C0080-002</b>	<b>FRC</b>	8679	22.02.2011
908/2009	WMAT36ZZZYW039117 / <b>45156</b>	<b>FRC</b>	8680	08.02.2012
909/2009	<b>YV2A4B2C7WB188191</b>	<b>FNA</b>	8681	09.10.2012
910/2009	WKESDR27011157715 / <b>24906</b>	<b>FRC</b>	8671	09.10.2012
911/2009	VM4381BRWA004227 / <b>39474</b>	<b>FRC</b>	8672	31.12.2010
912/2009	<b>WSM00000005012076</b>	<b>FRC</b>	8673	09.10.2012
913/2009	<b>WSMS7480000438716</b>	<b>FRC</b>	8674	10.10.2012
914/2009	<b>WSM00000005035855</b>	<b>FRC</b>	8675	18.10.2013
915/2009	<b>WSM00000005000067</b>	<b>FRC</b>	8676	10.10.2012
916/2009	<b>WSMS7480000458491</b>	<b>FRC</b>	8682	12.10.2012
917/2009	<b>WSMS7480000454108</b>	<b>FRC</b>	8683	13.10.2012
918/2009	<b>WSMS7480000454109</b>	<b>FRC</b>	8684	13.10.2012
919/2009	<b>WSMS7480000454110</b>	<b>FRC</b>	8685	13.10.2012
920/2009	<b>VVCS0RXBCS4301500</b>	<b>FRC</b>	8686	12.10.2012
921/2009	<b>WSM00000005011491</b>	<b>FRC</b>	8689	15.10.2012
922/2009	VF644AGE000006906 / <b>11003909</b>	<b>FRC</b>	8687, 7382, M593	30.09.2015
923/2009	WDB9702581L393991 / <b>11006039</b>	<b>FNA</b>	8688, 6336, M538	31.10.2015
924/2009	<b>WSMS7480000453179</b>	<b>FRC</b>	8690	16.10.2012
925/2009	<b>WSMS7480000451486</b>	<b>FRC</b>	8691	14.10.2012
926/2009	VM3LVFS3EY1R10365 / <b>01C1343.001</b>	<b>FRC</b>	8695	16.10.2012
927/2009	WK0SVKA24X0238794 / <b>02-38794</b>	<b>FRC</b>	8692	10.09.2011
928/2009	W09W00334YDT18S09 / <b>17000100D6</b>	<b>FRC</b>	8693	16.10.2012
929/2009	<b>WSMS7780000411601</b>	<b>FRC</b>	8694	29.09.2010
930/2009	<b>WSMS7480000450228</b>	<b>FRC</b>	8697	16.10.2012
931/2009	VM3LVFS3FY1R01319 / <b>00C1115.007</b>	<b>FRC</b>	8698	30.06.2012
932/2009	WKESDR27011269605 / <b>26153</b>	<b>FRC</b>	8699	19.10.2012
933/2009	<b>WSMS7480000445257</b>	<b>FRC</b>	8700	16.10.2012
934/2009	WKESDR27041218308 / <b>30944</b>	<b>FRC</b>	8701	16.10.2012
935/2009	WKESDR27041218307 / <b>30943</b>	<b>FRC</b>	8702	16.10.2012
936/2009	VM3LVFS3EV1R06215 / <b>97/C1399.001</b>	<b>FNA</b>	8703	19.10.2012
937/2009	VM3LVFS3ET1R05007 / <b>96/C1295.01</b>	<b>FNA</b>	8704	22.10.2012
938/2009	VM3LVFS3FX1R00813 / <b>99/C2390-001</b>	<b>FRC</b>	8705	31.12.2011
939/2009	VAVSAF3383H185396 / <b>123UG5796</b>	<b>FRC</b>	8706	20.10.2012
940/2009	<b>WSMS7780000435895</b>	<b>FRC</b>	8707	28.09.2012

941/2009	WK0SVKT2420299822	FRC	8708	21.10.2012
942/2009	WSMS7480000441998	FRC	8709	22.10.2012
943/2009	VM3LVFS3F36R06692 / 03C0242.001	FRC	8710	21.10.2012
944/2009	WSMS7480000445505	FRC	8711	23.10.2012
945/2009	VM3LVFS3FY1R01089 / 00C0336-022	FRC	8712	11.05.2012
946/2009	WDB9061331N431469 / 0909183	FNA/X	8713, 7788, M591A	23.10.2015
947/2009	WSMS7780000444551	FRC	8714	23.10.2012
948/2009	VM4CD381G3A011756 / 57019	FRC	8715	19.10.2012
949/2009	WSMS7480000454430	FRC	8716	23.10.2012
950/2009	VF645ACA000002634 / 201314	FRC	8717	26.10.2012
951/2009	VF624CPA000002577 / 11005659	FNA	8718, 6336, MR91	31.10.2015
952/2009	WMAN15ZZ6AY240242 / 11005999	FNA	8719, 6336, M568	31.10.2015
953/2009	ZCFC35A38A5807543 / 11005979	FNA/X	8720, 7327, M607	31.10.2015
954/2009	WMA18XZZ49P019097 / 11003569	FRC/X	8721, 6652, MR92	30.09.2015
955/2009	WK0SVKT24W9822651	FRC	8722	16.11.2011
956/2009	WSM00000005017879	FRC	06 1281, MR79	08.2012
957/2009	WSMS7480000445383	FRC	8724	27.10.2012
958/2009	WSMS7480000453324	FRC	8725	27.10.2012
960/2009	WSMS7780000070730	FNA	8727	27.10.2012
961/2009	WSMS7480000094182	FRC	8728	31.12.2010
962/2009	WSM00000005031622	FRC	8729	28.10.2012
963/2009	WSMS7480000561016	FRC	8730	29.10.2012
964/2009	WSMS7480000450223	FRC	8731	30.10.2012
965/2009	VM3LVFS3F31R07179 / 03C0989/002	FRC	8732	30.10.2012
966/2009	WSM00000005061635	FRC	05 1248, M602	11.09.2015
967/2009	WSMS7480000454431	FRC	8734	02.11.2012
968/2009	WSMS7480000447066	FRC	8735	03.11.2012
969/2009	WSMS7480000088297	FNA	8736	03.11.2012
970/2009	WSMS7480000090479	FNA	8737	03.11.2012
971/2009	WSMS7480000096007	FNA	8738	03.11.2012
972/2009	WSMS7480000438817	FRC	8739	03.11.2012
973/2009	WSMS7480000430891	FRC	8740	30.06.2011
974/2009	WSMS7480000447336	FRC	8741	02.11.2012
975/2009	WSMS7480000452289	FRC	8742	29.10.2012
976/2009	WSMS7780000448053	FRC	8743	02.11.2012
977/2009	WSMS7780000443198	FRC	8744	04.11.2012
978/2009	VM3LVFS3FY1A00911 / 00C3047.001	FRC	8745	30.04.2012
979/2009	VM3LVFS3ES1A03725 / 95.C1559.001	FNA	8746	02.11.2012
980/2009	XLDTXZ33900043315 / 39183	FRC	8747	29.03.2012
981/2009	WSMS7480000451917	FRC	8748	05.11.2012
982/2009	WSMS7480000453181	FRC	8749	02.11.2012
983/2009	WSMS7480000453180	FRC	8750	02.11.2012
984/2009	VV1F3FA1XSN110826 / C3 362	FRC	8751	05.11.2012
985/2009	WSM00000005029488	FRC	8752	06.11.2012
986/2009	WMAN14ZZ16Y170411 / 0909187	FNA	8753, 7788, M515	30.09.2015
987/2009	WSMS7480000435449	FRC	8754	21.08.2012
988/2009	VM3LVFS3F31R06613 / 03C0095.003	FRC	8755	09.11.2012
989/2009	VM3LVFS3F31R06615 / 03C0095.005	FRC	8756	06.11.2012
990/2009	YV2TN12A2AB551942 / 11005319	FRC	8757, 7328, M572	31.10.2015
991/2009	YS2R6X20002045012 / 11007409	FRC	8758, 6652, M578	31.10.2015
992/2009	276078	IR	8759	10.11.2015
993/2009	WSMS7780000455481	FRC	8760	12.11.2012
994/2009	WSMS7780000404525	FNA	8763	07.11.2012
995/2009	VM3LVFS3E31R10954 / 03C0003.098	FRC	8764	07.11.2012
996/2009	VM3LVFS3F11R02336 / 01C3428.001	FRC	8762	10.11.2012
997/2009	VM4CD381JYA001654 / 47538	FRC	8761	30.09.2012
998/2009	XLRAS47XS0E658819	FRC	8765	13.11.2012
999/2009	WKEZZW18041200811 / 511871	FRC	8766	13.11.2012
1000/2009	VM3LVFS3FY1A00873 / 00/C3009.001	FRC	8767	31.01.2012
1001/2009	WKESDR27011266939	FRC	8768	08.11.2012
1002/2009	WKESDR27011266943	FRC	8769	08.11.2012

1003/2009	WSMS7780000403502	FRC	8770	11.10.2011
1004/2009	WSM00000005053759	FRC	8771, 07 1328, MR79	03.03.2014
1005/2009	WSMS7480000454261	FRC	8772	12.11.2012
1006/2009	VM3LVFS3FY1R01081 / 00C0336-014	FRC	8773	31.03.2012
1007/2009	WSMS7480000455138	FRC	8774	16.11.2012
1008/2009	WSMS7480000560142	FRC	8775	10.11.2012
1009/2009	WSM00000005032374	FRC	8776, 05 1248, M528	17.08.2013
1010/2009	WSM00000005039987	FRC	8777, 05 1248, MR79	22.01.2014
1011/2009	W091643381HS09244 / 01C1712.002	FRC	8778	16.11.2012
1012/2009	VAVSAF3385H218306 / 23591	FRC	5780, T2003/1692	30.09.2011
1013/2009	WSM0000000704923	FRC	8780	16.11.2012
1014/2009	VM3LVFS3ES1A03450 / 95C0863.001	FNA	8781	14.11.2012
1015/2009	VM3LVFS3FY1R01086 / 00C0336.019	FRC	8782	31.03.2012
1016/2009	WSMS7480000453970	FRC	8783	12.11.2012
1017/2009	WDB9502031K762148 / 161588	FRC	8784	31.03.2011
1018/2009	WSMA7420000074318	FNA	8785	12.11.2012
1019/2009	WSMS7480000440489	FRC	7253	26.05.2011
1020/2009	WSMS7480000093108	FNA	8788	16.11.2012
1021/2009	VM3LVFS3FY1R01654 / 01C1896/001	FRC	8789	12.11.2012
1022/2009	WSM00000005001024	FRC	8794	18.11.2012
1023/2009	WSMS7780000434609	FRC	8795	18.11.2012
1025/2009	VFNSYY3CPW0001019	FNA	8790	17.11.2012
1026/2009	WAFXXXXXXSZ016788	FNA	8791	17.11.2012
1027/2009	94123855	FNA	8792	17.11.2012
1029/2009	WKESDR27011378079 / 26866	FRC	8797	20.11.2012
1030/2009	WKESDR27011264553	FRC	8798	19.11.2012
1031/2009	WSMS7480000447513	FRC	8799	18.11.2012
1032/2009	WSMS7480000447525	FRC	8800	18.11.2012
1033/2009	WSMS7480000450167	FRC	8801	20.11.2012
1034/2009	WKESDR27011272463	FRC	8802	20.11.2012
1035/2009	VF644AEA000001948 / 100903	FRC/X	8803	21.11.2012
1036/2009	WFDFLT33531001501 / 11002483	FRC	8804	21.11.2012
1037/2009	WFDFLT33531001502 / 11002643	FRC	8805	21.11.2012
1038/2009	YA914703809942112	FNA	8806	21.11.2012
1039/2009	WSMS7480000447516	FRC	8807	23.11.2012
1040/2009	WSM00000005013080	FRC	5459, 05 269, M461	02.2012
1041/2009	WSM00000005017856	FRC	5906, 06 1281, 2849K	07.2012
1042/2009	VM4C381DNTA002318 / 34188	FNA	8810	23.11.2012
1043/2009	WSM00000005032394	FRC	8811, 3395T, MR79	07.09.2013
1044/2009	VM3LVFS3F51R11101 / 05C0454/002	FRC	8812	23.11.2012
1045/2009	WSMS7480000453203	FRC	8813	23.11.2012
1046/2009	WKESDR27051227890 / 32.009	FRC	8815	25.11.2012
1047/2009	WSMS7780000455211	FRC	8816	24.11.2012
1048/2009	WSMS7480000453968	FRC	8817	25.11.2012
1049/2009	I 220-2D / 11005369	IN	8818, 6336	31.08.2015
1050/2009	WKESDR27071315087	FNA	8819	25.11.2015
1051/2009	VM3LVFS3F41R09158 / 04C0928/014	FRC	8820	25.11.2012
1052/2009	WSMS7480000408959	FRC	8821	27.05.2011
1053/2009	WSMS7480000090634	FNA	8822	28.11.2012
1054/2009	WKESDR27041219210 / 31155	FRC	8823	28.11.2012
1055/2009	WSM00000005003552	FRC	8824	27.11.2012
1056/2009	VM3LVFS3F21R04267 / 02-C0005/005	FRC	8831	01.12.2012
1057/2009	VF644ACA000014546 / 11014385	FNA	5192, 3033K	10.2011
1058/2009	WK0S0002400109931	FRC	8833	01.12.2012
1059/2009	WSM00000005029839	FRC	8834, 07 1310, MR79	25.07.2013
1060/2009	XLER6X20004381567 / 97.C0301.004	FNA	8835	30.11.2012
1061/2009	XLER6X20005127614 / 50286	FRC	8836	04.12.2012
1062/2009	VK1S338FHVG000570 / 99298	FRC	8837	18.09.2012
1063/2009	WSMS7780000459125	FRC	8838	05.12.2012
1064/2009	WKESDR27011498131 / 29061	FRC	8839	05.12.2012
1065/2009	WSM00000005002272	FRC	8840	03.12.2012

1066/2009	<b>XLDTXZ33900040937</b>	<b>FNA</b>	8841	03.12.2012
1067/2009	<b>WSMS7480000433840</b>	<b>FRC</b>	8842	09.06.2012
1068/2009	<b>WK0SVKT24X0223954</b>	<b>FRC</b>	8843	31.08.2012
1069/2009	<b>WK0SVKT2420287452</b>	<b>FRC</b>	8844	30.11.2012
1070/2009	<b>WSMS7780000447079</b>	<b>FRC</b>	8845	01.12.2012
1071/2009	VM3LVFS3FW3A00029 / <b>98/C0450-006</b>	<b>FNA</b>	8846	07.12.2012
1072/2009	<b>WSM00000005051082</b>	<b>FRC</b>	8847, 07 1310, MR79	31.12.2014
1073/2009	VK1ST39WGRE820892 / <b>208473</b>	<b>FRC</b>	8848, T3895, MR79	30.09.2014
1074/2009	WKESDR27011386644 / <b>27897</b>	<b>FRC</b>	8849	07.12.2012
1075/2009	<b>WSM00000005017339</b>	<b>FRC</b>	8850	07.12.2012
1076/2009	VV1F3FA3XSN114626 / <b>C4 235</b>	<b>FRC</b>	8851	07.12.2012
1077/2009	<b>WSM00000005010640</b>	<b>FRC</b>	8852	08.12.2012
1078/2009	VM3LVFS3E21R10703 / <b>02C0518.002</b>	<b>FRC</b>	8853	09.12.2012
1080/2009	<b>WSMS7480000453152</b>	<b>FRC</b>	8855	11.12.2012
1081/2009	<b>WSM00000005032624</b>	<b>FRC</b>	8856, 3395T, M576	31.10.2014
1083/2009	WDB6520571K016992 / <b>97/C0983.001</b>	<b>FNA</b>	8858	10.12.2012
1084/2009	VM3LVFS3FY1R01069 / <b>00C0336.002</b>	<b>FRC</b>	8859	31.03.2012
1085/2009	<b>WSMS7480000453969</b>	<b>FRC</b>	8860	12.12.2012
1086/2009	<b>WSM00000005063542</b>	<b>FRC</b>	05 1248, M576	05.11.2015
1087/2009	<b>WSM00000005011019</b>	<b>FRC</b>	8862	12.12.2012
1088/2009	XLRAE75PC0E611598 / <b>49237</b>	<b>FRC</b>	8863	12.12.2012
1089/2009	<b>WSMS7780000095598</b>	<b>FNA</b>	8864	15.12.2012
1090/2009	<b>YE730PF38WH200255</b>	<b>FRC</b>	8865	01.03.2011
1091/2009	<b>WSMS7480000457666</b>	<b>FRC</b>	8866	15.12.2012
1092/2009	<b>WSM00000005013774</b>	<b>FRC</b>	8867	15.12.2012
1093/2009	<b>WSMS7480000083368</b>	<b>FNA</b>	8868	14.12.2012
1094/2009	VM3LVFS3ET1A04828 / <b>96/C1047-002</b>	<b>FNA</b>	8869	14.12.2012
1095/2009	<b>VM3LVFS3EV6R06446</b>	<b>FNA</b>	8870	14.12.2012
1096/2009	<b>WSM00000005015425</b>	<b>FRC</b>	8871	15.12.2012
1097/2009	<b>WSMS7780000454610</b>	<b>FRC</b>	8872	14.12.2012
1098/2009	<b>WSM00000005027530</b>	<b>FRC</b>	8873	11.12.2012
1099/2009	WFDFLT33551001582 / <b>11007715</b>	<b>FNA</b>	4525, M576	30.06.2011
1100/2009	WFDFLT33551001580 / <b>11007695</b>	<b>FNA</b>	4525, M576	30.06.2011
1101/2009	WFDFLT33551001581 / <b>11007685</b>	<b>FNA</b>	4525, M576	30.06.2011
1102/2009	WFDFLT33551001579 / <b>11007705</b>	<b>FNA</b>	4525, M576	30.06.2011
1103/2009	<b>210163</b>	<b>FRC</b>	8878	17.12.2012
1104/2009	WK0S0002400101834 / <b>11009479</b>	<b>FRC</b>	8879, 4838, M576	31.12.2015
1105/2009	<b>WSM00000005063002</b>	<b>FRC</b>	09 1414, M602	07.10.2015
1106/2009	<b>WSMS7480000450201</b>	<b>FRC</b>	8881	28.12.2012
1107/2009	<b>WK0SVKT24W9892776</b>	<b>FNA</b>	8882	23.12.2012
1108/2009	WKESDR27011388141 / <b>28.203</b>	<b>FRC</b>	8883	30.12.2012
1109/2009	<b>WSMS7780000441343</b>	<b>FRC</b>	8884	28.12.2012
1110/2009	<b>WSMS7480000444735</b>	<b>FRC</b>	8885	28.12.2012
1111/2009	<b>WSM00000005003016</b>	<b>FRC</b>	8886	28.12.2012
1112/2009	<b>WSMS7480000457690</b>	<b>FRC</b>	8887	28.12.2012
1113/2009	<b>WSM00000005003009</b>	<b>FRC</b>	8888	28.12.2012
1114/2009	VM3LVFS3E21R10811 / <b>02C2066.001</b>	<b>FRC</b>	8889	28.12.2012
1115/2009	<b>WSMS7480000450359</b>	<b>FRC</b>	8890	28.12.2012
1116/2009	<b>WSM7480000452299</b>	<b>FRC</b>	8891	28.12.2012
1117/2009	<b>WSM00000005007298</b>	<b>FRC</b>	8892	28.12.2012
1118/2009	<b>210699</b>	<b>FRC</b>	8893	28.12.2012
1119/2009	<b>WSMS7480000452325</b>	<b>FRC</b>	8937	24.11.2012