

Spis świadectw wydanych przez COCH w 2010 r.

Numer świadectwa	Numer identyfikacyjny (punkt 3 świadectwa)	Uznaje się jako (punkt 6 świadectwa)	Nr protokołu badań (punkt 7.2.3 świadectwa)	Data ważności świadectwa (pkt.8)
1	2	3	4	5
001/2010	WSMS7480000453972	FRC	8894	04.01.2013
002/2010	CH 186 / 0911242	IR	8903	05.01.2016
003/2010	WK0SVKT24V0289537 / 512979	FRC	8895	02.01.2013
004/2010	W09000225E0R23612	FRC	8896	05.01.2013
005/2010	WSMS7480000441902	FRC	8897	05.01.2013
006/2010	WSMS7480000434285	FRC	8898	05.01.2013
008/2010	WSMS7780000459124	FRC	8900	05.01.2013
009/2010	WSMS7780000459122	FRC	8901	05.01.2013
010/2010	WSMS7780000459121	FRC	8902	05.01.2013
011/2010	WDB9302051L457600 / 0910189	FRC	8904, 8903, M525	31.12.2015
012/2010	WDB9302051L457601 / 0910190	FRC	8905, 8903, M525	31.12.2015
013/2010	WDB9302051L457397 / 0910191	FRC	8906, 8903, M525	31.12.2015
014/2010	WDB9302051L457599 / 0910192	FRC	8907, 8903, M525	31.12.2015
015/2010	WSMS7480000454045	FRC	8908	05.01.2013
016/2010	WSMS7480000453966	FRC	8909	05.01.2013
017/2010	WSMS748000094023	FNA	8910	05.01.2013
018/2010	WSMS7480000560263	FRC	8911	04.01.2013
019/2010	WSM00000005010866	FRC	8912	04.01.2013
020/2010	WK0S0002400090555	FRC	8913, 3388T, M576	12.11.2013
021/2010	WSM00000005061637	FRC	05 1248, M602	01.10.2015
022/2010	WSM00000005015583	FRC	8915, 07 1311, MR79	07.11.2013
023/2010	YE7SD3AASN3202923 / F3001.451783	FRC	8916	06.01.2013
024/2010	WSM00000005011189	FRC	8917	07.01.2013
025/2010	WSM00000005031522	FRC	8918	06.01.2012
026/2010	VM3LVFS3F44A09213 / 04C0985/002	FRC	8919	07.01.2013
027/2010	W09109335THS09420 / 9298	FNA	8920	07.01.2013
028/2010	VM3LVFS3EV1R05304 / 96/C1651.003	FNA	8921	07.01.2013
029/2010	VM3LVFS3EV1R05475 / 97/C0291.001	FNA	8922	07.01.2013
030/2010	VM3LVFS3EV1R06593 / 97/C1835-002	FNA	8923	07.01.2013
031/2010	WDF9402031B968338 / 11008209	FRC	8924, 6652, MR92	30.11.2015
032/2010	WDB9702751L460650 / 11008199	FRC	8925, 7328, M568	30.11.2015
033/2010	WSMS7480000453078	FRC	8926	08.01.2013
034/2010	VM4C381BRWA004254 / 40124	FNA	8927	08.01.2013
035/2010	WSMS7480000094025	FNA	8928	09.01.2013
036/2010	SUDNS1CTZ84017927 / 11008528	FRC	8929, 4838, M573	31.12.2015
037/2010	WSMS7480000451045	FRC	8930	12.01.2013
038/2010	VFNSYY3CXWAR16727 / 3517	FRC	8931	31.01.3011
039/2010	VS93105SNVL052459 / 38011	FNA	8932	12.01.2013
040/2010	YV2J4CJC33B326151 / 208242	FNA/X	8933	11.01.2013
041/2010	WSMS7480000436023	FRC	8934	13.01.2013
042/2010	WDB9046121R475541 / 03C2169/001	FRC/X	8935	08.01.2013
043/2010	WSMS7480000095704	FNA	8936	14.01.2013
044/2010	WSMS7480000442121	FRC	8939	19.01.2013
045/2010	WSMS7480000455078	FRC	8940	15.01.2013
046/2010	WSMS7480000455905	FRC	8941	15.01.2013
047/2010	WSMS7480000416606	FRC	8942	01.03.2011
048/2010	VM3LVFS3F11R02453 / 01C3805.001	FRC	8943	15.01.2013
049/2010	WSM00000005038786	FRC	8944, 07 1335, MR79	30.04.2014
050/2010	WK0SVKT24W0223910	FRC	8945	13.01.2011
051/2010	WK0SVKT24V9888168	FNA	8946	21.01.2013
052/2010	WSMS7480000405854	FNA	8947	21.01.2013
053/2010	WSMS7480000093097	FNA	8948	21.01.2013
054/2010	WK0SVKT24X9838353	FRC	8949	31.12.2011
055/2010	WKESDR27051236329 / 32834	FRC	8950	22.01.2013
056/2010	VFKTF34C1W3RB2232 / 39961	FNA	8951	21.01.2013
057/2010	WSMS7480000402465	FRC	8952	31.12.2011

058/2010	WSMS7780000436818	FRC	8954	08.12.2012
059/2010	VM4CD381GSA011541	FRC	8953	25.01.2013
060/2010	VM3LVFS3F61R14747 / 06C2338/003	FRC	8955	21.01.2013
061/2010	WSM00000005064373	FRC	09 1414, M576	07.12.2015
062/2010	WFDFLT33531000180	FRC	8957	27.01.2013
063/2010	WDB9702771L459913 / 11008739	FNA/X	8958, 6336, M589	31.12.2015
064/2010	WDB9702771L459912 / 11008729	FNA/X	8959, 6336, M589	31.12.2015
065/2010	WSMS7480000449792	FRC	8960	27.01.2013
066/2010	VM3LVFX3FX1R00527 / 99/C1204.001	FRC	8961	30.06.2011
067/2010	YE730PF384H203217 / F7001.452397	FRC	8962	01.02.2013
068/2010	WSMS7480000097006	FNA	8963	01.02.2013
069/2010	WSM00000005013996	FRC	8964	01.02.2013
070/2010	WSM00000005002497	FRC	8965	28.01.2013
071/2010	VFKTF34C1V3RB3066 / 97233	FNA	8966	28.01.2013
072/2010	VVCSORXBCS4401926 / 22481	FRC	8967	28.01.2013
073/2010	VM3LVFS3EX1R08993 / 99C0464/001	FRC	8968	31.12.2011
074/2010	WSMS7480000457678	FRC	8969	28.01.2013
075/2010	WSM00000005010358	FRC	8970	28.01.2013
076/2010	VM3LVFS3FY1R01520 / 00C1263.003	FRC	8971	13.07.2012
077/2010	VM3LVFS3F31R05771 / 03C3722-001	FRC	8972	03.02.2010
078/2010	WSM00000005032165	FRC	8973, 07 1310, M576	30.09.2013
079/2010	XLDTXZ33900039769 / 21261	FNA	8974	04.02.2013
080/2010	YE7SD3AARN3202989 / 184198	FRC	8975	02.02.2013
081/2010	WSM00000005007154	FRC	8976	03.02.2013
082/2010	VM3LVFS3EW1R07468 / 98/C0788.004	FNA	8977	05.02.2013
083/2010	WSMS7480000448377	FRC	8978	07.02.2013
084/2010	WSMS7480000456806	FRC	8979	07.02.2013
085/2010	WSM00000005001449	FRC	8980	03.02.2013
086/2010	WSMS7480000457648	FRC	8981	03.02.2013
087/2010	WSM00000005001403	FRC	8982	03.02.2013
088/2010	WSMS7480000455570	FRC	8983	04.02.2013
089/2010	WSMS7780000459611	FRC	8984	04.02.2013
090/2010	WSMS7480000455768	FRC	8985	04.02.2013
091/2010	WSMS74800004447530	FRC	8986	09.02.2013
092/2010	VM3LVFS3EW1R07246 / 97/C2066-001	FNA	8987	08.02.2013
093/2010	VF644AMM000000677 / 11009169	FRC/X	8988, 7328, M538	31.12.2015
094/2010	VF644AMM000000667 / 11009179	FRC/X	8989, 7328, M538	31.12.2015
095/2010	WJME2NSH4A4373400 / 110002310	FNA	8990, 6336, M578	31.01.2016
096/2010	WDB9061551N434344 / 11009969	FRC/X	8991, 5547, M486	31.01.2016
097/2010	WDB9061551N435901 / 11009959	FRC/X	8992, 5547, M486	31.01.2016
098/2010	WSMS7480000452651	FRC	8619	23.09.2012
099/2010	WSMS7480000443538	FRC	8993	09.02.2013
100/2010	WKESDR27011277433 / 26.854	FRC	8994	09.02.2013
101/2010	WSM00000005015534	FRC	8995	09.02.2013
102/2010	WSMS7480000450219	FRC	8996	09.02.2013
103/2010	WSMS7480000416541	FRC	8997	09.02.2011
104/2010	WKESDR27041204508 / 29940	FRC	8998	10.02.2013
105/2010	WKESDR27041204510 / 29942	FRC	8999	10.02.2013
106/2010	WSMS7480000451918	FRC	9001	05.02.2013
107/2010	WSMS7480000450879	FRC	9002	05.02.2013
108/2010	WK0SVKT24V0290928	FNA	9003	05.02.2013
109/2010	WSM00000005013993	FRC	9004	08.02.2013
110/2010	VM3LVFS3EX4R09800 / 99/C1902.009	FRC	9005	29.10.2011
111/2010	WSMS7480000455563	FRC	9006	08.02.2013
112/2010	WKESDR27041205692 / 30007	FRC	9007	08.02.2013
113/2010	WSMS7480000435622	FRC	9008	06.10.2012
114/2010	WSMS7480000458144	FRC	9009	08.02.2013
115/2010	VFNSYY3KEXAR00568 / 45318	FRC	9010	22.12.2011
116/2010	VM3LVFS3F21R04335 / 02C0142.005	FRC	9011	08.02.2013
117/2010	VM3LVFS3F31R06617 / 03C0095.007	FRC	9012	09.02.2013
118/2010	WSM00000005041940	FRC	9013, 3261T, M576	28.02.2014

119/2010	SUDNS1CTZ72012752 / 11002757	FRC	6450, 4838, M576	30.04.2013
120/2010	WSMS7480000456804	FRC	9015	12.03.2013
121/2010	WSMS7480000455731	FRC	9016	12.03.2013
122/2010	VK1S338DHPF001532 / 20941	FRC	7050	15.03.2011
123/2010	VM3LVFS3ES3A03057 / 95.C0446.001	FNA	9018	12.02.2013
124/2010	6502 / 23504	FNA	9019	12.02.2013
125/2010	WKESDR27011387754 / 28025	FRC	9020	16.02.2013
126/2010	WSMS7480000443020	FRC	9021	13.02.2013
127/2010	WKESDR27011262247 / 25323	FRC	9022	16.02.2013
128/2010	ZCFA75A0402558371 / 11003319	FRC/X	9023, 5547, M529	31.08.2015
129/2010	XLRAS47MS0E870919 / 11008539	FRC	9024, 6652, M421	31.01.2016
130/2010	XLRAS47MS0E870930 / 11008549	FRC	9025, 7328, M578	31.01.2016
131/2010	WSMS7480000437210	FRC	9026	15.02.2013
132/2010	WSM00000005084572	FRC	09 1414, M576	11.01.2016
133/2010	WSM00000005062888	FRC	3341, M576	01.02.2016
134/2010	VM4C381BNWA003936 / 39335	FNA	9029	18.02.2013
135/2010	WSM00000005020767	FRC	06 1286, MR79	10.2012
136/2010	WSM00000005020766	FRC	06 1286, MR79	10.2012
137/2010	WSMS7480000436427	FRC	9032	31.01.2013
138/2010	82096	FNA	9033	18.02.2013
139/2010	VM3LVFS3EW1R07575 / 70218	FRC	9034	19.02.2013
140/2010	VS9SOR3NSV3057272 / 45555	FRC	9035	25.01.2012
141/2010	4125867	FNA	9036	19.02.2013
142/2010	SUDNS1CBZ71011557 / 11019446	FRC	9037	19.02.2013
143/2010	WKESDR27051247361 / 33647	FRC	9038	20.02.2013
144/2010	WSM00000005000659	FRC	9039	20.02.2013
145/2010	WSM00000005024845	FRC	9040	20.02.2013
146/2010	WSM00000005024848	FRC	9041	20.02.2013
147/2010	WSM00000005024847	FRC	9042	20.02.2013
148/2010	WSM00000005062875	FRC	9043, 3395T, MR79	31.01.2016
149/2010	WSMS7780000457166	FRC	9044	20.02.2013
150/2010	WSM00000005024063	FRC	9045	20.02.2013
151/2010	WKESDR27011267026 / 25911	FRC	9046	20.02.2013
152/2010	WSM00000005025345	FRC	9047	20.02.2013
153/2010	WSMS7780000433225	FRC	9048	29.02.2012
154/2010	WDB97002551K529313 / 99/C1922-005	FRC	9049	31.12.2011
155/2010	WSMS7480000437237	FRC	9051	23.02.2013
156/2010	WSMS7480000560055	FRC	9052	22.02.2013
157/2010	WSMS7480000443837	FRC	9054	22.02.2013
158/2010	WKESDR27041203084 / 29418	FRC	9055	24.02.2013
159/2010	WKESDR27041204511 / 29943	FRC	9056	24.02.2013
160/2010	WKESDR27041222331 / 31282	FRC	9057	24.02.2013
161/2010	XLRAS47XS1E546091 / 1071	FRC	9058	20.02.2013
162/2010	WKESDR27011272465 / 26295	FRC	9059	20.02.2013
163/2010	VM3LVFS3EW1R06905 / 98C0043-001	FNA	9060	20.02.2013
164/2010	SUDNS1CTZ48005889 / C08U/6673	FRC	9061	20.02.2013
165/2010	WDB6790231K197875 / 8517	FNA	9062	20.02.2013
166/2010	WSMS7480000444434	FRC	9063	19.02.2013
167/2010	WSM00000005064552	FRC	3441T, M602	13.01.2016
168/2010	WSM00000005064936	FRC	3441T, M602	15.01.2015
169/2010	WKESDR27011499129 / 29253	FRC	9068	27.02.2013
170/2010	WKESDR27011378354 / 29891	FRC	9069	27.02.2013
171/2010	VM3LVFS3F31R07527 / 03C1601-010	FRC	9070	27.02.2013
172/2010	SUDNS1CTZ48005887 / 006/6671	FRC	9071	27.02.2013
173/2010	WKESDR27011496207 / 28927	FRC	9072	27.02.2013
174/2010	XLRAS47XS0E715765 / 080855	FRC	9073	23.02.2013
175/2010	WSMS7480000436966	FRC	9076	25.01.2013
176/2010	WSMS7480000453471	FRC	9077	03.03.2013
177/2010	WK0S0002400101854 / 110005510	FRC	9078, 4838, M576	29.02.2016
178/2010	WK0S0002400101855 / 110002810	FRC	9079, 4838, M576	29.02.2016
179/2010	WSMS7480000457672	FRC	3319T, M576	31.05.2010

180/2010	WSM0000005012631	FRC	9081	03.03.2013
182/2010	WKESDR27041203081 / 29415	FRC	9083	03.03.2013
183/2010	VAVSAF3387H249860 / 25944	FRC	9084	03.03.2013
184/2010	WSM0000005000051	FRC	7115	03.04.2011
185/2010	VM4CD381J1A010187 / 49129	FRC	9086	01.03.2013
186/2010	VM3LVFS3F41R08329 / 04C0024.001	FRC	9087	02.03.2013
187/2010	WKESD000000460779 / 2767	FRC	9088, 3392T, MR79	31.01.2016
188/2010	WSM0000005016893	FRC	9089	03.03.2013
189/2010	WK0SVKT24Y0254567	FRC	9092	31.12.2012
190/2010	WSMS7480000449566	FRC	9091	05.03.2013
191/2010	WSMS7480000447533	FRC	9093	05.03.2013
192/2010	WSMS7480000447521	FRC	9094	05.03.2013
193/2010	WKESDR27041203083 / 29417	FRC	9095	08.03.2013
194/2010	WSM0000005062873	FRC	9096, 3441T, MR79	04.01.2016
195/2010	WSM0000005017806	FRC	9097	03.03.2013
196/2010	WSMS7780000081242	FNA	9098	03.03.2013
197/2010	WSM0000005065240	FRC	3348T, M605	04.02.2016
198/2010	WKESDR2704120512 / 29944	FRC	9100	09.03.2013
199/2010	VM3LVFS3F71R15405 / 07C0034/004	FRC	9101	10.03.2013
200/2010	WKESDR27011387823 / 27989	FRC	9102	08.03.2013
201/2010	WKESDR27041205699	FRC	9103	08.03.2013
202/2010	WKESDR27071315969	FRC	9104	08.03.2013
203/2010	VM3LVFS3EV4R05461 / 97/C0234.004	FNA	9105	03.03.2013
204/2010	VM3LVFS3EW1R06880 / 98/C0002-002	FNA	9106	05.03.2013
205/2010	WSMS7480000455575	FRC	9108	08.03.2013
206/2010	VF645ACA000008953 / 11020195	FNA	5496, 4152, MR71	28.08.2012
207/2010	WFDFLT33551000920 / 11000885	FRC	4838, M576	02.2010
208/2010	VM3LVFS3FY4R01729 / 00C1942.001	FRC	9112	31.12.2012
209/2010	WSM0000005042181	FRC	9113, 03 1142, MR79	09.06.2014
210/2010	VM3LVFS3F21R05347 / 02C1640.003	FRC	9114	10.03.2013
211/2010	WSMS7480000456107	FRC	8857	15.03.2013
212/2010	WKESD000000379019 / 38850	FRC	9116	13.03.2013
213/2010	WK0SVKT2440527251	FRC	9115	13.03.2013
214/2010	WKESDR27011266450 / 25594	FRC	9119	16.03.2013
215/2010	WSMS7480000448549	FRC	9122	01.03.2013
216/2010	WKESDR27011378735 / 26761	FRC	9120	15.03.2013
217/2010	WSMS7480000453967	FRC	9121	15.03.2013
218/2010	WKESDR27011378361 / 26400	FRC	9123	16.03.2013
219/2010	WKESDR27041203087 / 29421	FRC	9124	16.03.2013
220/2010	WKESDR27041203086 / 29420	FRC	9125	16.03.2013
221/2010	WSMS7480000437329	FRC	9126	16.01.2013
222/2010	WK0S0002400122624	FRC	9127, 0809, MR79	03.03.2016
223/2010	VV1F3FA3ASN133722 / 75628	FRC	9128, BX 4933, MR79	31.12.2013
224/2010	VM4CD382GYA020076	FRC	9129	19.01.2013
225/2010	WSM0000005028630	FRC	9130	16.03.2013
226/2010	WSMS7480000446594	FRC	9131	16.03.2013
227/2010	VM3LVFS3FY1R02020 / 00C2613/002	FRC	9132	31.01.2013
228/2010	VM4C381BRWA004650	FRC	9133	31.12.2011
229/2010	VVICHNLNBTS1Y00353 / 17367	FRC	9134	19.03.2013
230/2010	VM4CD382G1A020244 / 49531	FRC	9135	19.03.2013
231/2010	VM4CD382G1A020243 / 49530	FRC	9136	19.03.2013
232/2010	WK0S0002400117332	FRC	9137	22.03.2013
233/2010	WSMS7480000441832	FRC	9138	18.03.2013
234/2010	WKOSVKT24W9892029	FNA	9139	19.03.2013
235/2010	WSMS7480000455762	FRC	9140	19.03.2013
236/2010	WSM0000005062862	FRC	9141, 3441T, MR79	01.02.2016
237/2010	WSM0000005017937	FRC	9142	22.03.2013
238/2010	WKESD000000460780 / 2768	FRC	9143, 3392T, MR79	31.01.2016
239/2010	WSM0000005064570	FRC	09 1414, M602	08.02.2016
240/2010	WSM0000005064557	FRC	3441T, M602	08.02.2016
241/2010	WKESDR27011497842	FRC	9146	20.03.2013

242/2010	WSMS7480000452911	FRC	9147	20.03.2013
243/2010	WKESDR27011387757	FRC	9148	20.03.2013
244/2010	WSMS7450000438395	FRC	9149	20.03.2013
245/2010	WSMS7480000404558	FRC	9150	20.03.2013
246/2010	12787	FRC	9151	07.06.2011
247/2010	SFRRCVSA3WR204202 / IC98514902	FNA	9152	22.03.2013
248/2010	WSMS7780000445754	FRC	9153	23.03.2013
249/2010	WSMS7780000445757	FRC	9154	23.03.2013
250/2010	WSMS7480000456457	FRC	9155	23.03.2013
251/2010	WSM00000005016892	FRC	9156	25.03.2013
252/2010	WSMS7480000455265	FRC	9157	26.03.2010
253/2010	WSMS7480000457657	FRC	9158	26.03.2013
254/2010	WSMS7480000456043	FRC	9159	26.03.2013
255/2010	WSMS7480000457685	FRC	9160	29.03.2013
256/2010	W091633382HS09168 / 01C1918.007	FRC	7262	23.05.2011
257/2010	WKESDR27051226198	FRC	9162	29.03.2013
258/2010	WKESDR27011272458 / 26351	FRC	9163	30.03.2013
259/2010	WSMS7480000560053	FRC	9166	01.04.2013
260/2010	WKESDR27041209143 / 30.355	FRC	9167	07.04.2013
261/2010	WK0SVKT2430517805	FRC	9165	06.04.2013
262/2010	YV2TN12A1AB558137 / 110002510	FRC	9168, 7328, M572	31.03.2016
263/2010	WDB9702751L412157 / 11014618	FNA/X	9169, 6336, M581	31.03.2015
264/2010	ZCFA1TJ0492556788 / 110012098	FRC	9170, 7328, MR91	30.06.2015
265/2010	WDB9702651L463903 / 11009339	FRC/X	9171, 7328, 139-CPABO/ATP/03	29.02.2016
266/2010	WDB9702571L467680 / 110012610	FRC/X	9172, 7328, M662	29.02.2016
267/2010	WFDFLT33551001284 / 11004275	FRC	4838, M576	04.2011
268/2010	WSM00000005064558	FRC	3441T, M602	08.02.2016
269/2010	WSMS7480000438607	FRC	9174	06.04.2013
270/2010	WSMS7480000434818	FRC	9175	31.07.2012
271/2010	WKESDR27011387758 / 28024	FRC	9176	06.04.2013
272/2010	WSMS7480000455735	FRC	9177	06.04.2013
273/2010	WSMS7480000437812	FRC	9178	08.04.2013
274/2010	WSM00000005062863	FRC	9179, 3441T, M605	04.01.2016
275/2010	WK0SVKT24W9807784	FNA	9180	07.04.2013
276/2010	WSMS7480000458547	FRC	9181	07.04.2013
277/2010	WSMS7480000401026	FNA	9182	07.04.2013
278/2010	WSMS7480000458546	FRC	9183	07.04.2013
279/2010	WSMS7480000401025	FNA	9184	07.04.2013
280/2010	ZCFA1EF0242434909 / 11002734	FRC	9185	07.04.2013
281/2010	ZCFA1EF0242434910 / 11002724	FRC	9186	07.04.2013
282/2010	WKESDR27041204509 / 29.941	FRC	9188	08.04.2013
283/2010	VM3LVFS3F21R05613 / 02C3704.001	FRC	9187	07.04.2013
284/2010	WMAL82ZZZ1Y076359 / 49183	FRC	9189	10.04.2013
285/2010	WKESDR27041204941	FRC	9190	10.04.2013
286/2010	WKESDR27041204935	FRC	9191	10.04.2013
287/2010	WK0SVKT24Y9854507	FRC	9192	15.09.2012
288/2010	VM3LVFS3F11R02875 / 01C0542.001	FRC	9193	07.04.2013
289/2010	WDB9502031K595042 / 160260	FNA	9194	07.04.2013
290/2010	VM3LVFS3R41R09096 / 04C0862.001	FRC	9195	07.04.2013
291/2010	WSMS7480000437813	FRC	9196	07.04.2013
292/2010	WSMS7780000438438	FRC	9197	07.04.2013
293/2010	VM3LVFS3F11R02142 / 01C3014.001	FRC	9198	28.02.2013
294/2010	WSM00000005018265	FRC	9199	09.04.2013
295/2010	WMAN03ZZSAY245536 / 100221	FNA/X	9200	29.02.2016
296/2010	VVCS0RXBCS4702971	FRC	9201	14.04.2013
297/2010	WSMS7780000447062	FRC	9202	12.04.2013
298/2010	WSM00000005025326	FRC	9203	12.04.2013
299/2010	WSMS7480000447528	FRC	9204	13.04.2013
300/2010	VYV2AG10C6AB558804 / 110002210	FRC	9205, 6652, MR92	31.03.2016
301/2010	YS2G6X20002052367 / 110005910	FNA	9206, 6336, M632	07.04.2016
302/2010	WSMS7480000455788	FRC	9207	13.04.2013

303/2010	WSMS7780000457528	FRC	9208	13.04.2013
304/2010	VM3LVFS3E21R10688 / 02C0867.005	FRC	9209	14.04.2013
305/2010	WKESD000000461453 / 2832	FRC	9210	31.01.2016
306/2010	WKESDR27011387748 / 28019	FRC	9211	15.04.2013
307/2010	WKESD000000439622 / 001735	FRC	9212	16.04.2013
309/2010	WSM00000005065609	FRC	9214	01.04.2016
310/2010	VM3LVFS3FY1A00889 / 00C3025.001	FRC	9215	21.03.2012
311/2010	WSMS7480000440297	FRC	9216	19.04.2013
312/2010	W0900335FOR23902	FRC	9217	21.04.2013
313/2010	WSM00000005027834	FRC	9218	21.04.2013
314/2010	WSM00000005022466	FRC	9219	20.04.2013
315/2010	FO-TR L3H3 / PVIK-25/ATP08/01	IN	4882	15.12.2010
316/2010	IV-DA L3H2 / CF-056/ATP10/01	IN	5130	10.08.2011
317/2010	FO-CO L2H2 / PVIK-42/ATP09/01	IN	5209	01.04.2011
318/2010	ME-VI L2H1 / CF-099K/ATP11/01	IN	5474	05.04.2012
319/2010	VW-T5 L1H1 / CF-104K/ATP12/01	IR	5556	16.05.2012
320/2010	PE-BO L3H2 / CF-138/ATP13/01	IR	5937	25.10.2012
321/2010	FB4 / IP-1623/ATP16/01	IR	6619	29.08.2013
322/2010	FB4 / IP-1683/ATP17/01	IR	6741	21.11.2013
323/2010	FB3 / IP-1713/ATP18/01	IR	7013	20.02.2014
324/2010	FB3 / IP-1845/ATP20/01	IR	7484	02.09.2014
325/2010	WF0FXXTTFAY70699 / 110011810	FRC/X	9220, 5547, M486	12.04.2016
326/2010	ZCFC50A32A5823366 / 110015810	FRC/X	9221, 5011, M607	14.04.2016
327/2010	WSM00000005023230	FRC	3379T, MR79	16.03.2013
328/2010	YV2E4C4A4XB232524 / 05-41489	FRC	9234	31.05.2011
329/2010	WSMS7480000454818	FRC	9235	26.04.2013
331/2010	WSMS7480000443802	FRC	7731	27.12.2011
332/2010	WSM00000005063975	FRC	3441T, M602	17.11.2015
333/2010	WSM00000005061602	FRC	08 1390, M602	02.06.2015
334/2010	VFKTX34VCY2EX0521 / 48697	FRC	9222	30.11.2012
335/2010	VK1S338WCRE000034 / 204134	FRC	9223	24.04.2013
336/2010	VM3LVFS3EY1R10263 / 00C0958-001	FRC	9224	30.06.2012
337/2010	SUDNS1CTZ4X006154 / 046UL6740	FRC	9225	24.04.2013
338/2010	VS9SA3NS61A013385 / C13666	FRC	9226	28.03.2013
339/2010	WSM00000005006371	FRC	9227	26.04.2013
340/2010	WSM00000005003721	FRC	9228	25.04.2013
341/2010	WSM00000005021475	FRC	9229	26.04.2013
342/2010	VM4CD381J3A011983 / 58312	FRC	9237	28.04.2013
343/2010	WK0SVKT24V9888942	FNA	9240	28.04.2013
344/2010	WSMS7480000437811	FRC	9241	26.04.2013
345/2010	YV2TBM0A98B516144 / 11004878	FNA	9238, 4152, M452	30.11.2014
346/2010	WDB9702651K604745 / 729640	FRC	9239	28.04.2013
347/2010	WSM00000005022796	FRC	9242	27.04.2013
348/2010	WSMS7480000458084	FRC	9243	28.04.2013
349/2010	WSMS7480000434661	FRC	9244	05.07.2012
350/2010	SUDNS1CTZ47005738 / 087UG6593	FRC	9245	23.04.2013
351/2010	WSMS7480000444798	FRC	9246	27.04.2013
352/2010	WSMS7480000440157	FRC	9247	27.04.2013
353/2010	SV93101SS1YRN1021	FRC	9248	01.02.2012
354/2010	VM3LVFS3F41R09166 / 04C0943/1	FRC	9249	27.04.2013
355/2010	WSMS7480000444789	FRC	9250	27.04.2013
356/2010	WSMS7480000441970	FRC	9251	27.04.2013
357/2010	W09001335WMT35056	FNA	9252	27.04.2013
358/2010	WSM00000005002376	FRC	9253	27.04.2013
359/2010	WSMS7780000449821	FRC	9254	27.04.2013
360/2010	WSMS7480000458761	FRC	9255	27.04.2013
361/2010	WSMS7480000432193	FRC	9256	22.12.2012
362/2010	WDB9505381L014491 / 63832	FRC	9257	30.04.2013
363/2010	WSM00000005034823	FRC	9258	29.04.2013
364/2010	WSMS7480000437795	FRC	9259	31.03.2013
365/2010	WSMS748000043837	FRC	9260	29.04.2013

366/2010	WSMS7480000457683	FRC	9261	04.05.2013
367/2010	WKESDR27011389580 / 28416	FRC	9262	01.05.2013
368/2010	WSMS7480000447517	FRC	9263	01.05.2013
369/2010	WSM00000005041666	FRC	9264, 04 1234, MR79	21.10.2014
370/2010	WSMS7480000403045	FNA	9265	01.05.2013
372/2010	WSM00000005065621	FRC	9267, 09 1414, MR79	19.04.2016
373/2010	WSM00000005011400	FRC	6071, 3319T, 3150K	12.2011
374/2010	VM3LVFS3F24R04701 / 02C0738.001	FRC	9269	29.04.2013
375/2010	WSMS7480000437810	FRC	9270	30.04.2013
376/2010	WKESD000000461429 / 2811	FRC	9271, 3392T, MR79	31.01.2016
377/2010	WSMS7480000457692	FRC	9272	05.05.2013
378/2010	WSM00000005014225	FRC	9273	05.05.2013
379/2010	WKESDR27011157720 / 249411	FRC	9274	05.05.2013
380/2010	WSM00000005039422	FRC	9275, 07 1295, M576	31.05.2014
381/2010	WSMS7480000096025	FNA	9276	04.05.2013
382/2010	WK0SVKT24W9823920	FNA	9277	04.05.2013
383/2010	VM3LVFS3F31R006636 / 03C0132.001	FRC	9278	06.05.2013
384/2010	WKESDR27041204659 / 30.085	FRC	9279	06.05.2013
385/2010	VFNSYY3CXWAL18276	FNA	9280	06.05.2013
386/2010	VAVSAF3383H182362 / 003UI5028	FRC	9281	07.05.2013
387/2010	XLDTXZ33900041017 / 39186	FRC	9282	05.01.2012
388/2010	VM3LVFS3FY1R01576	FRC	9283	31.12.2012
389/2010	WGA30KS27SL241152	FRC	9284	08.05.2013
390/2010	VM3LVFS3F54R12160 / 05C1774/004	FRC	9285	08.05.2013
391/2010	WSM00000005058285	FRC	9286, 08 1360, MR79	31.12.2014
392/2010	WSM00000005066529	FRC	3441T, M602	23.03.2016
393/2010	WSM00000005066531	FRC	3441T, M602	23.03.2016
394/2010	WK0S0002400041453 / 62071	FRC	9289	06.05.2013
395/2010	VAVSAF3382H172982 / 11505	FRC	9290	07.05.2013
396/2010	WSMS7480000436618	FRC	9291	31.12.2012
397/2010	VM3LVFS3F11A03927 / 01C2271.003	FRC	9292	10.05.2013
398/2010	WK0S0002400109934	FRC	9293	10.05.2013
399/2010	WSM00000005065622	FRC	9294, 09 1414, MR79	30.04.2016
400/2010	VM4C382DRXA005151 / 43754	FRC	9295	31.08.2011
401/2010	WSM00000005034052	FRC	9296, 07 1328, MR79	03.03.2014
402/2010	WSMS7480000437529	FRC	9297	28.02.2013
403/2010	WK0S0002400058329 / 67708	FRC	BX4978, M576	03.07.2012
404/2010	WSMS7480000455628	FRC	9299	04.05.2013
405/2010	WSMS7480000448564	FRC	9300	04.05.2013
406/2010	210191	FRC	9301	04.05.2013
407/2010	WSMS7480000442049	FRC	9302	04.05.2013
408/2010	WSMS7480000447730	FRC	9303	04.05.2013
409/2010	WK0SVKT2440527295	FRC	9304	04.05.2013
410/2010	WSMS7480000455629	FRC	9305	04.05.2013
411/2010	SUDNS1CTZ58007730 / ZS3CT6301862	FRC	9306	11.05.2013
412/2010	SUDNS1CTZ58007731	FRC	9307	11.05.2013
413/2010	VM3LVFS3F51R11887 / 05C1309/001	FRC	9308	14.05.2013
414/2010	WKESDR27011387126 / 25799	FRC	9311	14.05.2013
415/2010	WSM00000005023316	FRC	9312	14.05.2013
416/2010	VM3LVFS3F14R03225	FRC	9309	14.05.2013
417/2010	VM3LVFS3EX1R09104 / 99/C0672.001	FRC	9310	07.05.2011
418/2010	WSMS7480000456106	FRC	9313	15.05.2013
419/2010	WSMS7480000444381	FRC	9314	15.05.2013
420/2010	WSMS7480000453532	FRC	9315	17.05.2013
421/2010	WSMS7480000457713	FRC	9316	13.05.2013
422/2010	VVCS0RXBAS4201445 / 20130	FRC	9317	17.05.2013
423/2010	VM3LVFS3F11R02148 / 01C3020.001	FRC	9318	18.05.2013
424/2010	WSM00000005009159	FRC	9319	14.05.2013
425/2010	WSMS7480000456444	FRC	9320	14.05.2013
426/2010	WSM00000005064756	FRC	3348T, M602	11.01.2016
427/2010	WSM00000005064755	FRC	3348T, M602	11.01.2016

428/2010	WSM0000005064757	FRC	3348T, M602	11.01.2016
429/2010	WSMS7480000459272	FRC	9325	20.05.2013
430/2010	WSMS7480000446304	FRC	9326	18.05.2013
431/2010	WSMS7780000438659	FRC	9324	21.05.2013
432/2010	VS9SA3NS61A013508 / F/1113/05	FND	9328	10.05.2013
433/2010	WSM0000005013336	FRC	9327	21.05.2013
434/2010	WSMS7480000435845	FRC	9330	16.10.2012
435/2010	WSMS7480000457693	FRC	9331	22.05.2013
436/2010	WSM0000005066921	FRC	09 1414, M602	14.04.2016
437/2010	WSM0000005066922	FRC	09 1414, M602	15.04.2016
438/2010	XLEP6X20005109172 / 110013610	FRC	9334, 6652, MR92	31.03.2016
439/2010	VF644AHL000005073 / 110003110	FNA	9335, 6336, MR99	31.03.2016
440/2010	VF644AHL000005067 / 110003210	FNA	9336, 6336, MR99	31.03.2016
441/2010	WSMS7480000432090	FRC	7406	25.07.2011
442/2010	WAX064100010 / 04C0435/001	FRC	9338	26.05.2013
443/2010	SW9PT122C41CH3327 / 04C0465/001	FRC	9339	26.05.2013
444/2010	WSM0000005064563	FRC	09 1414, M602	01.04.2016
445/2010	WK0SVKT24V9888177	FNA	9341	25.05.2013
446/2010	SUZPOC02RYZ000028 / 003066	FRC	9343	31.03.2012
447/2010	WSMS7480000458085	FRC	9344	25.05.2013
448/2010	WSMS7480000457668	FRC	9345	26.05.2013
449/2010	VM4C383BRWA004712	FNA	9346	26.05.2013
450/2010	VM3LVFS3EV1A05510 / 97/C344-011	FNA	9347	22.05.2013
451/2010	VM3LVFS3FY1R01010 / 00C0126-013	FRC	9348	31.03.2012
452/2010	VM3LVFS3F31A07107 / 03C0610/003	FRC	9349	25.05.2013
453/2010	VM3LVFS3F16R02944 / 01C0739.001	FRC	9350	25.05.2013
454/2010	WSM0000005003512	FRC	9351	27.05.2013
455/2010	VM3LVFS3F21R04219 / 01C2614.001	FRC	9352	27.05.2013
456/2010	VM3LVFS3EW1A07342 / 98/C0626.02	FNA	9353	31.05.2013
457/2010	WSM0000005013777	FRC	05 1251, MR79	03.2012
458/2010	WK0S0002400079525	FRC	9356	28.05.2013
459/2010	WSMS7480000443467	FRC	9357	29.05.2013
460/2010	WSMS7480000457721	FRC	9358	29.05.2013
461/2010	WSMS7480000448051	FRC	9359	28.05.2013
462/2010	WSM0000005032432	FRC	9360, 07 1310, MR79	02.11.2013
463/2010	WSM0000005013029	FRC	9361	29.05.2013
464/2010	SUDNS1CTZ54006161	FRC	9362	29.05.2013
465/2010	WSMS7780000438430	FRC	9365	07.06.2013
466/2010	WSMS7480000437947	FRC	9366	07.06.2013
467/2010	WK0SVKT24W9892023	FNA	9363	02.06.2013
468/2010	WKESDR27011274992 / 26096	FRC	9364	05.06.2013
469/2010	WSMS7480000448252	FRC	9367	07.06.2013
470/2010	VM4CD382G3A021527 / 55495	FRC	7949	10.03.2012
471/2010	VM3LVFS3F11A03046 / 01C0905.002	FRC	8075	17.04.2012
472/2010	VV1F3FA3XSN110742 / C4 040	FRC	7763	09.01.2012
473/2010	WSMS7480000459863	FRC	9374	02.06.2013
474/2010	VM4C381BRXA005113 / 43659	FRC	9375	25.06.2011
475/2010	WK0SVKT2430517759	FRC	9376	01.06.2013
476/2010	VM4CD382G1A020635 / 51213	FRC	9377	01.06.2013
477/2010	WSM0000005065625	FRC	09 1414, M602	12.04.2016
478/2010	WKESDR27041214109 / 30680	FRC	9372	08.06.2013
479/2010	WKESDR27011380935 / 27133	FRC	9379	29.05.2013
480/2010	VV1LTFT3EFL84147	FNA	9380	29.05.2013
481/2010	VM3LVFS3F21R05650 / 02C3904.001	FRC	9370	08.06.2013
482/2010	VM3LVFS3F21R04427 / 02C0276.001	FRC	9371	08.06.2013
483/2010	VM3LVFS3ES1R03317 / 95.C0765.001	FNA	9381	08.06.2013
484/2010	WKESDR27011389349	FRC	9383	08.06.2013
485/2010	VM4CD381JYA001333 / 46632	FRC	9385	11.05.2012
486/2010	WK0SVKT24W9823934	FRC	9386	10.06.2013
487/2010	XLER6X20004500565 / 01C1300.001	FRC	9387	14.06.2013
488/2010	WSMS7480000456361	FRC	9388	14.06.2013

489/2010	VVCS0RXBCS4X00434	FRC	9389	31.12.2011
490/2010	WK0SVKT24W9819793	FNA	9390	10.06.2013
491/2010	WSM00000005030018	FRC	9391	11.06.2013
492/2010	VF644AHH000004087 / 01645	FNA/X	9392, M589-C	10.06.2016
493/2010	VF644AHH000004069 / 01647	FNA/X	9393, 9392, M589-C	10.06.2016
494/2010	VM3LVFS3F71R15799 / 07C0312.001	FRC	9395	14.06.2013
495/2010	VM3LVFS3F51R11088 / 05C0419.003	FRC	9396	14.06.2013
496/2010	WSMS7480000457724	FRC	9397	15.06.2013
497/2010	WKESDR27011270757 / 26168	FRC	9398	16.06.2013
498/2010	WSM00000005003552	FRC	9399	17.06.2013
499/2010	VM3LVFS3F41R09244 / 04C0974/002	FRC	9400	18.06.2013
500/2010	WSMS7480000459110	FRC	9401	16.06.2013
501/2010	WKESDR27061254822	FRC	9402	17.06.2013
502/2010	WSMS7480000458675	FRC	9403	17.06.2013
503/2010	WSMS7480000459111	FRC	9404	17.06.2013
504/2010	VM3LVFS3E41R11451 / 04C1216/002	FRC	9405	18.06.2013
505/2010	VM3LVFS3ET6R05179 / 96C1647.005	FNA	9406	14.06.2013
506/2010	VS9SA3NS61A013663 / C13978	FRC	9407	14.06.2013
507/2010	VM4CD381G2A011477	FRC	9408	14.06.2013
508/2010	WSMS7480000438410	FRC	9409	31.05.2013
510/2010	WKESDR27041201811 / 29585	FRC	9414	17.06.2013
511/2010	WSMS7480000457672	FRC	9415	17.06.2013
512/2010	WSMS7480000401034	FNA	9416	17.06.2013
513/2010	WSMS7480000095387	FNA	9417	17.06.2013
514/2010	WK0S0002400116811	FRC	9418, 3388T, 179-CPABO/ATP/05	28.05.2014
515/2010	WSM00000005066532	FRC	09 1414, M602	08.04.2016
516/2010	WSM00000005006304	FRC	9412	23.06.2013
517/2010	VM3LVFS3F41R0899 / 04C0809/002	FRC	9411	23.06.2013
518/2010	XLEP6X20005103283 / 04.C1193/001	FRC	9420	23.06.2013
519/2010	WSM00000005067869	FRC	3348T, M605	14.05.2016
520/2010	W09X99335RHS09798 / 7447	FNA	7565	13.10.2011
521/2010	WSM00000005034836	FRC	9423	21.06.2013
522/2010	WSMS7480000457687	FRC	9424	23.06.2013
523/2010	WSMS7480000456110	FRC	9425	24.06.2013
524/2010	WSM00000005066682	FRC	09 1414, M576	08.04.2016
525/2010	VVCS0RXBCS4401760	FRC	9427	14.06.2013
526/2010	WDB6703231N112800 / 01690	FNA/X	9413, 4934	20.06.2016
527/2010	YV2A4CMC54B375025 / 11007124	FRC	9428	25.06.2013
528/2010	YV2A4CMC84B374984 / 11007134	FRC	9429	25.06.2013
529/2010	SUDPC4ZTZ44005236 / 11007154	FRC	9430	25.06.2013
530/2010	SUDPC4ZTZ44005235 / 11007144	FRC	9431	25.06.2013
531/2010	WKESDR27051222747 / 31244	FRC	9432	29.06.2013
532/2010	VM3LVFS3F11R02138 / 01C3010.001	FRC	9433	29.06.2013
533/2010	WFDFLT33541001140 / 11002094	FRC	9434	29.06.2013
534/2010	WK0S0002400101850 / 110029410	FRC	9435, 4838, M576	31.05.2016
535/2010	WK0S0002400101853 / 110029510	FRC	9436, 4838, M576	31.05.2016
536/2010	WSMS7780000446444	FRC	9437	28.06.2013
537/2010	WKESDR27051226456 / 31765	FRC	9438	29.05.2013
538/2010	WK0SVKT2420203746	FRC	9439	28.06.2013
539/2010	VA9USLAKT2FZT0202	FRC	9440	24.06.2013
540/2010	VM3LVFS3F41R09033 / 04C0809/036	FRC	9441	28.06.2013
541/2010	VM3LVFS3F41R09032 / 04C0809/035	FRC	9442	28.06.2013
542/2010	VM3LVFS3F21R05345 / 02C1640.001	FRC	9443	28.06.2013
543/2010	WKESDR27011265120	FRC	9444	28.06.2013
544/2010	WSMS7480000455736	FRC	9445	28.06.2013
547/2010	WSM00000005064562	FRC	09 1414, M602	02.03.2016
550/2010	WDB6763371K336401 / 24604	FNA	9451	06.07.2013
545/2010	WKESD000000464999 / 3293	FRC	9446, 3392T, MR79	31.05.2016
546/2010	WSM00000005065624	FRC	9447, 09 1414, M479	26.03.2016
548/2010	WSM00000005064568	FRC	09 1414, M602	02.02.2013
549/2010	VM3LVFS3F11R02599 / 01C0137.007	FRC	9450	28.02.2013

550/2010	WDB6763371K336401 / 24604	FNA	9451	06.07.2013
551/2010	WKESDR27011269038 / 26003	FRC	9452	05.07.2013
552/2010	YV2J4DGA421203281 / 112285	FRC	9453	05.07.2010
553/2010	YE7SD3AABN3202704 / F3001.631713	FRC	9454	05.07.2013
554/2010	WSM0000005067870	FRC	3348T, M605	14.05.2016
555/2010	SMSS7780000700118	FRC	9456	01.07.2013
556/2010	WKESDR27051229232 / 32171	FRC	9457	06.07.2013
557/2010	WSM0000005058767	FRC	9458, 09 1414, M716	31.12.2014
558/2010	WSM0000005069017	FRC	9459, 09 1414, M580	28.06.2016
559/2010	WSM0000005069014	FRC	9460, 09 1414, M440	30.06.2016
560/2010	WSMS7480000404143	FNA	9462	15.07.2013
561/2010	WSMS7480000458778	FRC	9465	07.07.2013
562/2010	WSMS7780000438660	FRC	9466	04.05.2013
563/2010	VAVSAF3383H186694 / 073UF5841	FRC	9467	07.07.2013
564/2010	VM3LVFS3F31R05734 / 03C3708.001	FRC	9468	08.07.2013
565/2010	WKESDR27011393939 / 28215	FRC	9469	19.07.2013
566/2010	WSMS7780000435175	FRC	9470	21.08.2012
567/2010	SMSS7780000702023	FRC	9471	01.07.2013
568/2010	YV2E4C813VB176437 / 20576	FNA/X	9472	15.07.2013
569/2010	WKESDR27041201795 / 29569	FRC	9473	02.07.2013
570/2010	WSMS7480000440635	FRC	9474	09.07.2013
571/2010	WK0SVKT2420203669	FRC	9475	09.07.2013
572/2010	43912 / 1-0-008-93	FNA	9476	09.07.2013
573/2010	WSM0000005015296	FRC	9477	01.07.2013
574/2010	XLRAE55GF0L358325 / 110097910	FRC/X	9478, 6652, 214.150.99P140.06126	30.04.2016
575/2010	XLRAE65GC0E873839 / 110097810	FRC/X	9479, 6652, 156-CPABO/ATP/01	30.04.2016
576/2010	XLRAS85MC0E871125 / 11009779	FRC	9480, 6652, 232-CPABO/ATP/07	12.04.2016
577/2010	SUZCFKJ5FR0Z00097 / 11009809	FRC	9481, 7328, 156-CPABO/ATP/01	29.02.2016
578/2010	WMAN28ZZ1AY241765 / 11007619	FRC	9482, 6652, MR92	14.12.2015
579/2010	WK0S0002400101835 / 110035210	FRC	9483, 4838, M716	30.06.2016
580/2010	WK0S0002400101831 / 110056010	FRC	9484, 4838, M716	30.06.2016
581/2010	WDB9505361L478996 / 110035710	FNA/X	9485, 6336, M667	30.04.2016
582/2010	WDB9061531N450300 / 110032610	FRC/X	9486, 8610, M486	23.06.2016
583/2010	WSMS7780000099239	FNA	9487	13.07.2013
584/2010	WSMS7780000435005	FRC	9488	15.08.2012
585/2010	WSMS7480000456196	FRC	9489	09.07.2013
586/2010	WSMS7480000456362	FRC	9490	13.07.2013
587/2010	WK0SVKT24V2181230	FNA	9491	09.07.2013
588/2010	VM3LVFS3F41R09005 / 04C0809/008	FRC	9492	13.07.2013
589/2010	VAVSAF3384H199654 / 135-942DQ*081*	FRC	9493	13.07.2013
590/2010	WSMS7480000458227	FRC	9494	12.07.2013
591/2010	WSMS7480000447369	FRC	9495	12.07.2013
592/2010	WSMS7480000072466	FNA	9496	12.07.2013
593/2010	WSMS7480000455953	FRC	9497	15.07.2013
596/2010	WSMS7480000450591	FRC	9500	15.07.2013
597/2010	210630	FRC	9501	19.07.2013
598/2010	VM3LVFS3F11R03818 / 01C2114008	FRC	9502	20.07.2013
599/2010	VM3LVFS3F41R09243 / 04C0974/001	FRC	9503	21.07.2013
600/2010	VM3LVFS3F24R04348 / 02C0186.003	FRC	9504	21.07.2013
601/2010	WSMS7480000457703	FRC	9506	22.07.2013
602/2010	WSMS7480000457717	FRC	9507	22.07.2013
603/2010	WKESDR27071297769 / 37077	FRC	9508	23.07.2013
604/2010	WSMS7480000457691	FRC	9509	23.07.2013
605/2010	22049 / 33840	FRC	9510	24.07.2013
606/2010	WSM0000005023701	FRC	9511	26.07.2013
611/2010	WK0S0002400133739 / 110029810	FRC	9516, 4838, M576	21.07.2016
612/2010	WK0S0002400133741 / 110029710	FRC	9517, 4838, M576	21.07.2016
613/2010	WK0S0002400133740 / 110029610	FRC	9518, 4838, M576	21.07.2016
614/2010	WSMS7480000458011	FRC	9519	29.07.2013
615/2010	WK0SVKT24Y0266994	FRC	9520	02.08.2013
616/2010	VM3LVFS3F71R16627 / 07C1002/008	FRC	9521	31.07.2013

617/2010	WSMS7480000456366	FRC	9522	02.08.2013
618/2010	VM3LVFS3EV1A06161 / 97/C1704.001	FNA	9526	02.08.2013
619/2010	WSMS7480000432673	FRC	9253	31.12.2012
620/2010	VM3LVFS3F21R04673 / 02C0683.001	FRC	9524	31.07.2013
621/2010	WKESDR27041214110 / 30681	FRC	9525	02.08.2013
622/2010	WKESDR27041200915	FRC	9528	30.07.2013
623/2010	WSMS7480000455347	FRC	9529	03.08.2013
624/2010	WSMS7480000442236	FRC	9533	03.08.2013
625/2010	WDB9702771L213571 / 07C0488-003	FRC	9534	03.08.2013
626/2010	WSMS7480000435587	FRC	9530	31.12.2012
627/2010	WKESDR27011158189 / 25016	FRC	9531	04.08.2013
628/2010	WSMS7780000439319	FRC	9532	23.07.2013
629/2010	WKESDR27041204562 / 29951	FRC	9535	06.08.2013
630/2010	WMAH10ZZ55M421684	FNA	9536	06.08.2013
631/2010	WSM00000005025347	FRC	9537	04.08.2013
632/2010	WK0S0002400076210	FRC	9538	04.08.2013
633/2010	VM3LVFS3ET1A05224 / 97/C0428-001	FNA	9539	27.07.2013
634/2010	VV5STNSFRYV009138 / 17.136	FRC	9540	30.09.2012
635/2010	VM3LVFS3F34R07055 / 03C0737.001	FRC	9541	07.08.2013
636/2010	WKESDR27041214939 / 30765	FRC	9542	07.08.2013
637/2010	80552	FNA	9543	10.08.2013
638/2010	XLRAE45BF4L256576 / 11001424	FRC/X	9544	11.08.2013
639/2010	VM3LVFS3F31A07109 / 03C0610/005	FRC	9545	05.08.2013
640/2010	XLDTXZ33900041006 / 39851	FNA	9546	03.08.2013
641/2010	VM4CD382G3A021735 / 55835	FRC	9547	03.08.2013
642/2010	VM4CD381J1A010880 / 51987	FRC	9552	02.08.2013
643/2010	WKESDR27041220470 / 31136	FRC	9548	13.08.2013
644/2010	WKESDR27041220474 / 31140	FRC	9549	13.08.2013
645/2010	WKESDR27041220467 / 31138	FRC	9550	13.08.2013
646/2010	WKESDR27041220469 / 31135	FRC	9551	13.08.2013
647/2010	VF644AHH000004161 / 110037210	FRC/X	9553, 7328, 178-CPABO/ATP/02	05.07.2016
648/2010	VF644AGE000007844 / 110037310	FRC/X	9554, 7328, 178-CPABO/ATP/02	05.07.2016
649/2010	YS2G6X20002054337 / 110053710	FNA	9555, 6336, M630	09.07.2016
650/2010	YS2G6X20002054284 / 110054010	FNA	9556, 6336, M630	09.07.2016
651/2010	SUZCFJ05RAZ000102 / 110054110	FNA	9557, 6336, M630	31.03.2015
652/2010	SUZCFJ05RAZ000101 / 110053810	FNA	9558, 6336, M630	31.05.2015
653/2010	WDB9702751L487327 / 110040110	FRC/X	9559, 7328, M581	31.03.2016
654/2010	ZCFC35713A5830758 / 110040310	FNA/X	9560, 7327, M621	23.07.2016
655/2010	ZCFC35713A5836674 / 110040710	FRC/X	9561, 8610, M631	28.07.2016
656/2010	ZCFC35713A5836924 / 110040610	FRC/X	9562, 8610, M631	28.07.2016
657/2010	ZCFC35713A5836702 / 110040510	FRC/X	9563, 8610, M631	28.07.2016
658/2010	ZCFC35713A5836703 / 110040410	FRC/X	9564, 8610, M631	28.07.2016
659/2010	WDB9061531N455688 / 110056910	FRC/X	9565, 8610, M631	31.07.2016
660/2010	WDB9061531N455689 / 110057010	FRC/X	9566, 8610, M631	31.07.2016
661/2010	ZCFA1AD0372500748 / 110048310	FNA/X	9567, 8609, M631	31.07.2016
662/2010	YV2AG10C8AB564264 / 110038910	FRC	9568, 6652, M630	25.05.2016
663/2010	WDB9300571L363768 / 11006109	FRC	9569, 6652, M630	28.09.2015
664/2010	VV5STNSFRYV009137 / 17132	FRC	9570	30.09.2012
665/2010	VM3LVFS3F41R09417 / 04C1288.005	FRC	9571	10.08.2013
666/2010	WSMS7480000403821	FNA	9572	12.08.2013
667/2010	WSMS7780000452121	FRC	9573	13.08.2013
668/2010	WSM00000005010807	FRC	9574	15.07.2013
669/2010	WSMS7480000455581	FRC	9575	13.08.2013
670/2010	WSMS7480000452285	FRC	9576	13.08.2013
671/2010	WSMS7480000452286	FRC	9577	13.08.2013
672/2010	WKESDR27011152069 / 24269	FRC	9578	25.05.2013
673/2010	WSMS7480000449642	FRC	9579	21.08.2013
674/2010	WSMS7480000445865	FRC	9580	21.08.2013
675/2010	VM4CD382G1A020222 / 49244	FRC	9581	13.03.2013
676/2010	VVCS0RXBAS4X00570 / 15932	FRC	9582	30.11.2011
677/2010	WSM00000005032525	FRC	9583	21.08.2013

678/2010	WSMS7780000451669	FRC	9584	21.08.2013
679/2010	VVCS0RXBCS4Y00740 / 16746	FRC	9585	30.09.2012
680/2010	SUDNSICTZ4X006155 / 047UL6744	FRC	9586	21.08.2013
681/2010	WSMS7480000436739	FRC	9587	31.12.2012
682/2010	WK0SVKT24W9806203	FNA	9588	21.08.2013
683/2010	WKESDR27000149826	FRC	9589	02.04.2013
685/2010	SUDNSICTZ48005891 / 013UI6675	FRC	9591	21.08.2013
686/2010	SUDNSICTZ4X006146 / 033UL6732	FRC	9592	21.08.2013
687/2010	VVCS0RXBCS4X00373	FRC	9593	21.08.2013
688/2010	WSMS7480000410967	FNA	9594	21.08.2013
689/2010	WSMS7450000414600	FRC	9595	21.08.2013
690/2010	WSMS7450000439817 / 2002363	FRC	9596	21.08.2013
691/2010	WKESDR27011387749 / 27980	FRC	9597	21.08.2013
692/2010	VF7232F5215393294 / 711474	FNA/X	9598	13.08.2012
693/2010	WSMS7480000416727	FNA	9599	07.08.2013
694/2010	WSMS7480000453580	FRC	9600	17.08.2013
695/2010	WSM00000005024084	FRC	9601	19.08.2013
697/2010	WSM00000005069007	FRC	9603, 3395T, MR79	30.06.2016
699/2010	WK0SVKT2430206628	FRC	9605	23.08.2013
700/2010	WSMS7780000434234	FRC	9606	31.12.2012
701/2010	WKESD000000380943 / 39222	FRC	9607	18.08.2013
702/2010	VM3LVFS3F21A04543 / 02C0465.001	FRC	9608	24.08.2013
703/2010	WKESDR27041215756 / 30800	FRC	9609	04.08.2013
704/2010	WKESDR27041220472 / 31138	FRC	9610	25.08.2013
705/2010	WKESDR27041220475 / 31141	FRC	9611	25.08.2013
706/2010	WKESDR27041220473 / 31139	FRC	9612	25.08.2013
707/2010	VAVSAF3384H196002 / 21931	FRC	9613	25.08.2013
708/2010	WSMS7480000411010	FNA	9614	25.08.2013
709/2010	WKESDR27041201820 / 29594	FRC	9615	24.08.2013
710/2010	WSMS7480000433824	FRC	9616	27.08.2013
711/2010	W09001335WMT35055 / 27861	FRC	9617	27.08.2013
712/2010	WKESDR27011388919	FRC	9618	27.08.2013
713/2010	WSMS7480000432517	FRC	9619	27.08.2013
714/2010	WSMS7480000433627	FRC	9620	27.08.2013
715/2010	SV9PCH263WPMN1033	FNA	9621	27.08.2013
716/2010	WKESDR27011274640 / 26679	FRC	9622	27.08.2013
717/2010	15998 / F11025344	FRC	9623	27.08.2013
718/2010	YE730PF38YH201136 / F9001.450964	FRC	9624	31.05.2013
719/2010	W903F336TSA10308 / 8804	FNA	9625	27.08.2013
720/2010	VM3LVFS3F41R09151 / 04C0928/007	FRC	9626	27.08.2013
721/2010	VM3LVFS3F41R08538 / 04C0197.001	FRC	9627	26.08.2013
722/2010	WSMS7480000446051	FRC	9628	26.08.2013
723/2010	WSMS7480000458711	FRC	9629	27.08.2013
724/2010	WSM00000005066925	FRC	09 1414, M602	03.05.2016
725/2010	VM3LVFS3FY1R01626 / 00C1564.001	FRC	9634	10.08.2012
726/2010	VM4CD382G1A020241 / 49528	FRC	9635	19.03.2013
727/2010	WKESDR27011220476 / 31142	FRC	9631	31.08.2013
728/2010	WKESDR27041220468 / 31134	FRC	9632	31.08.2013
729/2010	WKESDR27041220471 / 31137	FRC	9633	31.08.2013
730/2010	WSMS7480000457665	FRC	9636	02.09.2013
731/2010	WKESDR27061260201 / 3488	FRC	9637	02.09.2013
732/2010	WKESDR27051234764 / 32554	FRC	9638	03.09.2013
733/2010	WKESDR27041201846 / 29620	FRC	9639	03.09.2013
734/2010	W091693382HS09006 / 11380	FRC	9640	02.09.2013
735/2010	15597	FRC	9641	28.08.2013
736/2010	VM3LVFS3F41R09011 / 04C0809/014	FRC	9642	30.08.2013
737/2010	WK0SVKT24W9892028	FNA	9643	27.08.2013
738/2010	WKESDR27061268297	FNA	9644	30.08.2013
739/2010	WSM00000005069046	FRC	9645, 3395T, M576	20.08.2016
740/2010	VM3LVFS3F34R07686 / 03C1836.27	FRC	9646	04.09.2013
741/2010	WSMS7780000440812	FRC	9647	04.09.2013

742/2010	VVCS0RXBCS4201360 / 19583	FRC	9648	04.09.2013
743/2010	VM3LVFS3E21R10676 / 02C0673.001	FRC	9649	04.09.2013
744/2010	VM3LVFS3EX1R08848 / 99/C0065-002	FRC	9650	23.02.2011
745/2010	WK0S0002400133742 / 110029910	FRC	9651, 4838, M588	13.08.2016
746/2010	WK0S0002400133743 / 110030010	FRC	9652, 4838, M588	13.08.2016
747/2010	WK0S0002400133744 / 110030110	FRC	9653, 4838, M588	13.08.2016
748/2010	WDB9061351N459048 / 110062510	FNA/X	9654, 6653, M604	31.08.2016
749/2010	YV2AG10C9AB567724 / 110058510	FRC	9655, 6652, M421	12.08.2016
750/2010	YV2AG10C2AB567550 / 110058610	FRC	9656, 6652, M421	12.06.2016
751/2010	VF156ANA141469870 / 110061710	FRC/X	9657, 5547, M610	30.04.2016
752/2010	VWANFTTK074009788 / 118UA7912	FNA/X	9658, 094-CPABO/ATP/04	07.09.2016
753/2010	WKESD000000420215	FRC	9659	05.09.2013
754/2010	WSM00000005017330	FRC	9660	05.09.2013
755/2010	WK0S0002400076212	FRC	9661	05.09.2013
756/2010	WSM00000005019029	FRC	9662	05.09.2013
757/2010	WKESD000000379018 / 38849	FRC	9663	05.09.2013
758/2010	WKESDR27041201829 / 29603	FRC	9664	05.09.2013
759/2010	WSMS7480000455346	FRC	9665	05.09.2013
760/2010	WSM00000005039983	FRC	9666, 3404T, MR79	24.07.2014
761/2010	WK0SVKT2430206629	FRC	9667	05.09.2013
762/2010	WKESDR27011380136 / 27128	FRC	9668	05.09.2013
763/2010	WSM00000005025738	FRC	9669	05.09.2013
764/2010	WSMS7480000456312	FRC	9670	05.09.2013
765/2010	WSMSK024000064115	FNA	9671	10.09.2013
766/2010	WSMS7480000097303 / 451045	FRC	9672	10.09.2013
767/2010	VM3LVFS3F41R09415 / 04C1288/003	FRC	9673	10.09.2013
768/2010	WSMS7780000441324	FRC	9674	11.09.2013
769/2010	WK0SVKT240266993	FRC	9675	11.09.2013
770/2010	WMAL35ZZZ2Y100867 / 236.02.02	FNA	9676	11.09.2013
771/2010	WMAL334933G133012 / 98595	FNA	9677	11.09.2013
772/2010	WSMS7480000441983	FRC	9678	07.09.2013
773/2010	WSM00000005034023	FRC	9679, 3395T, MR79	25.10.2013
774/2010	WSMS7480000455630	FRC	9680	08.09.2013
775/2010	WK0SVKT24W9822673	FNA	9681	08.09.2013
776/2010	WKESD000000465008 / 3302	FRC	9682, 3392T, M576	30.04.2016
777/2010	WSMS7480000419020	FRC	9683	22.09.2011
778/2010	VAW3SNK36SYY07686	FNA	9684	10.09.2013
779/2010	WSMS7480000071190	FNA	9685	10.09.2013
780/2010	WSMS7480000078873	FNA	9686	10.09.2013
781/2010	WSM00000005057719	FRC	9687, 08 1348, M576	30.09.2014
782/2010	WSM00000005055236	FRC	9688, 08 1348, M576	31.05.2014
783/2010	SUDNS1CTZ43004945 / 212UD6369	FRC	9689	10.09.2013
784/2010	VK1ST39WGPE720140 / 208027	FRC	9690, T3895, M576	31.01.2014
785/2010	VS9SA3NS61A013386 / C13667	FNA	9691	14.09.2013
786/2010	WKESDR27011387108	FRC	9692	11.09.2013
787/2010	WSMS7480000441233	FRC	9693	11.09.2013
788/2010	WKESDR27051247856 / 33526	FRC	9694	11.09.2013
789/2010	WK0S0002400052410 / 66068	FRC	9695	11.09.2013
790/2010	WK0SVKT24Y0269315	FRC	9696	31.12.2012
791/2010	VM3LVFS3F41R09413 / 04C1288/001	FRC	9697	13.09.2013
792/2010	VM3LVFS3F41R09414 / 04.C1288/002	FRC	9698	13.09.2013
793/2010	WSM00000005016895	FRC	9699	14.09.2013
794/2010	WSMS7480000457400	FRC	9700	14.09.2013
795/2010	YE730PF385H203688 / F5001 452035	FRC	9701	14.09.2013
796/2010	WSMS7480000437953	FRC	9702	31.03.2013
797/2010	SMXGA3S032F013537 / F4.02.4812	FRC	9703	15.09.2013
798/2010	WKESDR27011378738	FRC	9704	15.09.2013
799/2010	WDF9402041B968080 / 08C1916/001	FNA	9705	17.09.2013
800/2010	WKESD000000433754	FRC	9707	11.09.2013
801/2010	VM3LVFS3E41R11530 / 04C1874/001	FRC	9706	17.09.2013
802/2010	VA9USLAKT4FZT0193 / 10116571	FRC	9708	16.09.2013

803/2010	XLEP4X20004489684	FRC	9709	17.09.2013
804/2010	WKESDR27041203080 / 29.414	FRC	9710	14.09.2013
805/2010	VK1ST39WGPE720144 / 208034	FRC	9711, T3895, M576	28.02.2014
806/2010	VM3LVFS3F41R09140 / 04C0865/001	FRC	9712	14.09.2013
807/2010	WSM00000005011615	FRC	9713	20.09.2013
808/2010	WSM00000005041188	FRC	9714, 07 1295, M523	18.02.2014
809/2010	WSM00000005041184	FRC	9715, 07 1295, M509	13.02.2014
810/2010	WSM00000005041187	FRC	9716, 07 1295, MR79	18.02.2014
811/2010	SUDNS340000022826 / 110030510	FRC	9717, 4838, M588	03.09.2016
812/2010	SUDNS340000022824 / 110030210	FRC	9718, 4838, M588	07.09.2016
813/2010	ZCFC35713A5836923 / 110040810	FRC/X	9719, 8610, M631	28.07.2016
814/2010	SUDNS340000022825 / 110030310	FRC	9720, 4838, M588	03.09.2016
815/2010	110059510	FRC	9721, 6652, M700	23.09.2016
816/2010	WKESDR27061264968 / 35183	FRC	9722	22.09.2013
817/2010	VK1ST39WGPE720136 / 208029	FRC	9723, T3895, M523	08.02.2014
818/2010	WSMS7480000432795	FRC	9724	09.11.2012
819/2010	WSM00000005029125	FRC	9725	25.09.2013
820/2010	WSM00000005032297	FRC	9726, 3395T, MR79	29.10.2013
821/2010	WSM00000005056119	FRC	9727, 07 1311, M633	30.11.2014
822/2010	WSM00000005051447	FRC	9728, 07 1311, M633	31.05.2014
823/2010	VM3LVFS3F11R02602 / 01C0137.010	FRC	9729	09.03.2013
824/2010	WKESDR27011262205 / 25010	FRC	9730	25.09.2013
825/2010	VM3LVFS3F41R09010 / 04.C0809.013	FRC	9731	24.09.2013
826/2010	WSM00000005041185	FRC	9732, 07 1328, M425	18.02.2014
827/2010	WSMS748000044713	FRC	9733	24.09.2013
828/2010	SUDNS1CTZ48005897 / 020UI6681	FRC	9734	25.09.2013
829/2010	WSM00000005000330	FRC	9735	25.09.2013
830/2010	WSMS7780000446266	FRC	9736	28.09.2013
831/2010	WSM00000005002033	FRC	9737	29.09.2013
832/2010	VM3LVFS3F44A09214 / 04C0988.001	FRC	9738	30.09.2013
833/2010	VM3LVFS3F14R02970 / 01C0795.001	FRC	9739	31.05.2013
834/2010	WSMS7480000458087	FRC	9740	04.10.2013
835/2010	WSM00000005043443	FRC	9741, 07 1295, MR79	24.04.2014
836/2010	WSM00000005016538	FRC	9742	29.09.2013
838/2010	WSMS7480000406987	FNA	9744	05.10.2013
839/2010	SUDNS1CTZ4X005899 / 023UL6683	FRC	9746	25.09.2013
840/2010	SUDNS1CTZ4X006153 / 045UL6739	FRC	9747	25.09.2013
841/2010	WSMS7480000437066	FRC	9748	23.05.2013
842/2010	SUDNS1CTZ48005892	FRC	9749	25.09.2013
843/2010	SUDNSCTZ4X005900 / 024UL6684	FRC	9750	25.09.2013
844/2010	WSMS7480000456144	FRC	9751	28.09.2013
845/2010	WKESDR27051247519 / 33762	FRC	9752	27.09.2013
846/2010	VM3LVFS3EW1R08332 / 98C1515.002	FNA	9753	28.09.2013
847/2010	WK0SFSB2430712429	FRC	9754	29.09.2013
848/2010	WK0S0002400084346	FRC	9755	01.10.2013
849/2010	WSM00000005055234	FRC	9756, 08 1348, M576	31.05.2014
850/2010	VM3LVFS3F41R10253 / 04C2344.007	FRC	9757	01.10.2013
851/2010	SUDNS1CTZ71012187 / 11020006	FRC	6323, 4838, M576	31.03.2013
852/2010	VF644ACA000018133 / 11009346	FNA	5845, 4152, MR90	09.2012
853/2010	WSM00000005030021	FRC	9760	02.10.2013
854/2010	16014 / F11.025360	FRC	9761	02.10.2013
855/2010	16028 / F11.025374	FRC	9762	02.10.2013
856/2010	WK0SVKT24R2141188	FNA	9763	02.10.2013
857/2010	16011 / F11025357	FRC	9764	02.10.2013
858/2010	VM3LVFS3ES1A03988 / 95C1557.001	FNA	9765	02.10.2013
859/2010	WMAN15ZZ5BY252335 / 110067210	FNA	9766, 6336, M686	16.09.2016
860/2010	WMAN15ZZ9BY252368 / 110067310	FNA/X	9767, 8609, M641	16.09.2016
861/2010	WDB9702771L487329 / 110040210	FRC/X	9768, 7328, M589-A	03.08.2016
862/2010	ZCFC35713A5842332 / 110068410	FNA/X	9769, 7327, M621	23.09.2016
863/2010	ZCFC35713A5842331 / 110068510	FNA/X	9770, 7327, M621	23.09.2016
866/2010	VM3LVFS3F24R04347 / 02C0186.002	FRC	9773	04.10.2013

867/2010	WK0AVKT18P2132454	FNA	9774	05.10.2013
868/2010	YV2A4CFCX5B384463 / 041689/U105/04	FRC	9775	05.10.2013
869/2010	WKESDR27041222330 / 31281	FRC	9776	11.10.2013
870/2010	WSM00000005024727	FRC	6212, 3379T, MR79	01.2013
871/2010	WSM00000005017862	FRC	06 1281, MR79	07.2012
876/2010	WKESDR27011385994 / 27807	FRC	9784	14.10.2013
877/2010	VK1ST39WGRA60926	FRC	9785	13.10.2013
878/2010	XLRAS47XS0E544957 / 175845	FNA	9786	09.10.2013
879/2010	WKESDR27041201841 / 29615	FRC	9790	08.10.2013
880/2010	WSM00000005026999	FRC	9791	12.10.2013
881/2010	VM3LVFS3F24R04350 / 02C0186.005	FRC	9792	12.10.2013
882/2010	WSMS7480000455626	FRC	9793	13.10.2013
885/2010	WKESDR27041201836 / 29610	FRC	9787	13.10.2013
886/2010	WKESDR27041201837 / 29611	FRC	9788	13.10.2013
887/2010	WKESDR27041201838 / 29612	FRC	9789	13.10.2013
888/2010	VM3LVFS3F41R10026 / 04C2057/001	FRC	9796	11.10.2013
890/2010	WSM00000005011890	FRC	9798	12.10.2013
891/2010	WSM00000005022139	FRC	9799	12.10.2013
892/2010	WK0S0002400101832 / 11009669	FNA	9800, 4525, 3074K	31.12.2015
893/2010	SUDNS340000023145 / 110076110	FRC	9803, 9743, M601	19.10.2016
894/2010	WSM00000005012778	FRC	9801	20.10.2013
895/2010	WSM00000005069522	FRC	3367T, M602	26.08.2016
896/2010	WSM00000005066916	FRC	09 1414, M602	12.04.2016
897/2010	WSM00000005055237	FRC	9805, 08 1348, M576	31.05.2014
898/2010	WSM00000005002438	FRC	9806	16.10.2013
900/2010	WSM00000005000279	FRC	9808	16.10.2013
901/2010	WSMS7780000444389	FRC	9809	16.10.2013
902/2010	WSMS7480000416498	FRC	9810	09.07.2011
903/2010	WSMS7480000456304	FRC	9811	19.10.2013
904/2010	VM3LVFS3F21R04948 / 02C1196.005	FRC	9812	13.10.2013
905/2010	VM3LVFS3F41R09412 / 04C1287.001	FRC	9813	19.10.2013
906/2010	VAVSAF3384Z203996 / 22401	FRC	9814	19.10.2013
907/2010	WSMS7780000443509	FRC	9815	22.10.2013
908/2010	WSMS7480000443400	FRC	9816	25.10.2013
909/2010	WSM00000005066932	FRC	09 1414, M602	27.08.2016
910/2010	WSMS7780000439464	FRC	9818	26.10.2013
911/2010	WKESDR27041203716	FRC	8166	06.05.2012
912/2010	VM3LVFS3FY1R01095 / 00C0367-001	FRC	9820	31.03.2012
915/2010	VFNSYY3LLX2RB0214 / 90531...2	FRC	9823	28.01.2012
916/2010	WSM00000005005289	FRC	6662, 04 1181, MR79	15.03.2011
917/2010	VM3LVFS3F44R08367 / 110089410	FRC	9825, 9743, M479	22.10.2016
918/2010	VM3LVFS3FW1R00272 / 98/C1725.009	FNA	9826, M430	26.10.2016
919/2010	WK0SVKT2410283572	FRC	9827	08.10.2013
920/2010	WSMS7780000438663	FRC	9828	05.06.2013
921/2010	WKESDR27011153647 / 24625	FRC	9829	31.03.2013
922/2010	VM3LVFS3F41R09416 / 04C1288/004	FRC	9830	26.10.2013
923/2010	WK0SVKT2410284964	FRC	9831	25.10.2013
924/2010	VM3LVFS3F31R07888 / 03C2075/001	FRC	9832	25.10.2013
925/2010	WSM00000005019085	FRC	9833	25.10.2013
926/2010	ZCFC35713A5845252 / 110041110	FRC/X	9834, 8610, M631	30.09.2016
927/2010	ZCFC35713A5845251 / 110041210	FRC/X	9835, 8610, M631	30.09.2016
928/2010	ZCFC35713A5845527 / 110041310	FRC/X	9836, 8610, M631	30.09.2016
929/2010	ZCFC35713A5844819 / 110040910	FRC/X	9837, 8610, M631	28.09.2016
930/2010	ZCFC35713A5845038 / 110041010	FRC/X	9838, 8610, M631	28.09.2016
931/2010	VF3YCBMAC11845680 / 110068310	FRC/X	9839, 8610, M631	30.09.2016
932/2010	VF3YCBMAC11845641 / 110068210	FRC/X	9840, 8610, M631	30.09.2016
933/2010	ZCFC35713A5836923 / 110041410	FRC/X	9841, 5547, M628	28.07.2016
934/2010	ZCFA1EJ04A2572854 / 110089310	FRC	9842, 7328, 130-CPABO/ATP/07	13.10.2016
935/2010	WMA18SZZ3BP023909 / 110076710	FNA	9843, 6336, 156-CPABO/ATP/01	30.09.2016
936/2010	WMA18SZZ3BP023896 / 110076610	FNA	9844, 6336, 156-CPABO/ATP/01	30.09.2016
937/2010	WMAN16ZZ3BY252324 / 110076510	FNA/X	9845, 8609, 9016-ATP-09	30.09.2016

938/2010	WMAN16ZZ6BY252298 / 110076410	FNA/X	9846, 8609, 9016-ATP-09	30.09.2016
939/2010	WMAN16ZZXBY252336 / 110076310	FNA/X	9847, 8609, 9016-ATP-09	30.09.2016
940/2010	WMAN16ZZ1BY252273 / 110076210	FNA/X	9848, 8609, 9016-ATP-09	30.09.2016
941/2010	WSMS6080000504446 / 110030410	FRC	9849, 9743, M588	22.10.2016
942/2010	WKESDR27051235290	FRC	9850	03.11.2013
943/2010	WSMS7480000441522	FRC	9851	03.11.2013
944/2010	WMV30KS27WL244798 / TP 2836762953	FNA	9852, M430	03.11.2016
945/2010	WSMS7480000456370	FRC	9853	23.10.2013
946/2010	WSMS7480000456170	FRC	9854	23.10.2013
947/2010	WSM00000005002449	FRC	9855	23.10.2013
948/2010	WSM00000005002448	FRC	9856	18.10.2013
950/2010	XLER6X20005109428 / 11010524	FRC	9858	18.10.2013
954/2010	VM4C381BRTA002602 / 34376	FNA	9862	23.10.2013
955/2010	VM3LVFS3EW3R08489 / 98/C1660001	FNA	9863	23.10.2013
956/2010	WSMS7780000443796	FRC	9864	24.10.2013
957/2010	SUDNS340000023134 / 110075410	FRC	9865, 9743, M601	30.09.2016
958/2010	WSMS7780000439467	FRC	9866	30.09.2013
959/2010	WSM00000005069058	FRC	3367T, M588	20.09.2016
961/2010	WSMS7480000440911	FRC	9869	26.10.2013
962/2010	WSM00000005002359	FRC	9870	27.10.2013
964/2010	WSMS7480000409849	FNA	9872	29.10.2013
965/2010	WSMS7480000444715	FRC	9873	26.10.2013
966/2010	WSM7480000453206	FRC	9874	26.10.2013
967/2010	VM3LVFS3F41R09009 / 04C0809.012	FRC	9875	26.10.2013
968/2010	WSMS7780000439461	FRC	9876	30.09.2013
969/2010	WSMS7780000439453	FRC	9877	30.09.2013
970/2010	WSM00000005069516	FRC	3362T, M602	10.08.2016
971/2010	WSM00000005001470	FRC	9879	05.11.2010
972/2010	WSM00000005029494	FRC	9880	02.11.2013
973/2010	WKESDR27000150938	FRC	9881	18.06.2013
974/2010	SUDNS1CTZ45005398 / 051UF6537	FRC	9882	02.11.2013
975/2010	WSMS7480000437743	FRC	9883	01.10.2013
976/2010	VM3LVFS3F41R09184 / 04C0992.004	FRC	9884	02.11.2013
977/2010	WKESDR27011388772 / 28395	FRC	9885	04.11.2013
978/2010	WSM00000005001833	FRC	9886	03.11.2013
979/2010	WSM00000005000417	FRC	9887	04.11.2013
980/2010	WSM00000005065606	FRC	9888, 3367T, MR79	31.03.2016
981/2010	VM3LVFS3F71R16663 / 07C1002/044	FRC	9889	04.11.2013
982/2010	VM3LVFS3F41R09144 / 04C0919.002	FRC	9890	02.11.2013
983/2010	VM3LVFS3F41R09143 / 04C0919.001	FRC	9891	02.11.2013
984/2010	WSMS7480000091710	FNA	9892	02.11.2013
985/2010	WK0SVKT2410283714	FRC	9894	04.11.2013
986/2010	WSMS7480000450311	FRC	9893	04.11.2013
987/2010	WKESDR27011381589 / 27158	FRC	9895	04.11.2013
988/2010	WK0SVKT24Y9854504	FRC	9896	15.09.2012
989/2010	WSM00000005000548	FRC	9897	08.11.2013
990/2010	VM3LVFS3F61R12790 / 06C0038/007	FRC	9898	03.11.2013
991/2010	VM3LVFS3F61R12784 / 06C0038/001	FRC	9899	03.11.2013
992/2010	WSMS7480000456817	FRC	9900	03.11.2013
994/2010	WSMS7480000437806	FRC	9902	01.04.2013
995/2010	WSMS7480000410624	FNA	9903	02.11.2013
996/2010	WSMS7780000406154	FNA	9904	02.11.2013
998/2010	WSMS7480000437809	FRC	9906	03.11.2013
999/2010	VM3LVFS3F24R05095 / 02C1423.001	FRC	9907	10.11.2013
1000/2010	WSM00000005002369	FRC	9908	12.11.2013
1001/2010	WSM00000005000936	FRC	9909	12.11.2013
1002/2010	WSMS7780000436107	FRC	9910	17.01.2013
1003/2010	WSM00000005011736	FRC	9911	13.11.2013
1004/2010	VM3LVFS3F21R05140 / 02C1481.006	FRC	9912	13.11.2013
1005/2010	VM3LVFS3F21A04561 / 02C0496.001	FRC	9913	05.11.2013
1006/2010	WKESDR27041222343 / 31294	FRC	9914	05.11.2013

1007/2010	WKESDR27041222329 / 31280	FRC	9915	05.11.2013
1008/2010	WKESDR27041222339 / 31290	FRC	9916	05.11.2013
1009/2010	WKESDR27041222338 / 31289	FRC	9917	08.11.2013
1010/2010	WSMS7480000456325	FRC	9918	08.11.2013
1011/2010	WSMS7480000450195	FRC	9919	08.11.2013
1012/2010	WSM00000005000464	FRC	9920	09.11.2013
1013/2010	WSMS7480000560051	FRC	9921	10.11.2013
1014/2010	WSMS7480000440341	FRC	9922	22.10.2013
1015/2010	VM3LVFS3F71R16622 / 07C1002/003	FRC	9923	13.11.2013
1016/2010	WSMS7480000403776	FNA	9925	15.11.2013
1017/2010	WKESDR27051222218	FRC	9926	15.11.2013
1018/2010	WSMS7480000447535	FRC	9927	17.11.2013
1019/2010	WSMS7480000085854	FNA	9928	04.11.2013
1020/2010	VM3LVFS3F41R09187 / 04C0992/007	FRC	9929	05.11.2013
1021/2010	WSM00000005024188	FRC	9930	05.11.2013
1022/2010	WKOSVKT2450736209 / 60792	FRC	9931	05.11.2013
1023/2010	WSM00000005069575	FRC	9932, 3367T, MR79	30.09.2016
1024/2010	XLDTXZ33900040773 / 98.0116-53	FNA	9933	05.11.2013
1025/2010	WKESDR27051240486 / 33090	FRC	9934	09.11.2013
1026/2010	WSMS7780000451715	FRC	9935	09.11.2013
1027/2010	WSMS7480000440191	FRC	9936	15.10.2013
1028/2010	WSMS7780000453693	FRC	9937	10.11.2013
1029/2010	VAVSAF3384H208518 / 22413	FRC	9938	12.11.2013
1030/2010	VM3LVFS3F11R03820 / 01C2114.010	FRC	9939	15.11.2013
1031/2010	WSM00000005002425	FRC	9940	15.11.2013
1032/2010	WMAH20ZZ64W053399	FNA	9941	16.11.2013
1033/2010	WKESDR27051222202	FRC	9942	18.11.2013
1034/2010	SUDNS340000022980 / 110072510	FRC	9943, 9743, M601	31.10.2016
1035/2010	SUDNS340000022981 / 110072310	FRC	9944, 9743, M601	31.10.2016
1036/2010	SUDNS340000022982 / 110072610	FRC	9945, 9743, M601	31.10.2016
1037/2010	SUDNS340000022983 / 110072110	FRC	9946, 9743, M601	31.10.2016
1038/2010	SUDNS340000022984 / 110072710	FRC	9947, 9743, M601	31.10.2016
1039/2010	SUDNS340000022985 / 110072210	FRC	9948, 9743, M601	31.10.2016
1040/2010	SUDNS340000023381 / 110084510	FRC	9949, 9743, M601	31.10.2016
1041/2010	SUDNS340000022979 / 110072410	FRC	9950, 9743, M601	31.10.2016
1042/2010	XLEG6X20005247221 / 110071110	FRC	9951, 6652, M578	31.05.2016
1043/2010	YV2AG10C6BB573403 / 110085310	FRC	9952, 6652, M421	31.10.2016
1044/2010	SX90218ZGA5SP2483 / 11006010	FNA	9953, 6336, M568	31.10.2016
1045/2010	VF6VGU6C744062398 / 110070710	FRC/X	9954, 8610, M581	31.10.2016
1046/2010	VF6VGU6C744062399 / 110070810	FRC/X	9955, 8610, M581	31.10.2016
1048/2010	WSM00000005066683	FRC	09 1414, M576	08.04.2016
1049/2010	WSM00000005071620	FRC	3348T, M605	03.08.2016
1050/2010	WSM00000005071621	FRC	3348T, M605	03.08.2016
1051/2010	WSM00000005069083	FRC	3390T, M576	20.10.2016
1052/2010	WSM00000005072451	FRC	3390T, M602	13.10.2016
1053/2010	WSMS7780000451340	FRC	9962	25.11.2013
1054/2010	WSM00000005024707	FRC	9963	17.11.2013
1055/2010	WKESDR27071297103	FRC	9964	17.11.2013
1056/2010	WSM00000005031613	FRC	9965	17.11.2013
1057/2010	WSMS7480000444709	FRC	9966	17.11.2013
1058/2010	VM3LVFS3W6R07230	FRC	9967	17.11.2013
1059/2010	WSM00000005038589	FRC	9968, 07 1327, M576	10.01.2014
1060/2010	WSM00000005016761	FRC	9969	18.11.2013
1061/2010	WKESDR27041200591 / 29341	FRC	9970	18.11.2013
1062/2010	YS2R6X20002055614 / 110059610	FRC	9971, 6652, M421	24.09.2016
1063/2010	SUZ659FAB0A000446 / 110062310	FRC	9972, 6652, M421	30.09.2016
1064/2010	YV2AG30C5AB566131 / 110062210	FRC	9973, 6652, M421	31.08.2016
1065/2010	WSM00000005009257	FRC	9974	26.11.2013
1066/2010	VAVSAF3384H186462 / 11002554	FRC	9976	23.11.2013
1067/2010	WKESDR27011158826 / 24840	FRC	9975	24.11.2013
1068/2010	WSMA7420000409873	FNA	9977	25.11.2013

1069/2010	VF7YCBMAC11873854 / OP-20864/ATP18/09	FRC/X	9978, 7013, M697	30.10.2016
1070/2010	VAVSAF3384H195750 / 21690	FRC	9979	23.11.2013
1071/2010	VM3LVFS3F41R09562 / 04C1514/004	FRC	9980	23.11.2013
1072/2010	VNFSYY3CXRAR04388 / 405050	FNA	9981	23.11.2013
1075/2010	VM3LVFS3E61R11865 / 06C1815/008	FRC	9984	02.12.2013
1076/2010	WSM00000005066929	FRC	09 1414, M602	31.05.2016
1077/2010	VS9SA3NS84A013290 / C 15937	FRC	9986	07.10.2013
1078/2010	WSMS748000044712	FRC	9987	24.11.2013
1079/2010	VM3LVFS3F41R09008 / 04C0809/011	FRC	9988	24.11.2013
1080/2010	WSMS7480000453209	FRC	9989	24.11.2013
1081/2010	WSM00000005033164	FRC	9991	25.11.2013
1082/2010	SUDNS1CBZ71011558 / 11019456	FRC	6649, 4838, MR79	31.10.2013
1083/2010	WSM00000005000342	FRC	9993	02.12.2013
1084/2010	WSM00000005069589	FRC	9994, 3390T, M511	31.10.2016
1085/2010	VM3LVFS3F11R03822 / 01C2114/12	FRC	9995	03.12.2013
1086/2010	WSMS7480000439660	FRC	9996	17.08.2013
1087/2010	WSM00000005023545	FRC	9997	07.12.2013
1088/2010	WK0SVKT2450735492 / 60466	FRC	9998	09.12.2013
1089/2010	WK0S0002400110112	FRC	7902, 3365T, M576	20.03.2014
1090/2010	ZCFA1TM0492552931 / 110125110	FNA	10000, 6336, M572	06.12.2016
1091/2010	WMAL20ZZZ2Y094517	FNA/X	10001	11.12.2013
1092/2010	WSMS7780000447135	FRC	10002	11.12.2013
1093/2010	WSM00000005069531	FRC	3367, M602	06.10.2016
1094/2010	WKESDR27041200912 / 29349	FRC	10004	08.12.2013
1095/2010	VFKTX34VW12FX1511 / 50092	FRC	10005	31.10.2013
1096/2010	VS9SA3NS84A013291 / C15938	FRC	10007	10.12.2013
1097/2010	WDB9702771L522212 / 110086110	FRC/X	10008, 7328, M689	07.12.2016
1098/2010	VF624CPD000003143 / 110105210	FRC/X	10009, 6652, 232-CPABO/ATP/07	10.12.2016
1099/2010	WSM00000005031614	FRC	10010	09.12.2013
1101/2010	WSMS7480000445175	FRC	10012	14.12.2013
1102/2010	WSM00000005072426	FRC	3374T, M602	06.10.2016
1103/2010	WSMS7480000459112	FRC	10014	10.12.2013
1104/2010	3761867	FRC	10015	10.12.2013
1105/2010	200293	FRC	10016	31.12.2012
1106/2010	VGUST338A34006198	FNA	10017	10.12.2013
1107/2010	VM4CD382G2A021439	FRC	10018	10.12.2013
1108/2010	WMAN13ZZ4BY256140 / 110093710	FRC/X	10019, 7328, M667	07.12.2016
1109/2010	WSM00000005072428	FRC	3374T, M602	06.10.2016
1110/2010	WSM00000005066930	FRC	09 1414, M602	31.05.2016
1111/2010	WSM00000005066931	FRC	09 1414, M602	31.05.2016
1112/2010	WSM00000005069568	FRC	3362T, M602	17.09.2016
1113/2010	WSMS7480000455162	FRC	10024	17.12.2013
1114/2010	WSMS7780000441346	FRC	10025	18.12.2013
1116/2010	WSMS7480000406101	FNA	10027	21.12.2013
1117/2010	VM3LVFS3EW1R07111 / 98/C0150-001	FNA	10028	22.12.2013
1118/2010	WSMS7480000455158	FRC	10029	22.12.2013
1119/2010	WSMS7780000439462	FRC	10030	30.09.2013
1120/2010	VM3LVFS3F11R02460 / 01C3812.001	FRC	10031	28.02.2013
1121/2010	VM3LVFS3F41R08947 / 04C0702/001	FRC	10032	21.12.2013
1122/2010	WSMS7480000432424	FRC	10033	05.01.2012
1123/2010	WSMS7480000447601	FRC	10034	28.12.2013
1124/2010	WSMS7780000452777	FRC	10035	28.12.2013
1125/2010	WSM00000005030495	FRC	10036	28.12.2013
1126/2010	050553	FNA	10037	28.12.2013
1127/2010	XLER6X20005135026	FRC	10038	28.12.2013
1128/2010	WSM00000005072444	FRC	3374T, M601	08.10.2016
1129/2010	WFDFLT33551001168 / 11002625	FRC	4838, M576	04.2011
1130/2010	VF3YCBMAC11739451 / 110062910	FRC/X	10042, 8610, M581	29.09.2016
1131/2010	VF1UDC1K643021327 / 110019310	FNA/X	10043, 7327, M581	30.04.2016
1132/2010	SUDNS340000022829 / 110064710	FRC	10044, 9743, M588	15.12.2016
1133/2010	SUDNS340000022828 / 110064610	FRC	10045, 9743, M588	15.12.2016

1134/2010	SUDNS34000022830 / 110064410	FRC	10046, 9743, M588	15.12.2016
1135/2010	SUDNS34000022827 / 110064510	FRC	10047, 9743, M588	15.12.2016
1136/2010	WSMS748000094183	FNA	10048	30.12.2013
1137/2010	WSMS748000094177	FNA	10049	30.12.2013
1138/2010	VM3LVFS3F41R08774 / 04C0565/001	FRC	10050	30.12.2013
1139/2010	VM4CD381JYA001587 / 47338	FRC	10051	21.08.2012
1140/2010	VM3LVFS3F41R10021 / 04C210039/001	FRC	10052	30.12.2013
1141/2010	VM3LVFS3F11R02724 / 01C0273.002	FRC	10053	28.02.2013
1142/2010	VM3LVFS3EX1R09861 / 99.C2049.001	FNA	10054	28.12.2013
1143/2010	W0910F339WPA10146 / 22170	FNA	10055	28.12.2013
1148/2010	WSM00000005021552	FRC	10060	29.12.2013
1149/2010	WSM00000005016581	FRC	10062	29.12.2013
1150/2010	WSMS7480000459732	FRC	10063	29.12.2013
1151/2010	WSM00000005058448	FRC	10064, 05 1248, MR79	03.09.2014
1152/2010	WSMS7480000455624	FRC	10065	29.12.2013
1153/2010	WSM00000005041183	FRC	10066	29.12.2013
1154/2010	WSMS7480000453039	FRC	10067	29.12.2013
1155/2010	WSMS7480000452290	FRC	10068	29.12.2013
1156/2010	WSM00000005000677	FRC	10069	29.12.2013
1157/2010	WSM00000005016586	FRC	10070	29.12.2013
1158/2010	WSMS7480000458017	FRC	10071	30.12.2013
1159/2010	WSM00000005020784	FRC	10072	31.12.2013
1160/2010	WSM00000005002433	FRC	10073	31.12.2013
1161/2010	VF624CPA0000013378 / 110110310	FRC	10079, 6652, M699	22.12.2016
1162/2010	VF1VBU4C144074030 / 110074010	FNA/X	10080, 7327, M648	30.11.2016
1163/2010	VF1VBU4C144074024 / 110073910	FNA/X	10081, 7327, M648	30.11.2016
1164/2010	VF1VBU4C144074022 / 110074210	FNA/X	10082, 7327, M648	30.11.2016
1165/2010	VF1VBU4C144074021 / 110073810	FNA/X	10083, 7327, M648	30.11.2016
1166/2010	VF1VBU4C144074020 / 110074110	FNA/X	10084, 7327, M648	30.11.2016
1167/2010	VF1VBU4C144074029 / 110074510	FNA/X	10085, 7327, 279-CPABO/ATP/06	30.11.2016
1168/2010	VF1VBU4C144074028 / 110074610	FNA/X	10086, 7327, 279-CPABO/ATP/06	30.11.2016
1169/2010	VF1VBU4C144074027 / 110074410	FNA/X	10087, 7327, 279-CPABO/ATP/06	30.11.2016
1170/2010	VF1VBU4C144074026 / 110074710	FNA/X	10088, 7327, 279-CPABO/ATP/06	30.11.2016
1171/2010	VF1VBU4C144074023 / 110074310	FNA/X	10089, 7327, 279-CPABO/ATP/06	30.11.2016
1172/2010	ZCFA1ED04A2576144 / 10099610	FRC/X	10090, 7328, M721	21.12.2016