

Spis świadectw wydanych przez COCH w 2005 r.

| Numer świadectwa | Numer rejestracyjny (punkt 3 świadectwa) | Uznaje się jako (punkt 6 świadectwa) | Nr protokołu badań (punkt 7.2.3 świadectwa) | Data ważności świadectwa (pkt.8) |
|------------------|------------------------------------------|--------------------------------------|---------------------------------------------|----------------------------------|
| 1 | 2 | 3 | 4 | 5 |
| 006/2005 | WL 33488 / 4101104 | FRC/X | 4900 | 06.01.2011 |
| 010/2005 | LU 74942 / 11011974 | FRC | 4904, 4560 | 10.2010 |
| 011/2005 | LU 74941 / 11011984 | FRC | 4904.1, 4560 | 10.2010 |
| 012/2005 | LU 74918 / 11003364 | FNA/X | 4904.2, 4152 | 07.2010 |
| 013/2005 | LU 74917 / 11003324 | FNA/X | 4904.3, 4152 | 07.2010 |
| 014/2005 | LU 74927 / 11003374 | FNA/X | 4904.4, 4152 | 07.2010 |
| 015/2005 | LU 74839 / 11003254 | FNA/X | 4904.5, 4152 | 05.2010 |
| 016/2005 | LU 74916 / 11003334 | FNA/X | 4904.6, 4152 | 07.2010 |
| 017/2005 | LU 74883 / 11003264 | FNA/X | 4904.7, 4152 | 06.2010 |
| 018/2005 | LU 74843 / 11003244 | FNA/X | 4904.8, 4152 | 05.2010 |
| 019/2005 | LU 74886 / 11003314 | FNA/X | 4904.9, 4152 | 06.2010 |
| 051/2005 | KR 3016R / 05-01-901 | FNA/X | 4918 | 11.01.2011 |
| 068/2005 | KR 3054R / 05-01-902 | FNA/X | 4918.1 | 17.01.2011 |
| 070/2005 | WI 239AL / 456304 | FRC | 04 1183, MR79 | 10.2010 |
| 085/2005 | WZ 19414 / 5002448 | FRC | 04 1183, MR79 | 10.2010 |
| 086/2005 | WZ 19413 / 5002449 | FRC | 04 1183, MR79 | 10.2010 |
| 087/2005 | KR 2913R / 05-01-803 | FNA/X | 4918.2 | 24.01.2011 |
| 099/2005 | LU 74882 / 11003274 | FNA/X | 4152, 4904.10 | 30.06.2010 |
| 100/2005 | LU 74914 / 11003354 | FNA/X | 4152, 4904.11 | 31.07.2010 |
| 101/2005 | LU 74842 / 11003194 | FNA/X | 4152, 4904.12 | 31.05.2010 |
| 102/2005 | LU 74926 / 11003404 | FNA/X | 4152, 4904.13 | 31.08.2010 |
| 103/2005 | ZSL 60AJ / 11011694 | FRC | 4560, 4904.14 | 31.10.2010 |
| 106/2005 | GA 82736 / 456656 | FRC | 03 1178, 4922.8 | 28.02.2010 |
| 113/2005 | BI 3139A / 456193 | FRC | 3329T, MR79 | 07.2010 |
| 114/2005 | BI 2728A / 455578 | FRC | 3319T, MR79 | 03.2010 |
| 115/2005 | BI 3264A / 5000629 | FRC | 04 1213, MR79 | 10.2010 |
| 116/2005 | BI 2745A / 456457 | FRC | 03 1180, MR79 | 02.2010 |
| 117/2005 | RK 707AD / 056/2004 | FRC/X | 4945 | 31.12.2010 |
| 126/2005 | GA 77528 / 11017324 | FRC/X | 4904.15 | 31.12.2010 |
| 131/2005 | GD 5946C / 04-10-733 | FRC | 4918.3 | 10.2010 |
| 133/2005 | LU 74846 / 11003234 | FNA/X | 4152, 4904.16 | 31.05.2010 |
| 134/2005 | LU 74836 / 11003184 | FNA/X | 4152, 4904.17 | 31.05.2010 |
| 135/2005 | LU 74838 / 11003174 | FNA/X | 4152, 4904.18 | 31.05.2010 |
| 136/2005 | LU 74885 / 11003284 | FNA/X | 4152, 4904.19 | 30.06.2010 |
| 147/2005 | LLU 96PE / 04C2585/001 | FRC | T3917,4960 | 31.01.2011 |
| 148/2005 | WLS P906 / 458105 | FRC | 4961 | 31.03.2010 |
| 161/2005 | LLU 68PF / 1000335 | FRC | 4838, 4904.20 | 04.03.2011 |
| 162/2005 | LLU 67PF / 11000345 | FRC | 4838, 4904.21 | 04.03.2011 |
| 163/2005 | LLU 65PF / 11000355 | FRC | 4838, 4904.22 | 04.03.2011 |
| 164/2005 | LU 74915 / 11003344 | FNA/X | 4152, 4904.23 | 31.07.2010 |
| 165/2005 | LU 74840 / 11003214 | FNA/X | 4152, 4904.24 | 31.05.2010 |
| 166/2005 | LU 74928 / 11003994 | FNA/X | 4152, 4904.25 | 31.08.2010 |
| 171/2005 | SK 98191 / 457669 | FRC | 3319T, M576 | 31.05.2010 |
| 172/2005 | SK 98192 / 457670 | FRC | 3319T, M576 | 31.05.2010 |
| 173/2005 | SK 98193 / 457671 | FRC | 3319T, M576 | 31.05.2010 |
| 174/2005 | SK 98194 / 457668 | FRC | 3319T, M576 | 31.05.2010 |
| 175/2005 | WI 611AN / 457672 | FRC | 3319T, M576 | 31.05.2010 |
| 176/2005 | SK 98372 / 457673 | FRC | 3319T, M576 | 31.05.2010 |
| 177/2005 | SK 98373 / 457674 | FRC | 3319T, M576 | 31.05.2010 |
| 178/2005 | SK 98375 / 457676 | FRC | 3319T, M576 | 31.05.2010 |
| 179/2005 | SK 98374 / 457675 | FRC | 3319T, M576 | 31.05.2010 |
| 180/2005 | WL 0086A / 457678 | FRC | 3319T, M576 | 31.05.2010 |
| 181/2005 | WL 0085A / 457679 | FRC | 3319T, M576 | 31.05.2010 |
| 182/2005 | WL 0078A / 457680 | FRC | 3319T, M576 | 31.05.2010 |
| 183/2005 | WL 0087A / 457677 | FRC | 3319T, M576 | 31.05.2010 |
| 184/2005 | WL 0079A / 457681 | FRC | 3319T, M576 | 31.05.2010 |
| 185/2005 | WI 061AN / 457665 | FRC | 04 1183, M576 | 31.03.2010 |
| 186/2005 | WI 062AN / 457666 | FRC | 04 1183, M576 | 31.03.2010 |
| 187/2005 | WI 063AN / 457664 | FRC | 04 1183, M576 | 31.03.2010 |
| 188/2005 | WI 064AN / 457663 | FRC | 04 1183, M576 | 31.03.2010 |

| | | | | |
|----------|-------------------------|-------|-------------------------|------------|
| 189/2005 | WI 065AN / 457662 | FRC | 04 1183, M576 | 31.03.2010 |
| 190/2005 | WI 851AM / 457660 | FRC | 04 1183, M576 | 31.03.2010 |
| 191/2005 | WI 852AM / 457659 | FRC | 04 1183, M576 | 31.03.2010 |
| 192/2005 | WI 853AM / 457661 | FRC | 04 1183, M576 | 31.03.2010 |
| 193/2005 | WI 854AM / 457657 | FRC | 04 1183, M576 | 31.03.2010 |
| 194/2005 | WI 855AM / 457658 | FRC | 04 1183, M576 | 31.03.2010 |
| 198/2005 | NGI 5A25 / 11017254 | FRC | 4560, 4904.36, M421 | 18.03.2011 |
| 199/2005 | LU 74837 / 11003164 | FNA/X | 4152, 4904.26 | 31.05.2010 |
| 200/2005 | LU 74884 / 11003294 | FNA/X | 4152, 4904.27 | 30.06.2010 |
| 201/2005 | LU 74929 / 11003384 | FNA/X | 4152, 4904.28 | 31.07.2010 |
| 202/2005 | LU 74841 / 11003204 | FNA/X | 4152, 4904.29 | 30.06.2010 |
| 210/2005 | GD 3328P / 30.303 | FRC | 3312T, 4972.4 | 24.04.2010 |
| 211/2005 | WPN 72CH / 11003743 | FNA | 4525, 4736.3 | 30.11.2009 |
| 216/2005 | WY 122AF / 11004824 | FRC | 4838, M338 | 31.12.2010 |
| 217/2005 | WY 121AF / 11004834 | FRC | 4838, M338 | 31.12.2010 |
| 218/2005 | WY 120AF / 11004514 | IN | 4525 | 31.12.2010 |
| 233/2005 | BSI T167 / 5000417 | FRC | 04 1213, 4987 | 30.09.2010 |
| 236/2005 | BSI T202 / 700417 | FRC | 03 1178, 4988 | 31.12.2009 |
| 244/2005 | LB 91244 / 456194 | FRC | 3329T, MR79 | 02.09.2010 |
| 268/2005 | ST 1296A / 11000835 | FNA | 4525, M576 | 08.03.2011 |
| 269/2005 | ST 1294A / 11000845 | FNA | 4525, M576 | 08.03.2011 |
| 270/2005 | ST 1326A / 11001805 | FNA | 4525, M576 | 15.03.2011 |
| 271/2005 | ST 1324A / 11001795 | FNA | 4525, M576 | 15.03.2011 |
| 272/2005 | PVIK-42/ FO-CO L2H2 | IN | 5009 | 01.04.2011 |
| 274/2005 | C04D PC34 18 / 11004115 | IR | 5011 | 12.04.2011 |
| 282/2005 | LU 4460P / 5003153 | FRC | 3338T, MR79 | 01.2011 |
| 296/2005 | WZ 99263 / 092UA6927 | FRC | 153-CPA BO/ATP/04, 5030 | 31.12.2010 |
| 299/2005 | GD 2086E / 11000365 | FNA/X | 4968, 4904.31 | 31.01.2011 |
| 300/2005 | LU 4397P / 11003935 | FRC | 4560, 4904.32 | 22.04.2011 |
| 319/2005 | LLU 14PG / 5003081 | FRC | 04 1234, M523 | 02.2011 |
| 320/2005 | WY 265WE / 11000315 | FRC | 4838, M576 | 03.2011 |
| 321/2005 | WY 267WE / 11000325 | FRC | 4838, M576 | 03.2011 |
| 322/2005 | WY 266WE / 11000305 | FRC | 4838, M576 | 03.2011 |
| 323/2005 | WY 263WE / 11000885 | FRC | 4838, M576 | 02.2011 |
| 324/2005 | WY 046WE / 11002615 | FRC | 4838, M576 | 04.2011 |
| 325/2005 | WY 047WE / 11002605 | FRC | 4838, M576 | 04.2011 |
| 326/2005 | WY 045WE / 11002625 | FRC | 4838, M576 | 04.2011 |
| 327/2005 | WY 271WE / 11002575 | FRC | 4838, M576 | 03.2011 |
| 328/2005 | WY 273WE / 11002595 | FRC | 4838, M576 | 03.2011 |
| 329/2005 | WY 269WE / 11002585 | FRC | 4838, M576 | 03.2011 |
| 330/2005 | RLE Y040 / 5005553 | FRC | 04 1234, MR79 | 03.2011 |
| 339/2005 | TT 172 CH / 080/2004 | FRC/X | 4945.1 | 12.2010 |
| 340/2005 | TT 173 CH / 079/2004 | FRC/X | 4945.2 | 12.2010 |
| 341/2005 | TT 170 CH / 078/2004 | FRC/X | 4945.3 | 31.12.2010 |
| 342/2005 | TT 177 CH / 077/2004 | FRC/X | 4945.4 | 12.2010 |
| 343/2005 | TT 175 CH / 069/2004 | FRC/X | 4945.5 | 12.2010 |
| 344/2005 | TT 226 BY / 024/2004 | FRC/X | 4945.6 | 09.05.2010 |
| 357/2005 | WSC79 JX / 04C0164/005 | FRC | BX 4829,5054.1 | 28.02.2010 |
| 368/2005 | GA 82839 / 205201 | FRC | T3888, M576 | 09.05.2011 |
| 371/2005 | WMA 11AR / 5004064 | FRC | 04 1234, MR79 | 01.2011 |
| 372/2005 | WN 580AA / 5003001 | FRC | 04 1234, MR79 | 01.2011 |
| 373/2005 | WN 575AA / 5003006 | FRC | 04 1234, MR79 | 01.2011 |
| 374/2005 | WN 593AA / 5003150 | FRC | 04 1234, MR79 | 02.2011 |
| 381/2005 | RZE 97SY / 70.02.05 | FNA/X | 5067 | 02.06.2011 |
| 397/2005 | WY 183AF / 5002977 | FRC | 02 1114, MR79 | 12.2010 |
| 400/2005 | WI 413AL / 204486 | FRC | T3888, M576 | 16.12.2010 |
| 401/2005 | WL 0065A / 204487 | FRC | T3888, M576 | 29.12.2010 |
| 403/2005 | WT 23416 / 11004565 | FRC/X | 5011, M518 | 04.2011 |
| 404/2005 | WB 149AG / 11004595 | FRC | 4838, M576 | 04.2011 |
| 405/2005 | WY 302WE / 11004295 | FRC | 4838, M576 | 04.2011 |
| 406/2005 | WY 299WE / 11004285 | FRC | 4838, M576 | 04.2011 |
| 407/2005 | WY 301WE / 11004275 | FRC | 4838, M576 | 04.2011 |

| | | | | |
|----------|------------------------|--------|-----------------------|------------|
| 408/2005 | WY 289WE / 11004265 | FRC | 4838, M576 | 04.2011 |
| 409/2005 | WY 286WE / 11004255 | FRC | 4838, M576 | 04.2011 |
| 410/2005 | WY 288WE / 11004235 | FRC | 4838, M576 | 04.2011 |
| 423/2005 | TLW R164 / 05-05-827a | FNA | 4276, M463 | 13.06.2011 |
| 424/2005 | SB 67383 / 05-04-817 | FNA/X | 4276, M589 | 04.2011 |
| 427/2005 | WI 379AM / 454256 | FRC | 5086 | 30.11.2009 |
| 428/2005 | SK 5278C / 11007525 | FNA/X | 4561, M485 | 05.2011 |
| 429/2005 | SK 5277C / 11007515 | FNA/X | 4561, M485 | 05.2011 |
| 430/2005 | GWE C848 / 11006705 | FNA/X | 4968, M486 | 05.2011 |
| 441/2005 | BI 90000 / 05-06-833 | FNA | 4276, MR74 | 06.2011 |
| 442/2005 | WB 408AF / 455734 | FRC | 5087.2 | 01.2010 |
| 450/2005 | PB 9607AH / 29805 | FRC/X | 4945.9 | 06.2011 |
| 469/2005 | ELW U599 / 11006725 | FNA | 4525, M576 | 06.2011 |
| 470/2005 | ELW 11HA / 11006715 | FNA | 4152, M578 | 06.2011 |
| 471/2005 | WND 79ER / 11005685 | FRC/X | 4560, M538 | 06.2011 |
| 472/2005 | WND 19EP / 11005675 | FRC/X | 4560, M538 | 05.2011 |
| 475/2005 | LRA R490 / 29341 | FRC | 5106, 3275T | 11.2010 |
| 481/2005 | LLU 50PF / 388074 | FRC | 5111, 3297T | .06.2010 |
| 492/2005 | GD 3066P / 25797 | FRC | 5100.9, 3312T | 23.07.2010 |
| 495/2005 | WF 573AC / 454825 | FRC | 3282T, 4972.5 | 31.12.2009 |
| 508/2005 | WL 0680A / 452975 | FRC | 03 1178, 5122 | 31.01.2010 |
| 509/2005 | CG 25144 / 11013324 | FNA | 4152, MR71 | 30.11.2010 |
| 510/2005 | WB 018AG / 11000825 | FRC | 4838, MR79 | 31.01.2011 |
| 511/2005 | DW 8755P / 11007695 | FNA | 4525, M576 | 30.06.2011 |
| 512/2005 | DW 8756P / 11007705 | FNA | 4525, M576 | 30.06.2011 |
| 513/2005 | DW 8740P / 11007685 | FNA | 4525, M576 | 30.06.2011 |
| 514/2005 | DW 8790P / 11007715 | FNA | 4525, M576 | 30.06.2011 |
| 518/2005 | WB 788AF / 457633 | FRC | 3319T, 5125 | 30.04.2010 |
| 522/2005 | WZ 19825 / 5003011 | FRC | 04 1234, MR 79 | 04.2011 |
| 524/2005 | LU 93916 / 11005745 | FNA/X | 4968, M517 | 30.06.2011 |
| 525/2005 | LU 93929 / 11005715 | FNA/X | 4968, M517 | 30.06.2011 |
| 526/2005 | LU 93918 / 11005755 | FNA/X | 4968, M517 | 30.06.2011 |
| 527/2005 | LU 93917 / 11005725 | FNA/X | 4968, M517 | 30.06.2011 |
| 528/2005 | LU 93910 / 11005735 | FNA/X | 4968, M517 | 30.06.2011 |
| 529/2005 | LU 93912 / 11005775 | FNA/X | 4968, M517 | 30.06.2011 |
| 530/2005 | LU 93915 / 11005765 | FNA/X | 4968, M517 | 30.06.2011 |
| 531/2005 | LU 93913 / 11005705 | FNA/X | 4968, M517 | 30.06.2011 |
| 539/2005 | LLU 70PJ / 11011275 | FRC | 4838, 4904.37 | 25.08.2011 |
| 544/2005 | WOT 73ML / 05-08-841 | FNA/X | 4562, M529 | 08.2011 |
| 545/2005 | WOT 02MR / 05-08-843 | FNA/X | 4562, M529 | 08.2011 |
| 548/2005 | CF/056/IV-DA-L3H2 | IN | 5130 | 10.08.2011 |
| 553/2005 | KOL 18GH / 454381 | FRC | 03 1142, 4931.4 | 30.11.2009 |
| 564/2005 | BI 3777A / 5006475 | FRC | 04 1234,5137 | 31.05.2011 |
| 571/2005 | LBI S565 / 453969 | FRC | 3304T,MR79, 5140.3 | 11.2009 |
| 574/2005 | WI 015AM / 452300 | FRC | 5141.1, 03 1161 | 10.2009 |
| 575/2005 | LU 4128P / 456192 | FRC | 3329T,5141.2 | 07.2010 |
| 580/2005 | LRA P990 / 453967 | FRC | 03 1178, MR79,5143 | 02.2010 |
| 586/2005 | LBI S564 / 453968 | FRC | 03 1161,MR79,5145.1 | 11.2009 |
| 587/2005 | LBI 33VM / 5003010 | FRC | 04 1234, MR79 | 01.2011 |
| 591/2005 | LBI 33VC / 453972 | FRC | 5013.2, 02 1114, MR79 | 01.2010 |
| 592/2005 | LBI S570 / 453965 | FRC | 5013.3, 03 1161, MR79 | 10.2009 |
| 601/2005 | LU 4209P / 203017 | FRC | 5152, 2A000626, M523 | 08.09.2010 |
| 602/2005 | 3T3 2081 / 4020/03-150 | FRC /X | 4945.10 | 05.2011 |
| 606/2005 | LU 93921 / 11005795 | FRC/X | 4560, M589-A | 30.06.2011 |
| 607/2005 | LU 93927 / 11005805 | FRC/X | 4560, M589-A | 30.06.2011 |
| 608/2005 | LU 93923 / 11005785 | FRC/X | 4560, M589-A | 30.06.2011 |
| 609/2005 | LU 93928 / 11005815 | FRC/X | 4560, M589-A | 30.06.2011 |
| 610/2005 | LU 93922 / 11005825 | FRC/X | 4560, M589-A | 30.06.2011 |

| | | | | |
|----------|----------------------|-------|-----------------------|------------|
| 611/2005 | LU 93930 / 11005835 | FRC | 4560, M572 | 30.06.2011 |
| 612/2005 | WZ 19870 / 5008271 | FRC | 3352T, MR79 | 07.2011 |
| 621/2005 | LU 4855P / 5003074 | FRC | 3338T, MR79 | 31.01.2011 |
| 622/2005 | LU 4854P / 5003073 | FRC | 3338T, MR79 | 31.01.2011 |
| 635/2005 | WZ 19875 / 5003089 | FRC | 3338T, MR79 | 04.2011 |
| 642/2005 | WXG 714W / 16013 | FNA | 5161 | 06.10.2011 |
| 646/2005 | WPN 28CN / 01121 | FRC | T3341 , MR81, 4972.7 | 30.06.2010 |
| 647/2005 | WR 72466 / 11009475 | FRC/X | 4560, M517 | 30.09.2011 |
| 648/2005 | SCZ 55SL / 0010905 | FNA/X | 4797, M486 | 27.09.2011 |
| 649/2005 | BI 3779A / 5003196 | FRC | 04 1213, MR79 | 07.2011 |
| 658/2005 | LBI 27VH / 457722 | FRC | 5145.2, 04 1183, MR79 | 06.2010 |
| 669/2005 | LBI 20VR / 5003019 | FRC | 3352T, MR79 | 09.2011 |
| 670/2005 | WLS P939 / 5003065 | FRC | 04 1234, M523 | 01.2011 |
| 671/2005 | RDE 81PA / 250443 | FRC | 3344T, M576, 5156.7 | 22.08.2011 |
| 672/2005 | RDE 82PA / 250442 | FRC | 3344T, M576, 5156.8 | 22.08.2011 |
| 673/2005 | RDE 83PA / 250441 | FRC | 3344T, M576, 5156.9 | 22.08.2011 |
| 674/2005 | RDE 79PA / 250440 | FRC | 3344T, M576, 5156.10 | 19.08.2011 |
| 679/2005 | RDE 40PA / 226391 | FRC | 3344T, 4951.1 | 10.08.2011 |
| 680/2005 | RDE 14PA / 226386 | FRC | 3344T, 4951.2 | 06.07.2011 |
| 692/2005 | LLU 21PK / 5009025 | FRC | 05 1251, MR79 | 09.2011 |
| 694/2005 | GWE 3F07 / 11011445 | FNA/X | 4968, M591-A | 09.2011 |
| 695/2005 | GWE 3F08 / 11011435 | FNA/X | 4968, M591-A | 09.2011 |
| 698/2005 | KR 9346U / 05-10-847 | FNA/X | 4562, M538 | 10.2011 |
| 699/2005 | KR 9313U / 05-10-848 | FNA | 4276, M568 | 10.2011 |
| 700/2005 | WZ 29220 / 5009019 | FRC | 05 1251, MR79 | 09.2011 |
| 720/2005 | GA 82154 / 205150 | FRC | T3895, M576 | 30.04.2011 |
| 727/2005 | C389D / 11016265 | IN | 5192 | 08.11.2011 |
| 732/2005 | RDE 02PC / 250448 | FRC | 3344T, M576 | 10.2011 |
| 733/2005 | RDE 03PC / 250449 | FRC | 3344T, M576 | 10.2011 |
| 734/2005 | RDE 73PA / 250447 | FRC | 3344T, M576 | 10.2011 |
| 735/2005 | RDE 74PA / 250446 | FRC | 3344T, M576 | 10.2011 |
| 736/2005 | RDE 75PA / 250445 | FRC | 3344T, M576 | 10.2011 |
| 737/2005 | RDE 76PA / 250444 | FRC | 3344T, M576 | 10.2011 |
| 738/2005 | KR 3606P / 5009399 | FRC | 3352T, MR81 | 10.2011 |
| 739/2005 | KR 3649P / 5009400 | FRC | 3352T, MR81 | 10.2011 |
| 740/2005 | KR 3791P/ 05-11-849 | FNA | 4276, M568 | 11.2011 |
| 741/2005 | WPR 40WX / 205373 | FRC | T3888, M576 | 11.10.2011 |
| 742/2005 | WPR 39WX / 205374 | FRC | T3888, M576 | 11.10.2011 |
| 761/2005 | WY 378WE / 5003096 | FRC | 04 1213, MR79 | 23.05.2011 |
| 762/2005 | WY 380WE / 5003097 | FRC | 04 1213, MR79 | 23.05.2011 |
| 763/2005 | KR 2342P / 447547 | FRC | 5201, 04 1213, M576 | 31.12.2010 |
| 764/2005 | KR 2341P / 447546 | FRC | 5201.1, 04 1213, M576 | 31.12.2010 |
| 767/2005 | ZKL P092 / 11009745 | FRC | 4838, 443 Cemagref | 31.08.2011 |
| 779/2005 | BI 3939A / 5009403 | FRC | 03 1165, MR79 | 10. 2011 |
| 793/2005 | WL 1174A / 11014765 | FNA | 4525, M576 | 31.10.2011 |
| 794/2005 | WL 1175A / 11014775 | FNA | 4525, M576 | 31.10.2011 |
| 795/2005 | WL 1176A / 11014795 | FNA | 4525, M576 | 31.10.2011 |
| 796/2005 | WL 1177A / 11014785 | FNA | 4525, M576 | 31.10.2011 |
| 797/2005 | WOT 98PH / 11014835 | FRC | 4838, M576 | 30.11.2011 |
| 798/2005 | WY 372WE / 11014845 | FRC | 4838, M576 | 30.11.2011 |
| 799/2005 | EZD 75FG / 11009145 | FRC/X | 4560, M538 | 31.08.2011 |
| 800/2005 | EZD 74FG / 11009135 | FRC/X | 4560, M538 | 31.08.2011 |
| 801/2005 | WN 55136 / 11018185 | FNA/X | 4968, M486 | 30.06.2011 |
| 802/2005 | WN 56678 / 11008925 | FNA/X | 4968, M538 | 31.07.2011 |
| 804/2005 | WL 1162A / 5009864 | FRC | 03 1165, M576 | 10.2011 |
| 805/2005 | WL 1171A / 5009863 | FRC | 03 1165, M576 | 10.2011 |
| 806/2005 | WL 1165A / 5009862 | FRC | 03 1165, M576 | 10.2011 |
| 807/2005 | WL 1172A / 5009861 | FRC | 03 1165, M576 | 10.2011 |

| | | | | |
|----------|----------------------|-------|------------------------|------------|
| 811/2005 | SB 75073 / 05-11-856 | FNA | 4562, M568 | 11.2011 |
| 812/2005 | SB 75058 / 05-11-850 | FNA | 4276, MR71 | 11.2011 |
| 813/2005 | KK 703AR / SI-05/053 | FRC/X | 4945.11 | 10.09.2011 |
| 824/2005 | ST 34061 / 11013425 | FNA | 4152, M546 | 31.10.2011 |
| 825/2005 | WN 241AA / 447536 | FRC | 5201.3, 04 1183, M576 | 31.12.2010 |
| 826/2005 | WN 242AA / 447537 | FRC | 5201.4, 04 1183, M576 | 31.12.2010 |
| 827/2005 | WN 243AA / 447538 | FRC | 5201.5, 04 1183, M576 | 31.12.2010 |
| 828/2005 | WN 252AA / 447539 | FRC | 5201.5, 04 1183, M576 | 31.12.2010 |
| 829/2005 | WN 251AA / 447540 | FRC | 5201.7, 04 1183, M576 | 31.12.2010 |
| 842/2005 | DW 8065T / 11013435 | FRC | 4560, M541 | 09.2011 |
| 843/2005 | RZE 95UX / 11016285 | FRC/X | 5011, M517 | 11.2011 |
| 844/2005 | RZE 96UX / 11016275 | FRC/X | 5011, M517 | 11.2011 |
| 845/2005 | GKA 33NY / 11005355 | FRC/X | 5011, M529 | 06.2011 |
| 846/2005 | KR 2317P / 447548 | FRC | 5201.8. 03 1165, M576 | 31.12.2010 |
| 847/2005 | KR 2316P / 447549 | FRC | 5201.9, 03 1165, M576 | 31.12.2010 |
| 848/2005 | KR 2269P / 447545 | FRC | 5201.10, 03 1165, M576 | 31.12.2010 |
| 849/2005 | KR 2213P / 447542 | FRC | 5201.11, 03 1165, M576 | 31.12.2010 |
| 850/2005 | KR 2255P / 447544 | FRC | 5201.12, 03 1165, M576 | 31.12.2010 |
| 851/2005 | KR 2208P / 447543 | FRC | 5201.13, 03 1165, M576 | 31.12.2010 |
| 852/2005 | KR 2242P / 447541 | FRC | 5201.14, 03 1165, M576 | 31.12.2010 |
| 856/2005 | WOT 95PJ / 11018685 | FRC | 4838, M576 | 27.12.2011 |
| 857/2005 | RZ 54845 / 11019075 | FNA/X | 4561, M485 | 30.12.2011 |